(DO NOT USE THIS FORM FOR PROP DIFFERENT RESERVOIR. USE "APPLI	Energy, Minerals and Natural Resources Energy, Minerals and Natural Resources Energy, Minerals and Natural Resources OIL CONSERVATION DIVISION 1220 South St. Francis Dr. Santa Fe, NM 87505 SUNDRY NOTICES AND REPORTS ON WELLS NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A ERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		WELL API NO. 30-045-35642 5. Indicate Type of Lease STATE FEE 6. State Oil & Gas Lease No. 7. Lease Name or Unit Agreement Name: Crow Mesa 24-08 2		
PROPOSALS.) 1. Type of Well: Oil Well 🗷 Gas Well	pe of Well:			8. Well Number	
2. Name of Operator			9. OGRID Number		
ENERGEN RESOURCES CORPORATION			162928		
3. Address of Operator			10. Pool name or Wildcat		
2010 Afton Place, Farmington NM 87401			Dufers Point-Gallup Dakota		
4. Well Location					
Unit Letter :	1419feet from theSo	uth line and	505 feet f	rom the <u>East</u> line	
Section 2	Township 24N	Range 8W	NMPM	County San Juan	
	11. Elevation (Show whether		tc.)	建筑型型的高度工 工	
Party and the second of the second	73	18' GL			
NOTICE OF INT PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING DOWNHOLE COMMINGLE OTHER: 13. Describe proposed or complete of starting any proposed work) or recompletion. See attached for complete	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL ad operations. (Clearly state all poly. SEE RULE 1103. For Multiple ion work performed.	REMEDIAL WORK COMMENCE DRILL CASING/CEMENT J OTHER: Completinertinent details, and give Completions: Attack	on ve pertinent dates,	ALTERING CASING P AND A Sincluding estimated date	
OIL CONS. DIV DIST. 3					
NOV 2 0 2015					
Spud Date: 8/13/15		ase Date:			
I hereby certify that the information	above is true and complete to the	e best of my knowledg	ge and belief.		
SIGNATURE ANA STATE	TIT		ory Analyst	DATE11/19/15	
Type or print name Anna Stotts	E-n	astotts@ene nail address:	rgen.com	PHONE _505-324-4154	
APPROVED BY Robbins Conditions of Approval (if any):		DEPUTY DIL & TLE PY	GAS INSTÉ	DATE 12-8-15	



Crow Mesa 24-08 2 #3H 30-045-35642 C-103 Attachment

10/26/15 MIRU. NU BOP.

10/27/15 RIH w/153 jts. 4.50" tie back string, 11.6#, P-110 to TOL @ 6709'. PT to 500#, good test. ND BOP. NU bottom master valve.

10/28/15 PT bottom master valve on WH, low 250# & 9500# high, good test. WSI

10/30/15 TIH w/gauges, set @ 5773'. Pump DFIT. Leave well SI.

11/07/15 POOH w/gauges. Wait on frac job.

11/08/15 Prepare for frac. Install frac stack on WH. PT WH to 9000#, good test. 1st Stage: 11490'-11492' MD (RSI). Frac w/118300# of 20/40 sand.

2nd Stage: Set composite frac plug @ 11452' MD. Perf from 11253.5'-11432' MD, .41" HD, 6 spf, 36 holes. Frac w/210200# of 20/40 sand.

3rd Stage: Set cfp @ 11226' MD. Perf form 11017.5'-11196' MD, .41" HD, 6 spf, 36 holes. Frac w/203300 of 20/40 sand. 4th Stage: Set cfp @ 10990' MD. Perf from 10781.5' – 10960' MD, .41" HD, 6 spf, 36 holes.

11/09/15 Frac w/232700# of 20/40 sand.

5th Stage: Set cfp @ 11752' MD. Perf from 10545.5'-10724' MD, .41" HD, 6 spf, 36 holes. Frac w/230500# of 20/40 sand. 6th Stage: Set cfp @ 10525' MD. Perf from 10309.5'-10488' MD, .41" HD, 6 spf, 36 holes. Frac w/230000# of 20/40 sand. 7th Stage: Set cfp @ 10282' MD. Perf from 10073.5'-10252' MD, .41" HD, 6 spf, 36 holes. Frac w/230200# of 20/40 sand. 8th Stage: Set cfp @ 10046' MD. Perf from 9837.5'-10016' MD, .41" HD, 6 spf, 36 holes. Frac w/230300# of 20/40 sand. 9th Stage: Set cfp @ 9805' MD. Perf from 9601.5'-9780' MD, .41" HD, 6 spf, 36 holes. Frac w/230000# of 20/40 sand. 10th Stage: Set cfp @ 9574' MD. Perf from 9365.5'-9544' MD, .41" HD, 6 spf, 36 holes. Frac w/230000# of 20/40 sand. 11th Stage: Set cfp @ 9338' MD. Perf from 9129.5'-9308' MD, .41" HD, 6 spf, 36 holes. Frac w/230400# of 20/40 sand.

11/10/15 12th Stage: Set cfp @ 9102' MD. Perf from 8893.5'-9072' MD, .41" HD, 6 spf, 36 holes. Frac w/230200# of 20/40 sand. 13th Stage: Set cfp @ 8866' MD. Perf from 8657.5'-8836' MD, .41" HD, 6 spf, 36 holes. Frac w/229900# of 20/40 sand. 14th Stage: Set cfp @ 8630' MD. Perf from 8421.5'-8600' MD, .41" HD, 6 spf, 36 holes. Frac w/230000# of 20/40 sand. 15th Stage: Set cfp @ 8394' MD. Perf from 8185.5'-8364' MD, .41" HD, 6 spf, 36 holes. Frac w/230200# of 20/40 sand. 16th Stage: Set cfp @ 8158' MD. Perf from 7949.5'-8128' MD, .41" HD, 6 spf, 36 holes. Frac w/230200# of 20/40 sand. 17th Stage: Set cfp @ 7922' MD. Perf from 7713.5'-7892' MD, .41" HD, 6 spf, 36 holes. Frac w/230300# of 20/40 sand. 18th Stage: Set cfp @ 7686' MD. Perf from 7477.5'-7656' MD, .41" HD, 6 spf, 36 holes. Frac w/230300# of 20/40 sand.

11/11/15 19th Stage: Set cfp @ 7460' MD. Perf from 7241.5'-7420' MD, .41" HD, 6 spf, 36 holes. Frac w/229900# of 20/40 sand. 20th Stage: Set cfp @ 7214' MD. Perf from 7005.5'-7184' MD, .41" HD, 6 spf, 36 holes. Frac w/230000# of 20/40 sand. RIH w/4.50" CBP, set @ 5800'.

11/12/15 ND Frac stack. NU BOP. PT 250# low & 3000# high, good test.

11/13-14 TIH, mill CBP @ 5800' and composite frac plugs from 7214'-11452' . c/o well to PBTD.

11/15-16 TOOH w/4.50" tie back string. RIH w/tubing as follows: 36 joints 2.875", 6.5#, J-55, gas lift valve #10 @ 1210',
2015 22 jts 2.875", 6.5#, J-55 tbg, GLV #9 @ 1940', 20 jts 2.875", 6.5#, J-55 tbg, GLV #8 @ 2605', 20 jts 2.875", 6.5#, J-55,
GLV #7 @ 3269', 18 jts 2.875", 6.5#, J-55, GLV #6 @ 3867', 16 jts. 2.875", 6.5#, J-55, GLV #5 @ 4399', 16 jts,
2.875", 6.5#, J-55, GLV #4 @ 4931', 16 jts. 2.875", 6.5#, J-55, GLV #3 @ 5463', 15 jts 2.875", 6.5#, J-55, GLV #2
@ 5962', 20 jts 2.875", 6.5#, J-55, GLV #1 @ 6628', 1 jt 2.875", 6.5#, J-55, on/off tool @ 6667', 6 jts. 2.375", 4.7#,
J-55, end of tbg @ 6871'. Release rig 11/16/15.