Form 3160-5 (August 2007)

#### UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM APPROVED
OMB NO. 1004-0135
Expires: July 31, 2010

V NOTICES AND DEDODTS ON WELL

NMSF077184

Lease Serial No.

	NOTICES AND REPOR	THINOI OTT TO	THINOI OTT TOT			
Do not use the abandoned we	nis form for proposals to ell. Use form 3160-3 (APL	6. If Indian, Allottee	or Tribe Name			
SUBMIT IN TR	IPLICATE - Other instruc	tions on reverse side.	7. If Unit or CA/Agr	reement, Name and/or No.		
Type of Well     Oil Well	ther		8. Well Name and N LENIS A SHANI			
Name of Operator     BP AMERICA PRODUCTION		TOYA COLVIN n@bp.com	9. API Well No. 30-045-20205	-00-S1		
3a. Address 501 WESTLAKE PARK BLVI HOUSTON, TX 77079	D. THREE ELDRIGE PLAC	3b. Phone No. (include area code EPh: 281-366-7148	10. Field and Pool, of BLANCO PIC	or Exploratory TURED CLIFFS		
<ol> <li>Location of Well (Footage, Sec., Sec 14 T29N R9W SESW 07 36.720016 N Lat, 107.75125</li> </ol>	90FSL 1675FWL		11. County or Parish SAN JUAN CO			
12. CHECK APP	ROPRIATE BOX(ES) TO	INDICATE NATURE OF	NOTICE, REPORT, OR OTH	ER DATA		
TYPE OF SUBMISSION	Y STAN	ТҮРЕ С	OF ACTION			
Notice of Intent     □ Subsequent Report	Acidize Alter Casing	Deepen Fracture Treat	☐ Production (Start/Resume) ☐ Reclamation ☐ Recomplete	□ Water Shut-Off □ Well Integrity		

☐ Plug Back ■ Water Disposal ☐ Convert to Injection Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

■ New Construction

☑ Plug and Abandon

□ Recomplete

☐ Temporarily Abandon

BP America Production Company respectfully requests to P&A the subject well.

☐ Casing Repair

☐ Change Plans

☐ Final Abandonment Notice

Please see the attached P&A procedure including BLM required reclamation plan documents.

In accordance with NMOCD Pit Rule 19.15.17.9 NMAC, BP will use a closed-loop system during operations.

OIL CONS. DIV DIST. 3

Other

MAR 2 1 2016

14. I hereby certify that t	he foregoing is true and correct.  Electronic Submission #333253 verifie  For BP AMERICA PRODUCTION C  Committed to AFMSS for processing by JA	OMPAN	VY. sent to the Farmington	)	
Name (Printed/Typed)	TOYA COLVIN	Title	REGULATORY ANALYST		AL A
Signature	(Electronic Submission)	Date	03/09/2016		
STEEL STEEL	THIS SPACE FOR FEDERA	L OR	STATE OFFICE USE		
Approved By JACK S	AVAGE	TitleF	PETROLEUM ENGINEER	Date 03/	/15/2016
certify that the applicant ho	my, are attached. Approval of this notice does not warrant or olds legal or equitable title to those rights in the subject lease olicant to conduct operations thereon.	Office	e Farmington		

\*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\*



February 17, 2016

NMOCD:

BP would like to permanently abandon the **Lenis A. Shane USA #1** well as per the attached procedure and wellbore sketches.

#### PLUG AND ABANDONMENT PROCEDURE

Blanco Pictured Cliffs
790' FSL and 1675' FWL, Section 14, T29N, R9W
San Juan County, New Mexico / API 30-045-20205
Lat: N \_\_\_\_\_ / Lat: W \_\_\_\_\_

Note: All cement volumes use 100% excess outside pipe and 50' excess inside. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures. All cement will be Class B, mixed at 15.6 ppg with a 1.18 cf/sx yield.

- Install and test location rig anchors. Comply with all NMOCD, BLM, and Operator safety
  regulations. MOL and RU daylight pulling unit. Conduct safety meeting for all personnel on
  location. Record casing, tubing and bradenhead pressures. NU relief line and blow down well.
  Kill well with water as necessary and at least pump tubing capacity of water down the tubing. ND
  wellhead and NU BOP. Function test BOP.
- 2. Rods: Yes\_\_\_\_, No\_\_X\_\_, Unknown\_\_\_\_.

  Tubing: Yes\_\_X\_, No\_\_\_, Unknown\_\_\_\_, Size\_\_\_1-1/4"\_, Length\_\_2470'\_\_\_.

  Packer: Yes\_\_\_\_, No\_\_X\_\_, Unknown\_\_\_\_\_, Type\_\_\_\_\_\_.

If this well has rods or a packer, then modify the work sequence in step #2 as appropriate. TOH and LD 1-1/4" tubing. PU 2-3/8" tubing workstring (2400'). Round trip 4.5" mill to 2394'.

- Plug #1 (Pictured Cliffs interval and Fruitland top, 2394' 2060'): RIH and set 4.5" CR at 2394'. Circulate well clean. Pressure test tubing to 1000#. Pressure test casing to 800#. <u>If casing does not test then spot or tag subsequent plugs as appropriate.</u> Mix 30 sxs Class B cement inside casing from 2394' to cover the PC interval and Fruitland top. PUH.
- Plug #2 (Kirtland and Ojo Alamo tops, 1530' 1270'): Mix and pump 24 sxs Class B cement inside casing to cover through the Ojo Alamo top. TOH.
- Plug #3 (8.625" casing shoe, 272' 0'): Perforate 3 squeeze holes at 272'. Attempt to establish
  a rate. If able to establish circulation then mix and pump 90 sxs Class B cement to surface.
  Circulate good cement to surface. SI well and WOC.
- ND cementing valves and cut off wellhead. Fill annuli with cement as necessary. Install P&A
  marker to comply with regulations. Record GPS coordinate for P&A marker on tower report.
  Photograph P&A marker in place. RD, MOL and cut off anchors. Restore location per BLM
  stipulations

#### Lenis A. Shane USA #1

#### Proposed P&A

**Blanco Pictured Cliffs** 790' FSL, 1675' FWL, Section 14, T-29-N, R-9-W San Juan County, NM, API #30-045-20205

Today's Date:2/17/16 Spud: 12/19/67 Completed: 12/25/67 Elevation: 5911' GI

5921' KB

12.25" hole

8.625" 24# Casing set @ 222' Cement with 200 sxs, circulated

Perforate @ 272'

Plug #3: 272' - 0' Class B cement, 90 sxs

TOC unknown, did not circulate

Ojo Alamo @ 1320'

Kirtland @ 1480'

Plug #2: 1530' - 1270' Class B cement, 24 sxs

Plug #1: 2394' - 2060'

Class B cement, 30 sxs

Fruitland @ 2110'

Pictured Cliffs @ 2440'

7.875" hole



Set CR @ 2394'

Pictured Cliffs Perforations: 2444' - 2453'; 2475' - 2488'

4.5",10.5#, J-55 Casing set @ 2528' Cement with 650 sxs



Well name and no: Lenis A Shane USA 001

API No. 30-045-20205

Plugging & Abandonment Surface Reclamation Plan

Operator:	BP America	Location:	Sec. 14, Twn: 29N, Range 9W
Well name & No:	Lenis A Shane USA 001	County, State:	San Juan County, NM
API No:	30-045-20205	Revision:	0
Surface:	BLM	285	
Date:	03/03/2016		and the second second

This document outlines the final reclamation plan for the Lenis A Shane USA 001well site, API 30-045-20205, based on the BLM/BP on-site inspection conducted on 03/03/2016 and in accordance with Onshore Order No. 1 and the FFO Bare Soil Reclamation Procedures C (dated 2/2013).

Reclamation work on this well pad will be limited to equipment removal as it is Co-located with BP well Shane Gas Com 001A and Southland Royalties #2 Federal 29-9-14.

#### PROPOSED VEGETATION RECLAMATION PLAN

#### General Notes:

- BP will comply with the requirements in accordance with the approved Sundry Notice associated with this submittal.
- BP will notify the BLM forty-eight (48) hours prior to commencing earthwork.
- BP will notify the Authorized Officer forty-eight (48) hours prior to commencing with seed application.
- All underground production piping on the well site will be removed or abandoned-inplace.
- BP power poles, rectifier and/or radio equipment will be in current location as it is in service of the Shane Gas Com 001A and as approved by BLM Personnel.
- All rig anchors found on location will be removed.
- All surface equipment identified on location at time of P&A will be removed from location.
- All trash, if any, will be removed from location.
- The P&A marker will be permanent and comply with all NMOCD regulations.

Well Site Reclamation: NOT APPLICABLE well is co-located with active wells. (Note: some steps may occur in a different sequence than listed below)

Access Road Reclamation: NOT APPLICABLE well is co-located with active wells.

Re-vegetation: NOT APPLICABLE well is co-located with active wells.

Weed Management: NOT APPLICABLE well is co-located with active wells.

Monitoring: NOT APPLICABLE well is co-located with active wells.

ALL RECLAMATION RESPONSIBILITY WILL BE SHIFTED TO BP ACTIVE WELL SHANE GAS COM 001 A.

#### Attachments:

Well name and no: Lenis A Shane USA 001 API No. 30-045-20205

- Reference photos of location taken on February 25, 2016.
- P&A Field Inspection Sheet performed on March 3, 2016.
- Aerial of location with short description of reclamation plan.

#### Onsite Noxious Weed Form

If noxious weeds are found coordinator.	during the onsite, fill	out and submit to FFO weed
Operator: BP America	Surveyor(s): Ste	eve Moskal (BP), Sabre Beebe
(BP) and Bob Switzer (BLM)		
Well Name and Number W D	HEATH A 006	Date: March 3, 2016
Location: Township 29N Ran	nge <u>9W</u> Section <u>17</u>	
Location of Project NAD 83 D	Decimal Degrees	
Class A	Noxious Weed - Check Bo	ox if Found
Alfombrilla Diffuse	Hydrilla P	virole Vellow

Alfombrilla	Diffuse knapweed	Hydrilla	Purple Starthisle	Yellow toadflax
Black henbane	Dyer's woad	Leafy spurge	Ravenna grass	1998
Camelthorn	Eurasian watermilfoil	Oxeye daise	Scotch thistle	1 . 3
Canada thistle	Giant salvinia	Parrotfeather	Spotted knapweed	1 3 8 8
Dalmation toadflax	Hoary cress	Purple loosestrife	Yellow starthistle	4 7 7 7

#### Class B Noxious Weed - Check Box if Found

African rue	Perennial pepperweed	Russian knapweed	Tree of heaven
Chicory	Musk thistle	Poison hemlock	
Halogeton	Malta starthisle	Teasel	

X	No noxious weeds identified at tir	ne of on site
Com	ments:	
FFO Sign and a	Representative:	
Oper	rator Representative:	

#### P&A Field Inspection Sheet

Date: 03/03/	2016			Specialist: S. Beebe BP/S. Moskal BP/ R. Switzer BLM Well Name & Number: Lenis A Shane USA 001						
Operator: 1	BP America									
API Numb	er: 30-045-20205			Section: 14	Section: 14 Township: 29N Range: 9W					
Lease Nun	nber:	NMSF 0771	84	Footage: 790 FSL	, 1675 FWL					
		14 1		County: San Juan State: NM						
Surface:	BLM 🗸	BOR 🗌	State	Twinned:	Yes		No 🗸			
7 745	To the	THE CO.				75.4	the part of			
				Well Pad						
Topograph	y: Slight sloping and	sandy area		Stockpile 7	Topsoil	☐ Ye	s No			
	Sand and Silty	700					17/201			
	Community: Pin	on/Juniper					NOT THE REAL PROPERTY.			
Sage b		-34			TA TO	1965	THE BUT			
2 Forbes	Pleasure II			A CONTRACTOR OF THE PARTY OF TH		- Value	5071 7 72.1			
3				Section of property	P	27.00	1 ST. 1 C. 1 S			
4	W. DIRTH			The state of the s	a Epil del	1 1 1 1 1 1	1.000			
5	OTRING 20			THE PLANE		150				
5	94.5 K		2-70		7	1,120	CORRECT AND			
7				GERMAN DE L	7		The State of the S			
3	( 00)				1177		F-12116			
)							William III			
_	Cages: Yes	ZNI-					CONTRACTOR OF THE PARTY OF THE			
Steel Pits:	Above Grade / B	cation: Ves	]No		In .					
Cathodic Con Service: Remove W		eation: Ves_Abandoned: move Rectifier	No Yes No The No	Plugged: Yes Re	lo move Power	Poles:	Yes No			
Cathodic Con Service: Remove W	Groundbed on loc Yes No A ire Re- cation: Yes on Diversion Dite	eation: Ves_Abandoned: move Rectifier	No Yes No The No	Plugged: Yes Re	move Power		Yes No			
Cathodic Con Service: Remove W	Groundbed on loc Yes No A Vire Recocation: Yes on Diversion Dita Side	cation: Ves_Abandoned: move Rectifier No Power Poch: Above	No Yes No The No	Plugged: Yes Res	move Power	√No	]Yes ☑No			
Cathodic Con Service: Remove Warsh on lo	Groundbed on loc  Yes No A  Yire Resocation: Yes on Diversion Ditu  Side  Side  Side  on Silt Trap(s): No	cation: Ves_Abandoned:	No Yes No Les: Yes Below A	Plugged:YesN  No Restround  Contaminated S  Remove:Yes	move Power	√No	Yes No			
Cathodic Con Service: Remove Worash on lo	Groundbed on loc  Yes No A  Yire Resocation: Yes on Diversion Ditu  Side  Side  Side  on Silt Trap(s): No  Trap Disturbed Area	cation: Ves_Abandoned:	No Yes No Des: Yes Below A  Becessary  Pecessary  Pecessary  Pecessary	Plugged: Yes Remove: Yes  No Remove: Yes	oil: Yes	No ocation:				
Cathodic Con Service: Remove W Grash on lo Construction Construction Re-Contour Re-Contour Recial Fee	Groundbed on loc  Yes No A  Yire Report Repo	cation: Ves Abandoned: move Rectifier No Power Poch: Above draining draining o silt traps will be not sto Natural Totaled with BP well S	No Yes No Toles: Yes  Below A  ecessary errain: Yes hane Gas Com 00	Plugged:YesN  No Restround  Contaminated S  Remove:Yes	oil: Yes	No ocation:				
Cathodic Con Service: Remove W Grash on lo Construction C	Groundbed on loc  Yes No A  Yes Son Diversion Dita  Side  Area  Atures: Well is collocat  Access Barricae	cation: Ves Abandoned: move Rectifier No Power Poch: Above draining draining o silt traps will be not so to Natural Totaled with BP well Side: Yes	No Yes No Toles: Yes Below A  ecessary errain: Yes hane Gas Com 00 No / How:	Plugged: Yes No Retround Contaminated S Remove: Yes	oil: Yes s, where on lo	No ocation:	ch remain active wells			
Cathodic Con Service: Remove W Grash on lo Construction C	Groundbed on loc  Yes No A  Yes Son Diversion Dita  Side  Area  Atures: Well is collocat  Access Barricae	cation: Ves Abandoned: move Rectifier No Power Poch: Above draining draining o silt traps will be not so to Natural Totaled with BP well Side: Yes	No Yes No Toles: Yes Below A  ecessary errain: Yes hane Gas Com 00 No / How:	Plugged: Yes Remove: Yes  No Remove: Yes	oil: Yes s, where on lo	No ocation:	ch remain active wells			
Cathodic Con Service: Remove We Trash on le Construction	Groundbed on loc  Yes No A  Yire Resocation: Yes Yes  on Diversion Ditu  Side  Side  Side  on Silt Trap(s): No  or Disturbed Area  atures: Well is collocate  Access Barricae  on Comments / Con  ngth:	cation: Yes Abandoned: move Rectifier No Power Poch:Above _ draining draining o silt traps will be not to Natural To tated with BP well S de:Yes Remediation	No  Yes No  Tes No  Tes No  Tes No  Hes No  He	Plugged: Yes No Retround Contaminated S Remove: Yes	oil: Yes oil: Yes s, where on lo	No ocation:	ch remain active wells			
Cathodic Con Service: Remove Worash on lo Construction Co	Groundbed on loc  Yes No A  Yire Resocation: Yes Yes  on Diversion Ditu  Side  Side  Side  Side  On Silt Trap(s): No  Area atures: Well is collocated Access Barrica Con Comments / Connects / Connect	cation: Ves Abandoned: move Rectifier No Power Poch: Above draining draining o silt traps will be not to Natural Totaled with BP well Side: Yes Remediations reverse other wells a	Pon Methods:	Plugged:YesN  No	oil: Yes oil: Yes s, where on lo	No ocation:	ch remain active wells			
Cathodic Conservice: Remove Workship on local Construction Construction Re-Contour Special Ference Construction Access Let Other: The a	Groundbed on loc  Yes No A  Yire Resocation: Yes Yes  on Diversion Ditu  Side  Side  Side  on Silt Trap(s): No  or Disturbed Area  atures: Well is collocate  Access Barricae  on Comments / Con  ngth:	cation: Ves Abandoned: move Rectifier No Power Poch: Above draining draining o silt traps will be not to Natural Totaled with BP well Side: Yes Remediations reverse other wells a	Pon Methods:	Plugged:YesN  No	oil: Yes oil: Yes s, where on lo	No ocation:	ch remain active wells			
Cathodic Con Service: Remove Worash on le Construction Co	Groundbed on loc  Yes No A  Yes Yes  On Diversion Ditt  Side  Side  Side  Side  Side  Side  Side  On Silt Trap(s): No  On Disturbed Area  atures: Well is collocate  Access Barricae  On Comments / Con  Ingth:  Indication: Belo  Yes No Cat	cation: Ves Abandoned: move Rectifier No Power Poch: Above I draining draining o silt traps will be not set to Natural Totaled with BP well Serves other wells are well as we Grade  Remediations Wes Grade Ves Grade Ve	Poles: Yes Decessary  ecessary  errain: Yes  hane Gas Com 00  No / How:  amation can be perform  Acon Methods:  and will remain  Above Grade	Plugged:YesN  No	oil: Yes s, where on lo	No ocation:	ch remain active wells ion will shift to BP active we ablish Drainages			
Cathodic Construction Construct	Groundbed on loc  Yes No A  Side  Side  Side  Side  Side  Side  Side  Side  On Silt Trap(s): No  In Disturbed Area  atures: Well is collocat  Access Barrica  To Comments / Con  Ingth:  Indicess to this location is  Indition: Belo	cation: Ves Abandoned: move Rectifier No Power Poch: Above I draining draining o silt traps will be not set to Natural Totaled with BP well Serves other wells are well as we Grade  Remediations Wes Grade Ves Grade Ve	Poles: Yes Decessary  ecessary  errain: Yes  hane Gas Com 00  No / How:  amation can be perform  Acon Methods:  and will remain  Above Grade	Plugged: Yes Norman Remove: Yes  No Remove: Yes  No N	oil: Yes s, where on lo	No ocation:	ch remain active wells ion will shift to BP active we ablish Drainages			

This well location has 3 wells on it the subject well Lenis A Shane USA 001, the Shane Gas Com 001A (BP) and the #2 Federal 29-9-14 (Southland Royalties) and therefore no reclamation will be able to be performed. The meter run will be removed and the location reclamation will be shifted to the Shane Gas Com 001A at such time that it is P&A'd. Upon removal of equipment BP will file a FAN sundry shifting reclamation to BP active well per BLM approval.

## SURFACE USE PLAN OF OPERATIONS WEED MANAGEMENT

#### A.1. Pre Disturbance Weed Management Procedure and Form

During the onsite inspection, the FFO and operator's representative(s) will survey the proposed action area for noxious weeds listed on the New Mexico Department of Agriculture's A and B list (attached). If no weeds on the A or B list were observed, the FFO will indicate on the standard onsite check list form that no noxious weeds were observed within the proposed project site. If noxious weeds are found, the FFO will fill out the Onsite Noxious Weed form (attached). The FFO representative and the operator's representative will sign the form, and the FFO representative will submit the completed form to the FFO weed coordinator.

The FFO weed coordinator will review the form and analyze the noxious weed issues. The FFO weed coordinator will electronically submit to the operator within 30 days of the onsite, specific requirements and instructions for weed treatments. The requirements and instructions will include the time frame of treatment, approved herbicides that may be used, required documentation to be submitted to the FFO after treatment, and any other site specific instructions that may be applicable. Due to the seasonal nature of effective weed treatment techniques, the operator may be required to treat before ground disturbance, or may be required to treat the area after ground disturbance to avoid unreasonable delays to the operator's drilling program.

#### A.2. Class A Species

Class A species are currently not present in New Mexico, or have limited distribution. Preventing new infestations of these species and eradicating existing infestations is the highest priority.

Black henbane Camelthorn Alhagi psuedalhagi Canada thistle Canada	Common Name	Scientific Name
Camelthorn  Alhagi psuedalhagi  Canada thistle  Cirsium arvense  Dalmation toadflax  Linaria dalmatica  Centaurea diffusa  Diffuse knapweed  Degr's woad  Eurasian watermilfoil  Eurasian watermilfoil  Myriophyllum spicatum  Giant salvinia  Hoary cress  Cardaria spp.  Hydrilla  Hydrilla verticllata  Leafy spurge  Euphorbia esula  Decye daisy  Parrotfeather  Purple loosestrife  Lythrum salicaria  Purple starthistle  Centaurea calcitrapa  Ravenna grass  Saccharum ravennae  Scotch thistle  Onopordum acanthium  Yellow starthistle  Centaurea solstitialis	Alfombrilla	Drymaria arenariodes
Canada thistle  Cirsium arvense  Linaria dalmatica  Ciffuse knapweed  Centaurea diffusa  Lisatis tinctoria  Eurasian watermilfoil  Myriophyllum spicatum  Giant salvinia  Hoary cress  Cardaria spp.  Hydrilla  Leafy spurge  Cirsium arvense  Eurasian watermilfoil  Myriophyllum spicatum  Cardaria spp.  Hydrilla  Leafy spurge  Euphorbia esula  Oxeye daisy  Leucanthemum vulgare  Parrotfeather  Purple loosestrife  Lythrum salicaria  Purple starthistle  Centaurea calcitrapa  Ravenna grass  Saccharum ravennae  Scotch thistle  Onopordum acanthium  Yellow starthistle  Centaurea solstitialis	Black henbane	Hyoscyamus niger
Dalmation toadflax  Diffuse knapweed  Dyer's woad  Eurasian watermilfoil  Giant salvinia  Hoary cress  Hoary cress  Hydrilla  Leafy spurge  Dixye daisy  Parrotfeather  Purple loosestrife  Purple starthistle  Ravenna grass  Scotch thistle  Spotted knapweed  Diffuse knapweed  Centaurea diffusa  Linaria dalmatica  Centaurea diffusa  Lisatis tinctoria  Myriophyllum spicatum  Salvinia molesta  Cardaria spp.  Hydrilla Hydrilla verticllata  Leucanthemum vulgare  Myriophyllum aquaticum  Lythrum salicaria  Centaurea calcitrapa  Saccharum ravennae  Soctch thistle  Onopordum acanthium  Centaurea biebersteinii  Yellow starthistle  Centaurea solstitialis	Camelthorn	Alhagi psuedalhagi
Diffuse knapweed Dyer's woad Dyer's woad Eurasian watermilfoil Myriophyllum spicatum Giant salvinia Salvinia molesta Hoary cress Cardaria spp. Hydrilla Hydrilla verticllata Leafy spurge Euphorbia esula Dxeye daisy Leucanthemum vulgare Parrotfeather Myriophyllum aquaticum Purple loosestrife Lythrum salicaria Purple starthistle Ravenna grass Saccharum ravennae Scotch thistle Onopordum acanthium Spotted knapweed Yellow starthistle Centaurea solstitialis Centaurea solstitialis	Canada thistle	Cirsium arvense
Dyer's woad  Eurasian watermilfoil  Myriophyllum spicatum  Giant salvinia  Salvinia molesta  Hoary cress  Cardaria spp.  Hydrilla  Hydrilla verticllata  Leafy spurge  Euphorbia esula  Dxeye daisy  Parrotfeather  Purple loosestrife  Lythrum salicaria  Purple starthistle  Ravenna grass  Saccharum ravennae  Scotch thistle  Spotted knapweed  Yellow starthistle  Centaurea solstitialis  Centaurea solstitialis	Dalmation toadflax	Linaria dalmatica
Eurasian watermilfoil  Giant salvinia  Salvinia molesta  Cardaria spp. Hydrilla  Hydrilla verticllata  Euphorbia esula  Description of the surface of the su	Diffuse knapweed	Centaurea diffusa
Giant salvinia  Balvinia molesta  Cardaria spp. Hydrilla Hydrilla verticllata Leafy spurge Euphorbia esula Dxeye daisy Parrotfeather Purple loosestrife Lythrum salicaria Purple starthistle Ravenna grass Saccharum ravennae Scotch thistle Onopordum acanthium Spotted knapweed Yellow starthistle Centaurea solstitialis  Centaurea solstitialis	Dyer's woad	Isatis tinctoria
Hoary cress Cardaria spp. Hydrilla Hydrilla verticllata Leafy spurge Euphorbia esula Oxeye daisy Leucanthemum vulgare Parrotfeather Myriophyllum aquaticum Purple loosestrife Lythrum salicaria Purple starthistle Centaurea calcitrapa Ravenna grass Saccharum ravennae Scotch thistle Onopordum acanthium Spotted knapweed Centaurea biebersteinii Yellow starthistle Centaurea solstitialis	Eurasian watermilfoil	Myriophyllum spicatum
Hydrilla Hydrilla verticllata Leafy spurge Euphorbia esula Oxeye daisy Leucanthemum vulgare Parrotfeather Myriophyllum aquaticum Purple loosestrife Lythrum salicaria Purple starthistle Centaurea calcitrapa Ravenna grass Saccharum ravennae Scotch thistle Onopordum acanthium Spotted knapweed Centaurea biebersteinii Yellow starthistle Centaurea solstitialis	Giant salvinia	Salvinia molesta
Leafy spurge Euphorbia esula Dxeye daisy Leucanthemum vulgare Parrotfeather Myriophyllum aquaticum Purple loosestrife Lythrum salicaria Purple starthistle Centaurea calcitrapa Ravenna grass Saccharum ravennae Scotch thistle Onopordum acanthium Spotted knapweed Centaurea biebersteinii Yellow starthistle Centaurea solstitialis	Hoary cress	Cardaria spp.
Dxeye daisy  Leucanthemum vulgare  Myriophyllum aquaticum  Purple loosestrife  Lythrum salicaria  Purple starthistle  Ravenna grass  Saccharum ravennae  Scotch thistle  Onopordum acanthium  Spotted knapweed  Yellow starthistle  Centaurea solstitialis	Hydrilla	Hydrilla verticllata
Parrotfeather Myriophyllum aquaticum Purple loosestrife Lythrum salicaria Purple starthistle Centaurea calcitrapa Ravenna grass Saccharum ravennae Scotch thistle Onopordum acanthium Spotted knapweed Centaurea biebersteinii Yellow starthistle Centaurea solstitialis	Leafy spurge	Euphorbia esula
Purple loosestrife  Lythrum salicaria  Centaurea calcitrapa Ravenna grass Saccharum ravennae Scotch thistle Onopordum acanthium Spotted knapweed Yellow starthistle Centaurea solstitialis	Oxeye daisy	Leucanthemum vulgare
Purple starthistle  Ravenna grass  Saccharum ravennae  Scotch thistle  Onopordum acanthium  Spotted knapweed  Yellow starthistle  Centaurea solstitialis	Parrotfeather	Myriophyllum aquaticum
Ravenna grass Scotch thistle Onopordum acanthium Spotted knapweed Centaurea biebersteinii Yellow starthistle Centaurea solstitialis	Purple loosestrife	Lythrum salicaria
Scotch thistle  Onopordum acanthium  Centaurea biebersteinii  Yellow starthistle  Centaurea solstitialis	Purple starthistle	Centaurea calcitrapa
Spotted knapweed Centaurea biebersteinii Yellow starthistle Centaurea solstitialis	Ravenna grass	Saccharum ravennae
Yellow starthistle Centaurea solstitialis	Scotch thistle	Onopordum acanthium
WE SELDS SUPPLIED TO PERSONS AND ADDRESS OF THE PERSONS AND ADDRESS AND ADDRESS OF THE PERSONS AND ADDRESS OF THE PERSONS AND ADDRESS AND ADDRES	Spotted knapweed	Centaurea biebersteinii
Yellow toadflax Linaria vulgaris	Yellow starthistle	Centaurea solstitialis
	Yellow toadflax	Linaria vulgaris

### A.3. Class B Species

Class B species are limited to portions of the state. In areas with severe infestations, management should be designed to contain the infestation and stop any further spread.

Common Name	Scientific Name
African rue	Peganum harmala
Chicory	Cichorium intybus
Halogeton	Halogeton glomeratus
Malta starthistle	Centaurea melitensis
Musk thistle	Carduus nutans
Perennial pepperweed	Lepidium latifolium
Russian knapweed	Acroptilon repens
Poison hemlock	Conium maculatum
Teasel	Dipsacus fullonum
Tree of heaven	Ailanthus altissima

## **Onsite Noxious Weed Form**

Oper	xious weeds a	1				Surv	veyor(	s) S.	Beebe,	BP / S. Mos	kal, BP	/ Bob	Switzer, BLM
	Name and No									Date 3/3	3/2016	100	
Loca	tion: Townsh	ip, Ra	inge, S	Section 2	9N, 9V	V, 14	700 ESI			1675	CIAII	32	
Loca	tion of Projec	t NAI	0 83 1	Jecimal	Degi	ees /	90 FSL		-	1675	FVVL	-0.00	
		Cla			us V	Veed	l – C	hec	k Bo	x if Fou	nd		
	Alfombrilla		Diffu			Hyd	rilla			Purple starthistle	1		Yellow toadflax
	Black henbane		-	's woad		Leaf	y spurg	e		Ravenna g	grass		
	Camelthorm		Euras	sian milfoil		Oxe	ye daise			Scotch thi	stle		3-7
	Canada thistle		Giant	salvinia			otfeathe	r		Spotted knapweed			Service .
	Dalmation toadflax		Hoar	y cress		Purp	le estrife			Yellow starthistle			
		Cla	ass B	Noxio	us V	Veed	1 – C	hec	k Bo	x if Fou	nd		
	African rue			Perennia pepperw		C IV		Rus	sian k	napweed		Tree	of heaven
	Chicory			Musk thi	stle			Poi	son her	mlock			
	Halogeton			Malta sta	arthist	le		Tea	sel				
	nments: No Noxious	Weed	ds ide	entified o	durin	g site	e insp	ecti	on.				
	Represent	tativ	e:									Tes	A.
	nd date erator Rep	rese	ntati	ve sak	ore.b	eeb	e@bp	.cor	n ,	Digitally signed by sab DN: cn=sabre beebeal Date: 2016.03.08 11:57	bp.com	com	

# UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

6251 COLLEGE BLVD. FARMINGTON, NEW MEXICO 87402

Attachment to notice of Intention to Abandon:

Re: Permanent Abandonment Well: Lenis A. Shane USA 1

#### **CONDITIONS OF APPROVAL**

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."
- 2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 564-7750.

Operator must run a CBL to verify cement top. Submit the electronic copy of the log for verification to the following addresses: jwsavage@blm.gov Brandon.Powell@state.nm.us

Low concentrations of H<sub>2</sub>S (2 ppm -< 100 ppm GSV) have been reported in several wells within a 1 mile radius of this location.

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.