RECEIVED

Form 3160-5 (February 2005)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

APR 2 / 201

FORM APPROVED OMB No. 1004-0137 Expires: March 31, 2007

Expires: March 31, 200

5. Lease Serial No.

SUNDRY NOTICES AND REPORTS ON WELLES mington Field Office MMNM 057164 Do not use this form for proposals to drill or to revenue of and Management 6. If Indian, Allottee or Tribe Name abandoned well. Use Form 3160-3 (APD) for such proposals. 7. If Unit of CA/Agreement, Name and/or No. SUBMIT IN TRIPLICATE - Other instructions on page 2. 1. Type of Well 8. Well Name and No. Lybrook 2309 34B #765 Oil Well Gas Well Other 2. Name of Operator 9. API Well No. WPX Energy Production, LLC 30-045-35731 3a. Address 3b. Phone No. (include area code) 10. Field and Pool or Exploratory Area PO Box 640 Aztec, NM 87410 505-333-1808 **Basin Mancos** 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 11. Country or Parish, State SHL: 550' FNL & 1508' FEL SEC 34 23N 9W San Juan, NM BHL: 399' FNL & 1516' FEL SEC 34 23N 9W 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Water Shut-Off Acidize Deepen Production (Start/Resume) Notice of Intent Fracture Treat Well Integrity Alter Casing Reclamation New Construction Other Casing Repair Recomplete Subsequent Report SPUD SURFACE Plug and Abandon Temporarily Abandon Change Plans CASING Convert to Final Abandonment Notice Plug Back Water Disposal Injection 13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.) NOTE: MO-TE SET SURFACE 4/25/16- SPUD @ 11:30hrs. TD 12-1/4" Surf Hole @ 325'. RU &Ran 15jts, 9-5/8", ST&C, 36#, J-55, csg set @ 320', FC @ 295'. Pumped 10bbls FW spacer, dumped 28.9bbls (101sx) Type I-II w/ 20% fly-ash @ 14.5PPG into casing, dropped plug & displaced w/ 23bbls H2O, bumped plug @ 350psi, circulated 8bbls of good cmt to surface. RDMO Mo-Te. NOTE: WPX will MI AWS to Install & test BOP at a later date. We will file another sundry at that time. ACCEPTED FOR RECORD 14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed) Marie E. Jaramillo Permit Tech FARMINGTON FIELD OFFI 4/26/16 THIS SPACE FOR FEDERAL OR STATE OFFICE USE Approved by Title Date Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease Office which would entitle the applicant to conduct operations thereon. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

