			RECEIVED		
	UNITED STA DEPARTMENT OF TA UREAU OF LAND M	HE INTERIOR	APR 0 5 2016	Expires: March 31, 2007	
SUNDRY	NOTICES AND REF	ORTS ON WELLS	minaton Field O	5. Lease Serial No. ffichemisf 078771	
Do not use this	form for proposals	to drill or to receipt	teroahand Mana	ement 6. If Indian, Allottee or Tribe Name	
abandoned well. Use Form 3160-3 (APD) for such proposals. SUBMIT IN TRIPLICATE – Other instructions on page 2.				7. If Unit of CA/Agreement, Name and/or No.	
1. Type of Well				NMNM 78407E	
Oil Well Gas Well Other				8. Well Name and No. Rosa Unit #642H	
2. Name of Operator				9. API Well No.	
WPX Energy Production, LLC 3a. Address 3b. Phone No. (incl			area code)	30-039-31315 10. Field and Pool or Exploratory Area	
PO Box 640 Aztec, NM 87410		505-333-1808		Basin Mancos	
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) SHL: 975' FNL & 524' FWL SEC 19 T31N R5W BHL: 1309' FNL & 1' FEL SEC 23 T31N R6W				11. Country or Parish, State Rio Arriba, NM	
12. CHECK T	THE APPROPRIATE BOX	ES) TO INDICATE NAT	URE OF NOTICE, RE	EPORT OR OTHER DATA	
TYPE OF SUBMISSION		TYPE OF ACTION			
Notice of Intent	Acidize	Deepen	Start/Resu	Water Shut-Off	
	Alter Casing	Fracture Treat	Reclan	·	
Subsequent Report	Casing Repair	New Construction	Recom	Other Completion	
	Change Plans	Plug and Abandon	Tempo	orarily	
Final Abandonment Notice	Convert to Injection	Plug Back	Abandon Water	Disposal	
of the involved operations. If the o	peration results in a multiple con be filed only after all requirement te squeeze sundry dated	npletion or recompletion in a ration, including reclamation, hav	new interval, a Form 3160 e been completed and the	the must be filed within 30 days following completion. 0-4 must be filed once testing has been completed. operator has determined that the site is ready for final OIL CONS. DIV DIST ,	
<u>13/10-</u> 1 au prep 101 11ac. 1 31	test polly lines wy all to	199bar neid for 19mma,	, no leak on-6000 t	APR 1 1 2016	
3/16/16-3/21/16-Prep for DFIT & monitor DFIT pressure.			1	ALA 1 1 2010	
3/22/16-RU Frac. PSI test Frac Iron to 9800psi-held for 15min. Good test.			CONF	IDENTIAL	
<u>3/23/16</u> -					
				-12125′ — w/ 355,740# 40/70 PSA Sand. s 2 nd stage w/ 358,521# 40/70 & 100	
et flo-thru Frac plug @ 11630'	MD. Perf 3 rd stage 1140	4'- 11589'- w/ 24, 0.35'	' holes. Frac Manco	s 3 rd stage w/ 358,537#, 40/70 & 100	
/lesh PSA Sand et flo-thru Frac plug @ 11379'	MD. Perf 4 th stage 1119	8'-11354'- w/ 24. 0.35"	holes.		
 I hereby certify that the foregoing Name (Printed/Typed) 					
Marie E. Jaramillo			Title Permit Tech		
Signature MOUL	THIS SPACE FO	DR FEDERAL OR S	Date 4/5/16	IISE	
pproved by	THIS OF AGE PO	INTEDENAL ON			
Conditions of approval, if any, are attached Approval of this notice does not warrant or cert he applicant holds legal or equitable title to those rights in the subject lease which would er applicant to conduct operations thereon.				ACCEPTED FOR RECORD	
	e 43 U.S.C. Section 1212, mal			to make to any department of agarcy of the 2016	
	Copyright 2006 Forms in Word			-branch use only FARMINGTON FIELD OFFICE	

NMOCD

W: William Tambekouz

Rosa Unit #642H Pg. 2

3/24/16-Frac Mancos 4th stage w/ 357,931# 40/70 & 100 Mesh PSA Sand.

Set flo-thru Frac plug @ 11180' MD. Perf 5th stage 10992'-11148'-w/ 24, 0.35" holes. Frac Mancos 5th stage w/ 359,176#, 40/70 & 100 Mesh PSA Sand

Set flo-thru Frac plug @ 10967' MD. Perf 6th stage 10786'-10941'- w/ 24, 0.35" holes. Frac Mancos 6th stage w/ 359,180#, 40/70 & 100 Mesh PSA Sand

Set flo-thru Frac plug @ 10760' MD. Perf 7th stage 10576'-10735'- w/ 24, 0.35" holes. Frac Mancos 7th stage w/ 358,721#, 40/70 & 100 Mesh PSA Sand

Set flo-thru Frac plug @ 10555' MD. Perf 8th stage 10374'-10529'- w/ 24, 0.35" holes. Frac Mancos 8th stage w/ 358,875#, 40/70 & 100 Mesh PSA Sand

Set flo-thru Frac plug @ 10346' MD. Perf 9th stage 10168'-10324'- w/ 24, 0.35" holes. Frac Mancos 9th stage w/ 358,701#, 40/70 & 100 Mesh PSA Sand

Set flo-thru Frac plug @ 10143' MD. Perf 10th stage 9962'-10118'- w/ 24, 0.35" holes.

3/25/16

Frac Mancos 10th stage w/ 358,886#, 40/70 & 100 Mesh PSA Sand

Set flo-thru Frac plug @ 9937' MD. Perf 11th stage 9756'-9912'- w/ 24, 0.35" holes. Frac Mancos 11th stage w/ 358,870#, 40/70 & 100 Mesh PSA Sand

Set flo-thru Frac plug @ 9731' MD. Perf 12th stage 9550'-9705'- w/ 24, 0.35" holes. Frac Mancos 12th stage w/ 358,690# 40/70 & 100 Mesh PSA Sand

Set flo-thru frac plug @ 9525' MD. Perf 13th stage 9344'-9499'- w/ 24, 0.35" holes. Frac Mancos 13th stage w/ 358,743#, 40/70 & 100 Mesh PSA Sand

Set flo-thru Frac plug @ 9319' MD. Perf 14th stage 9138'-9289'- w/ 24, 0.35" holes. Frac Mancos 14th stage w/ 359,231# 40/70 & 100 Mesh PSA Sand

Set flo-thru Frac plug @ 9120' MD. Perf 15th stage 8932'-9087'- w/ 24, 0.35" holes. Frac Mancos 15th stage w/ 358,927# 40/70 & 100 Mesh PSA Sand

Set flo-thru Frac plug @ 8907' MD. Perf 16th stage 8726'-8882'- w/ 24, 0.35" holes.

3/26/16-Frac Mancos 16th stage w/ 358,742# 40/70 & 100 Mesh PSA Sand.

Set flo-thru Frac plug @ 8701' MD. Perf 17th stage 8520'-8676'- w/ 24, 0.35" holes. Frac Mancos 17th stage w/ 358,718# 40/70 & 100 Mesh PSA Sand

Set flo-thru Frac plug @ 8495' MD. Perf 18th stage 8314'-8470'- w/ 24, 0.35" holes. Frac Mancos 18th stage w/ 358,874# 40/70 & 100 Mesh PSA Sand

Set flo-thru Frac plug @ 8289' MD. Perf 19th stage 8108'-8263'- w/ 24, 0.35" holes. Frac Mancos 19th stage w/ 358,987# 40/70 & 100 Mesh PSA Sand

Set flo-thru Frac plug @ 8083' MD. Perf 20th stage 7902'-8057'- w/ 24, 0.35" holes. Frac Mancos 20th stage w/ 358,801# 40/70 & 100 Mesh PSA Sand

Set flo-thru Frac plug @ 7877' MD. Perf 21st stage 7696'-7851'- w/ 24, 0.35" holes. Frac Mancos 21st stage w/ 358,711# 40/70 & 100 Mesh PSA Sand

Set flo-thru Frac plug @ 7675' MD. Perf 22nd stage 7490'-7645'- w/ 24, 0.35" holes. Frac Mancos 22nd stage w/ 358,764# 40/70 & 100 Mesh PSA Sand

Set flo-thru Frac plug @ 7465' MD. Perf 23rd stage 7284'-7440'- w/ 24, 0.35" holes. Frac Mancos 23rd stage w/ 368,620# 40/70 & 100 Mesh PSA Sand

3/27/16-RDMO Liberty Oilfield / Basin Wireline. Prep pad for DO & RU flow back.

3/28/16-RU CUDD 2" Coil Unit. Make up BHA as follows: 3 7/8" Verral Tri cone. Pressure test to 5000psi coil stack and flowback. RIH, w/ coil to tag fill @ 7300. DO Flo thru Frac plug @ 7465', 7675', 7877', 8083', 8289', & 8495'.

<u>3/29/16</u>-DO Flo thru Frac plug @ 8701', 8907', 9120', 9319', 9525', 9731', 9937', 10143', 10346', 10555', 10760', 10967', 11180', 11379', 11360', & 11894'.

3/30/16-TOOH w/ coil tubing. RDMO CUDD coil tubing.

First gas delivered to sales.

Install 5K 7 1/16" BOP and pressure test- Low test to 300psi high-Good Test.

3/31/16-RIH Landed @ 7042' w/ 25' KB as follows, 218jts, 2 3/8" of L-80 4.7# 6976', X-nipple 1.25', 1jt L-80 32.32, XN Nipple 1.25', 8' L-80 pup 8.05'. RD snubbing unit NU wellhead and pump off plug.

4/1/16-Choke Size= 24/64", Tbg Prsr= 1870psi, Csg Prsr=2425psi, Flow Rate= 4.067mcf/d, 24hr Fluid= 647bph,