	Submit 1 Copy To Appropriate Distr	rict St	State of New Mexico			Form C-103		
	Office <u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 882		Energy, Minerals and Natural Resources			Revised July 18, 2013 WELL API NO.		
	District II – (575) 748-1283		OIL CONCEDUATION DIVISION			30-31- 05265- 05266		
	811 S. First St., Artesia, NM 88210 District III – (505) 334-6178		OIL CONSERVATION DIVISION			5. Indicate Type of Lease		
	1000 Rio Brazos Rd., Aztec, NM 87	410	1220 South St. Francis Dr.			STATE FEE 🖂		
		District IV – (505) 476-3460 Santa Fe, NM 87505 1220 S. St. Francis Dr., Santa Fe, NM 87505			6. State Oil & Ga Fee	is Lease No.		
	SUNDRY NOTICES AND REPORTS ON WELLS				7. Lease Name or Unit Agreement Name			
	(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH				Farris 8. Well Number 002			
,	PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other				o. Well realises 2002			
	2. Name of Operator				9. OGRID Numb	er		
	Farris Mines 3. Address of Operator				10. Pool name or	Wildest	-	
	419 Palomino Lane, Bloom	mfield, NM 87413 505	5-632-8438		Seven Lakes	Wildcat		
	4. Well Location 4	90		996)'		\neg	
	Unit Letter P9		<u>S</u> 1	ine and 330		he <u>E</u> line		
	Section 18	Townsh	ip 18N	Range 10	W NMPM	McKinley		
2	County	11 Flevation (Show whather DR	, RKB, RT, GR, etc.		220 G S S S S S S S S S S S S S S S S S S	77. A. W.	
5		6540' Gl	snow whether DN	, KKB, K1, GK, etc.,				
	12. Ch	eck Appropriate Bo	x to Indicate N	lature of Notice,	Report or Other	Data		
	NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:							
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORK						ALTERING CASING [
	TEMPORARILY ABANDON	☐ CHANGE PLAN	The state of the s	COMMENCE DRI		P AND A	\times	
	PULL OR ALTER CASING	☐ MULTIPLE COI	MPL	CASING/CEMEN	Г ЈОВ □			
	DOWNHOLE COMMINGLE							
le.	CLOSED-LOOP SYSTEM OTHER:			OTHER:		г	7	
	13. Describe proposed or	completed operations.	(Clearly state all		d give pertinent date	es, including estimated	date	
	of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of							
	proposed completion Farris Mines Plugged	•	well on May 1	1. 2016 ner the at	tached report by	A-Plus Well Service		
	Farris Mines Plugged and Abandoned this well on May 11, 2016 per the attached report by A-Plus Well Service.							
	Plug #1 with 48 sxs (56.64 cf) Class B cement from 348' to surface circulate good cement out 5-1/2" casing. Tag TOC at 25'. Plug #2 with 10 sxs Class B cement top off casings and install on P&A marker with coordinates N 35° 47' 4" W 107° 56' 6".							
	5/10/16 Rode rig and equip	pment to location. RU a	nd SDFD. Trave	back to A-Plus yard	I.			
	5/11/16 Travel to location.	Open up well: no press	ures. X-over to r	od tools. Attempt to	unseat pump, una	ble to unseat pump. Pl	J on	
	5/11/16 Travel to location. Open up well; no pressures. X-over to rod tools. Attempt to unseat pump, unable to unseat pump. PU or tubing and slips. Well had old tubing head, tubing 2-1/16" IJ. Strip off tubing head and strip on 5-1/2" x 8-5/8" tubing head and 8-5/8" companion flange. Strip on BOP. Strip out 2-1/16" tubing using 2-1/16" x 2-3/8" x- over and 3' 2-3/8" sub. LD 1 – 12							
	sub, cut 5/8 rod with hacksaw, LD 10 jnts 2-1/16" with rod pump, 1-8' MA using same method. Round trip 5-1/2" A-Plus str mill to 352' and tag. Circulate well clean. TOH with tubing. Spot plug #1 with TOC at surface. ND BOP and companion flar							
	and tubing head. RD rig. Dig out wellhead. Cut off wellhead. Tag TOC down 25' in 5-1/2" casing. Spot plug #2 top off cas and install on P&A marker with coordinates N 35° 47' 4" W 107° 56' 6".							
	and install on Pax i	marker with coordinates	N 35 47 4 W	07 30 0 .		OIL CONS. DIV DIST	F 0	
						ו פוע עום .סווסס	. 3	
	Spud Date:		Rig Release D	ate:		MAY 3 1 2016		
*	well mixed up with Fac	via #2 during also	9/A -	sker will man	re " alate			
•	I hereby certify that the information above is true and complete to the best of my knowledge and belief.							
	•							
	SIGNATURE BUIL		TITLE	A-Plus Field Supervi	cor DA	TE 5/26/16		
	SIGNATURE PARIL	w ;	IIILEA	x-rius rieid Supervi	SUIDA	TE5/26/16	-	
	Type or print name Bill Ra	ndall E-mail ad	dress:billr@	apluswell.com_		PHONE:325-2627_	_	
	For State Use Only	200	Dan	Oil 0 O !-		4		
	APPROVED BY:	all	TITLE	ty Oil & Gas In District #3	ispector, DA	TE 10/5/16		
	Conditions of Approval (if any			VISTRICT #3				