RECEIVED

Form 3160-5 (February 2005)

UNITED STATES DEPARTMENT OF THE INTERIOR

OCT 1 8 2016

FORM APPROVED OMB No. 1004-0137 Expires: March 31, 2007

BUREAU OF LAND MANAGEMENT Farmington Field Offices. Lease Serial No. Expires: March 31, 2007 Bureau of Land Managerhe Jicarilla Apache Contract #92 Do not use this form for proposals to drill or to re-enter an 6. If Indian, Allottee or Tribe Name Jicarilla Apache Nation abandoned well. Use Form 3160-3 (APD) for such proposals. SUBMIT IN TRIPLICATE - Other instructions on page 2. 7. If Unit of CA/Agreement, Name and/or No. 1. Type of Well OIL CONS. DIV DIST. 3 8. Well Name and No. Jicarilla 92 #18A Gas Well Oil Well Other OCT 2 1 2016 9. API Well No. 2. Name of Operator WPX Energy Production, LLC 30-039-29943 10. Field and Pool or Exploratory Area 3a. Address 3b. Phone No. (include area code) PO Box 640 505-333-1816 Aztec, NM 87410 Blanco MV 11. Country or Parish, State 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 1850' FNL & 2000' FEL SEC 29, T27N, R3W Rio Arriba, NM 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Water Shut-Off Acidize Deepen Production (Start/Resume) Notice of Intent Fracture Treat Well Integrity Alter Casing Reclamation Other New Construction Casing Repair Recomplete Request MIT/TA Subsequent Report Change Plans Plug and Abandon Temporarily Abandon Convert to Injection Water Disposal Plug Back Notice 13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No, on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.) WPX received TA status until 11/1/17. The MIT was conducted on 10/14/16. BLM-Jicarilla (Bryce Hammond) and OCD (Monica) were on location at the time of the test. Tested good.

ACCEPTED FOR RECORD test. Tested good. Attached is the pressure test chart and updated wellbore. OCT 1 8 2016 FARMINGTON FIELD OFFICE 14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed) Lacey Granillo Permitting Tech III Signature 10/18/16 CE FOR FEDERAL OR STATE OFFICE USE Approved by Title Date Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease Office which would entitle the applicant to conduct operations thereon.


(Instructions on page 2)



Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the

United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Jicarilla 92 #18A Blanco Mesa Verde



TD @ 6641' PBTD @ 6370'

HOLE SIZE	CASING	CEMENT	CU. FT.	CMT TOP
12-1/4"	9-5/8",36#	200 s xs	240 cu.ft.	surface
8-3/4"	7",23#	545 s xs	1330 cu.ft.	surface
6-1/4"	4-1/2", 11.6#	250 s xs	342 cu.ft.	4290' (CBL)

