Form	3160-5
(June	2015)

UNITED STATES DEPARTMENT OF THE INTERIOR

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 201

BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.				Lease Serial No. NMSF078384 If Indian, Allottee or Tribe Name If Unit or CA/Agreement, Name and/or No.	
SUBMIT IN TRIPLICATE - Other instructions on page 2					
1. Type of Well ☐ Oil Well ☐ Gas Well ☐ Other				8. Well Name and No. NEWSOM B 20	
Name of Operator COLEMAN OIL & GAS INCORPORATEMail: mhanson@cog-fmn.com			9. API Well No. 30-045-24505-00-S1		
3a. Address FARMINGTON, NM 87499	end o	3b. Phone No. (include area code) Ph: 505-327-0356 Ext: 106 Fx: 505-327-9425		10. Field and Pool or Exploratory Area BALLARD PICTURED CLIFFS	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Sec 5 T26N R8W NWSW 1850FSL 0790FWL 36.514114 N Lat, 107.711014 W Lon NOV 2.8 2016			-	11. County or Parish, State SAN JUAN COUNTY, NM	
12. CHECK THE AI	PPROPRIATE BOX(ES)	TO INDICATE NATURE O	F NOTICE,	REPORT, OR OTI	HER DATA
TYPE OF SUBMISSION	TYPE OF ACTION				
Notice of Intent □ Subsequent Report	☐ Acidize ☐ Alter Casing ☐ Casing Repair	☐ Deepen ☐ Hydraulic Fracturing ☐ New Construction	☐ Production (Start/Resume) ☐ Reclamation ☐ Recomplete		☐ Water Shut-Off ☐ Well Integrity ☐ Other
Final Abandonment Notice	☐ Change Plans ☐ Convert to Injection	☑ Plug and Abandon ☐ Plug Back	☐ Temporarily Abandon ☐ Water Disposal		St. +
following completion of the involved	ally or recomplete horizontally, rk will be performed or provide operations. If the operation re bandonment Notices must be fil	nt details, including estimated startingive subsurface locations and measurthe Bond No. on file with BLM/BIA sults in a multiple completion or record only after all requirements, including the substantial of the substantia	red and true ver Required sub empletion in a n	rtical depths of all pertir sequent reports must be ew interval, a Form 316	nent markers and zones. filed within 30 days 60-4 must be filed once

Coleman Oil & Gas proposes to P&A this well per the attached procedure, reclamation plan.

Notify NMOCD 24 hrs prior to beginning operations

SEE ATTACHED FOR CONDITIONS OF APPROVAL

BLM'S APPROVAL OR ACCEPTANCE OF THIS ACTION DOES NOT RELIEVE THE LESSEE AND OPERATOR FROM OBTAINING ANY OTHER AUTHORIZATION REQUIRED FOR OPERATIONS ON FEDERAL AND INDIAN LANDS

14. I hereby certify that the	ne foregoing is true and correct. Electronic Submission #357600 verifie For COLEMAN OIL & GAS INCORF Committed to AFMSS for processing by ABDEL	ORATE	D. sent to the Farmington	1SE)		
Name (Printed/Typed)	MICHAEL T HANSON	Title	ENGINEER			
Signature	(Electronic Submission)	Date	11/10/2016	5		
THIS SPACE FOR FEDERAL OR STATE OFFICE USE						
Approved By ABDELO	GADIR ELMANDANI	TitleF	PETROLEUM ENGINEER	Date 11/21/2016		
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		Office	Farmington			
Title 18 U.S.C. Section 100 States any false, fictitious	I and Title 43 U.S.C. Section 1212, make it a crime for any pe or fraudulent statements or representations as to any matter w	rson kno ithin its j	owingly and willfully to make to any departure of the control of t	rtment or agency of the United		

(Instructions on page 2)
*** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **





Coleman Oil & Gas, Inc.

Final P&A Procedure **Ballard Pictured Cliffs**

Thursday, November 03, 2016

Well:

Newsom B20

SL Location:

1850' FSL & 790' FWL (NWSW) Sec 5, T26N, R8W, NMPM

San Juan County, New Mexico

Field: Ballard Pictured Cliffs

Elevation: 6207' RKB

6194' GL

Lease:

SF-078384

API#:

30-045-24505

Ballard Pictured Cliffs: 2026-2107, Producing. Cast Iron Bridge Plugs @ 2850, 3550, 4244


Original PBTD at 4470 FT GL

Procedure: All cement volumes use 100% excess outside pipe and 50' excess inside. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures. All cement will be Class B, mixed at 15.6 ppg with a 1.18 cf/sx yield. (Note: This procedure will be adjusted on site based upon actual conditions)


- 1. Review and Comply with Regulatory Requirements.
- 2. MIRU Well Service Rig and Equipment.
- 3. Nipple up BOP equipment. Function test BOP.
- 4. Tag with Production Tubing. POOH and Tally Tubing.
- 5. RIH with Cement Retainer on tubing and set at + 1976 FT KB. May want to run casing scraper prior to setting retainer.
- 6. Pressure Test Tubing, Unstring from retainer roll hole and pressure test casing.
- 7. Place Minimum 10 sacks cement on top of Cement Retainer.
- 8. Plug #2 Cement Fruitland Top from 1757'- 1657' Inside 4 1/2" Casing with 12 sacks neat cement. Plug #2 inside plug based on Long String Cement to Surface. Attempt to pressure test Braden head annulus to 300 psig, note volume to load.
- 9. Plug #3 Cement Kirtland Top, 1373-1273. Plug #3 inside plug based on Long String Cement to Surface.
- 10. Plug #4 Cement Ojo Alamo Top, 1058-958. Plug #4 inside plug based on Long String Cement to Surface.
- 11. Plug # 5 Cement Base of Surface Casing, 357-257. Plug #5 inside plug based on Long String Cement to Surface.

- Plug #6 Surface, 100-0. Plug #6 inside plug based on Long String Cement to Surface.
- 13. Cut off well head and top off casing and annulus as necessary with cement.
- 14. Install dry hole marker, remove production equipment and reclaim location.

COLEMAN OIL GAS, INC. NEWSOM B20 PRODUCING



COLEMAN OIL GAS, INC. NEWSOM B20 PROPOSED P&A



UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

6251 COLLEGE BLVD. FARMINGTON, NEW MEXICO 87402

Attachment to notice of Intention to Abandon: Re: Permanent Abandonment

Well: Newsom B#20

CONDITIONS OF APPROVAL

- Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."
- 2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 564-7750.
 - a) Combine plug #3 and plug #4 Set Plug (1375 -1111) ft. to cover the entire Ojo Alamo formation. BLM picks top of Ojo Alamo at 1161 and the Bottom of the Ojo Alamo at 1325 ft.

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.