

## **United States Department of the Interior**

## BUREAU OF LAND MANAGEMENT

Farmington District Office 6251 College Blvd. - Suite A Farmington, New Mexico 87402 www.blm.gov/nm



In Reply Refer To: NMNM73621 3105 (21110)

December 29, 2016

Logos Operating, LLC 2010 Afton Place Attn: Mr. Lewis Farmington, NM 87401 OIL CONS. DIV DIST. 3

Dear Mr. Lewis:

Enclosed please find three copies of the Designation of Successor of Operator for the following Communitization Agreements:

Communitization Agreement No. NMNM73621 (14080017357)

Well Name & No.: Gordon A No.2 (Blanco Dakota) Lots1-4, W2E/2 (E/2), API: 30-045-306336 of Section 24, Township 27 N., Range 10 W., SESE, San Juan County, New Mexico

Well Name & No.: Gordon A No. 2E (Blanco Dakota) Lots1-4, W2E/2 (E/2), API: 30-045-34811 of Section 24, Township 27 N., Range 10 W., SENE, San Juan County, New Mexico

Under the terms of the Designation of Successor Operator, Logos Operating, LLC agrees to fulfill the duties and obligations of operator of the communitized area; pursuant to the terms and conditions of the referenced communitization agreement. Logos Operating, LLC has demonstrated sufficient bonding including but not limited to BLM Statewide Bond Number NMB000917.

The instrument is hereby accepted for the record purposes effective July 1, 2016. In accepting this designation, the Authorized Officer neither warrants no certifies that the designated party has obtained all required approvals that would entitle it to conduct operations.

Under provisions of 43 CFR 3165.3, you may request an Administrative Review of the orders described above. Such request, including all supporting documents, must be filed in writing within 20 business days of receipt of this notice and must be filed with the State Director, Bureau of Land Management (NM-93000), P.O. Box 27115, Santa Fe, New Mexico 87502-0015. Such

requests shall not result in a suspension of the order(s) unless the reviewing official so determines. Procedures governing appeals from instructions, orders or decisions are contained in 43 CFR 3165.4 and 43 CFR 4.400 et seq.

If you have any questions, regarding this Designation of Successor Operator Change, please contact Cynthia Marquez at (505) 564-7741 or e-mail cmarquez@blm.gov.

Sincerely,

Cynthia Marquez

Land Law Examiner

Petroleum Management Branch

Distribution: NMOCD-1

CA File: NMNM73621-1

NMF0110: CMarquez: cm: 12/29/2016: X7741: U: DSO: Logos