Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

RECEIVED

JAN 0 3 2017

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enteranned NGTON FIELD OFF abandoned well. Use form 3160-3 (APD) for such proposals.					NMSF078097		
					6. If Indian, Allottee or Tribe Name		
SUBMIT IN TRIPLICATE - Other instructions on page 2					7. If Unit or CA/Agreement, Name and/or No.		
1. Type of Well					8. Well Name and No. HEATON LS 016		
☐ Oil Well ☑ Gas Well ☐ Other							
2. Name of Operator Contact: SABRE BEEBE BP AMERICA E-Mail: sabre.beebe@bp.com					9. API Well No. 30-045-13134		
3a. Address 200 ENERGY COURT FARMINGTON, NM 87401	. (include area code) 5-7530	10. Field and Pool or Exploratory Area BASIN DAKOTA					
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					11. County or Parish, State		
Sec 28 T31N R11W 1843FSL 1056FWL					SAN JUAN COUNTY COUNTY, NM		
12. CHECK THE AF	PROPRIATE BOX(ES)	TO INDICA	TE NATURE O	F NOTICE,	REPORT, OR OTH	IER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION						
☐ Notice of Intent	☐ Acidize	☐ Dee	Deepen Production		on (Start/Resume)	■ Water Shut-Off	
	☐ Alter Casing	☐ Hydraulic Fracturing		■ Reclamation		■ Well Integrity	
Subsequent Report	sequent Report Casing Repair		Construction		lete	Other	
☐ Final Abandonment Notice	☐ Change Plans	e Plans 🔲 Plug		l Abandon Temporaril			
	☐ Convert to Injection	☐ Plug	☐ Plug Back ☐ Y		isposal		
13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. The Heaton LS 016 well API 30-045-13134 was plugged and abandoned on 11/20/1996. As of 9/16/2016 BP has completed reclamation work to include equipment removal, re-contouring and seeding of location. On December 1, 2016 Sabre Beebe, BP and Randy McKee, BLM performed a site visit to evaluate the reclamation work performed. Mr. McKee approved all work performed on location and agrees the location is ready for monitoring of re-vegetation. Should you have any questions or concerns regarding this matter please contact Sabre Beebe, BP Compliance Specialist at sabre beebe@bp.com or 970-779-9398.							
					AL	N 19 2017	
14. I hereby certify that the foregoing is	Electronic Submission #3	362511 verifie AMERICA, se	d by the BLM Wel	II Information Iton	System		
Name (Printed/Typed) SABRE BEEBE			Title COMPLIANCE SPECIALIST				
Signature (Electronic Submission)			Date 01/03/2	017			
THIS SPACE FOR FEDERAL OR STATE OFFICE USE							
Approved By MOUNTIN R			Title St.	U		Date 1117	
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.			Office U	364			
				-			

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

