UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

SUNDRY NOTICES	AND REPORTS ON WELLS	

 Lease Serial No. NMSF078390

Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposition NINGTON FIELD O	6. Gr Indian, Allottee or Tribe Name
abandoned wen. Ose form 5100-5 (AFD) for such proposate.	

1			
SUBMIT IN TRIPLICATE - Other instructions on page 2		7. If Unit or CA/Agreement, Name and/or No.	
1. Type of Well	ther		8. Well Name and No. JONES A LS 013
2. Name of Operator BP AMERICA			9. API Well No. 30-045-23849
3a. Address 200 ENERGY COURT FARMINGTON, NM 87401		3b. Phone No. (include area code) Ph: 970-375-7530	10. Field and Pool or Exploratory Area BLANCO PICTURED CLIFFS
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		11. County or Parish, State	
Sec 10 T28N R8W 900FSL 1090FWL		SAN JUAN COUNTY COUNTY, NM	

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
□ Notice of Intent	□ Acidize	Deepen	Production (Start/Resume)	□ Water Shut-Off
Subsequent Report	Alter Casing	Hydraulic Fracturing	Reclamation	Well Integrity
	Casing Repair	New Construction	Recomplete	Other
Final Abandonment Notice	Change Plans	Plug and Abandon	Temporarily Abandon	
	Convert to Injection	Plug Back	U Water Disposal	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.

The Jones A LS 013 well API 30-045-23849 was plugged and abandoned on 1/26/1998. As of 10/21/2016 BP has completed reclamation work to include equipment removal, re-contouring, and seeding of location. On December 20, 2016 Sabre Beebe, BP and Randy McKee, BLM performed a site visit to evaluate the reclamation work performed. Mr. McKee approved all work performed on location and agrees the location is ready for monitoring of re-vegetation.

Should you have any questions or concerns regarding this matter please contact Sabre Beebe, BP Compliance Specialist at sabre.beebe@bp.com or 970-779-9398.



14. I hereby certify that the foregoing is true and correct. Electronic Submission #362586 verified by the BLM Well Information System For BP AMERICA, sent to the Farmington			
Name (Printed/Typed) SABRE BEEBE	Title COMPLIANCE SPECIALIST		
Signature (Electronic Submission)	Date 01/03/2017		
THIS SPACE FOR FEDERAL OR STATE OFFICE USE			
Approved By MWILL In	Title HTM Date MM		
Conditions of approval, if any, are attached. Approval of this notice does no certify that the applicant holds legal or equitable title to those rights in the su which would entitle the applicant to conduct operations thereon.	t warrant or bject lease Office BM		
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.			
(Instructions on page 2) ** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED **			