Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

Empireo: validary 51, 2010
Lease Serial No. NMSF078384
 AT 11 A11 TO 11 AT

Do not use this form for proposals to drill or to re-enter abandoned well. Use form 3160-3 (APD) for such propos					ter an 6. If Indian, Allotte			ee or Tribe Name	
	andoned wer		7. If Unit or CA/Agreement, Name and/or No.						
	SUBMIT IN 1	RIPLICATE - Other inst	ructions on	page 2		7. If Unit or CA/Agre	ement, Name and/or	No.	
. Type of Well				8. Well Name and No. NEWSOM B 25					
	Gas Well Oth								
Name of Operator COLEMAN OII	Contact: RPORAT E Mail: mhanson@	HANSON	9. API Well No. 30-045-24371-00-S1						
3a. Address	3b. Phone No. (include area code) Ph: 505-327-0356 Ext: 106			10. Field and Pool or BALLARD PICT					
FARMINGTON	Fx: 505-327		,	BALLARD PICT	UKED CLIFFS				
Location of Well	(Footage, Sec., T.	, R., M., or Survey Description)			11. County or Parish, State			
Sec 9 T26N R8 36.506454 N L				SAN JUAN COUNTY, NM					
12. C	HECK THE AP	PROPRIATE BOX(ES)	TO INDICA	TE NATURE C	F NOTICE,	REPORT, OR OTH	HER DATA		
TYPE OF SUE	BMISSION			ТҮРЕ О					
□ Notice of Late	unt.	☐ Acidize	☐ Deepen		☐ Production (Start/Resume)		☐ Water Shut-	Off	
Notice of Inte		☐ Alter Casing	☐ Hyd	raulic Fracturing	☐ Reclama	ation	☐ Well Integrit	ty	
Subsequent R	leport	☐ Casing Repair	□ New	Construction	☐ Recomp	lete	☐ Other		
☐ Final Abando	nment Notice	☐ Change Plans	Plug	and Abandon	☐ Tempor	arily Abandon			
		☐ Convert to Injection	□ Plug	Back	☐ Water Disposal				
See the attach been reclaimed		for the Newsom B25. Dry	hole marker	installed. Acces					
						OIL CONS. DIV	DIST. 3		
						FEB 242	017		
14. I hereby certify the		true and correct. Electronic Submission # For COLEMAN OIL & ted to AFMSS for processi	GAS INCORP	ORATED, sent t	o the Farming	gton			
Name (Printed/Typ	ped) MICHAEL	T HANSON		Title ENGIN	EER				
S:	(Flantonia S			D	047				
Signature	(Electronic S	THIS SPACE FO	R FEDERA	Date 01/27/2		SE			
		- IIIIO OI AGETO							
Approved By AC	CCEPT	ED		ABDELGADIR ELMANDANI ePETROLEUM ENGINEER Date 02/22/2			2/2017		
nditions of approval, if any, are attached. Approval of this notice does not warrant or tify that the applicant holds legal or equitable title to those rights in the subject lease ich would entitle the applicant to conduct operations thereon.				Office Farming	jton				

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Office Farmington

(Instructions on page 2) ** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **

A-PLUS WELL SERVICE, INC.

P.O. BOX 1979

Farmington, New Mexico 87499 505-325-2627 *fax: 505-325-1211

Coleman Oil & Gas Inc.
Newsom B 25

December 20, 2016

Page 1 of 1

800' FNL and 1560' FEL, Section 9, T-26-N, R-8-W San Juan County, NM Lease Number: NMSF078384 API #30-045-24371

Plug and Abandonment Report Notified NMOCD and BLM on 12/14/16

Plug and Abandonment Summary:

- Plug #1 with 160 sxs (188.8 cf) Class B cement from 2800' to surface at 96 sxs caught pressure slowed pump down shut in well at 160 sxs with 78 sxs inside and 82 sxs outside. Tag TOC at 595'.
- Plug #2 with 26 sxs (30.68 cf) Class B cement from 595' to surface to cover the casing shoe and surface.
- Plug #3 with 14 sxs Class B cement top off with poly pipe and install P&A marker with coordinates N 36° 30' 24" / W 107° 41' 3".

Plugging Work Details:

- 12/16/16 Rode rig and equipment to location. Spot in and RU. Check well pressures: tubing and casing 300 PSI, bradenhead 0 PSI. Blow well down. ND wellhead. NU A-Plus B-1 adapter. NU BOP. X-over to 1-1/4" tubing equipment. Pressure test bradenhead to 300 PSI, OK. LD 87 jnts 1-1/4" EUE on gooseneck trailer, total tally 2756'. ND BOP and B-1 adapter. **Spot plug #1** with TOC at surface. SI well. SDFD.
- 12/19/16 Open up well; no pressures. Attempt to tag TOC with tally tape, no tag 100'. NU BOP. TIH and tag TOC low at 595'. Dig out wellhead. **Spot plug #2** with TOC at surface. TOH and LD all tubing. ND BOP. Write Hot Work Permit. Cut off wellhead. Found cement down 30' in 2-7/8" and down 37' in 2-7/8" x 7". **Spot plug #3** top off with poly pipe and install P&A marker with coordinates N 36° 30' 24" / W 107° 41' 3". RD and ready equipment for move. SDFD.
- 12/20/16 Travel to location. Move equipment to A+ yard.

Bobby Espinoza, Coleman O&G representative, was on location. Dustin Porch, BLM representative, was on location.