Form 3160-5 (June 2015) UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.			FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018 5. Lease Serial No. NMNM16760 6. If Indian, Allottee or Tribe Name		
SUBMIT IN	TRIPLICATE - Other inst	ructions on page 2	7. If Unit or CA/	Agreement, Name and/or No.	
 Type of Well Oil Well Gas Well Other 			8. Well Name and MF 4	8. Well Name and No. MF 4	
2. Name of Operator DUGAN PRODUCTION COR	ALIPH REENA @duganproduction.com	9. API Well No. 30-045-251	30-045-25165-00-S1		
		3b. Phone No. (include area code) Ph: 505-325-1821	10. Field and Poo BISTI		
4. Location of Well (Footage, Sec., 7		11. County or Par	rish, State		
Sec 14 T24N R10W SENE 15 36.316956 N Lat, 107.858978		SAN JUAN	COUNTY, NM		
12. CHECK THE A	PPROPRIATE BOX(ES)	TO INDICATE NATURE OI	NOTICE, REPORT, OR	OTHER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION				
□ Notice of Intent	C Acidize	Deepen	Production (Start/Resume	e) 🔲 Water Shut-Off	
N Subsequent Report	□ Alter Casing	Hydraulic Fracturing		□ Well Integrity	
Final Abandonment Notice	 Casing Repair Change Plans 	New Construction Plug and Abandon	 Recomplete Temporarily Abandon 	□ Other	
	Convert to Injection	Plug Back	□ Water Disposal		
13. Describe Proposed or Completed Op If the proposal is to deepen direction Attach the Bond under which the wo following completion of the involved testing has been completed. Final A determined that the site is ready for f	ally or recomplete horizontally, rk will be performed or provide d operations. If the operation resonant of the performance bandonment Notices must be file	give subsurface locations and measur the Bond No. on file with BLM/BIA sults in a multiple completion or reco	ed and true vertical depths of all p Required subsequent reports mu mpletion in a new interval, a Form ng reclamation, have been comple	ertinent markers and zones. st be filed within 30 days a 3160-4 must be filed once sted and the operator has	
Well was P&A'd as per the fol	lowing procedure:			DIST. 3	
1) Set 4-1/2" CR @ 5082'. Pr to surface.	essure test casing to 600	psi. Casing won't test. Run C	BL from 5082'	IS. DIV DIST.	
2) Spot Plug I above CR @ 5 4791'. Plug I, Gallup: 4791'-5	082' w/24 sks (28.32 cu ft) 082'.	Class B cement w/2% CaCl2	WOC. Tag TOC @ F	IS. DIV DIST. 3 EB 2 4 2017	
3) Set CR @ 4301'. Spot insi w/2% CaCl2. WOC. Tag TO	de plug above retainer fro C @ 4030'. Plug II, Manco	m 4301' w/24 sks (28.3 cu ft) os: 4030'-4301'.	Class B cement		
4) Set CR @ 2430'. Spot insi	de plug above retainer w/4	46 sks (54.3 cu ft) Class C cer	nent w/2%		
14. I hereby certify that the foregoing is Commit Name (<i>Printed/Typed</i>) ALIPH RE	#Electronic Submission For DUGAN PRODUC ted to AFMSS for processin	359345 verified by the BLM Well CTION CORPORATION, sent to Ig by ABDELGADIR ELMADANI Title AGENT.	the Farmington		
Rune(17micuriy)cu) ALIFTI KL		AGENT,	ENGINEERING SUPERVI	301	
Signature (Electronic		Date 11/30/20			
	THIS SPACE FO	R FEDERAL OR STATE	OFFICE USE		
Approved By ACCEPTED		ABDELGA	ABDELGADIR ELMANDANI TitlePETROLEUM ENGINEER Date 02/22/2017		
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		subject lease	Office Farmington		
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent	U.S.C. Section 1212, make it a statements or representations as	crime for any person knowingly and to any matter within its jurisdiction.	willfully to make to any department	nt or agency of the United	
(Instructions on page 2) ** BLM REV	ISED ** BLM REVISED) ** BLM REVISED ** BLM	REVISED ** BLM REVI	SED **	

*

.

NMOCDPY

Additional data for EC transaction #359345 that would not fit on the form

+

\$

32. Additional remarks, continued

CaCl2. WOC. Tag TOC @ 1875'. Plug III, Mesaverde-Chacra: 1875'-2430'.

2

5) Perforate @ 1640'. Set CR @ 1590'. Set inside/outside plug w/166 sks (196 cu ft) Class B cement w/2% CaCl2. Pumped 119 sks (140 cu ft) below retainer and 47 sks (55.6 cu ft) above retainer. WOC. Tag TOC @ 1005'. Plug IV, PC-Fruitland: 1005'-1640'.


6) Perforate @ 978'. Set CR @ 928'. Spot inside/outside plug w/122 sks (144 cu ft) Class B w/2% CaCl2. WOC. Tag TOC @ 730'. Plug V, Ojo Alamo-Kirtland: 730'-978'.

7) Perforate @ 251'. Establish circulation to surface. Circulate cement to surface from 251' w/145 sks (171 cu ft) Class B cement. Plug VI, Surface-251'.

8) Cut wellhead off. Tag TOC @ surface. Install dry hole marker. Fill cellar.

9) Well P&A'd 11/04/2016.

<u>Completed P & A Schematic</u> MF # 004 30-045-25165 1520' FNL & 790' FEL H-14-T24N-R10W



7

8 5/8" J-55 24# casing @ 201'. Hole size: 12-1/4"

Cemented with 135 sks Class B w/ 2% gel. Circulated cement to surface

Perforate @ 251'. Circulate cement to surface w/ 145 sks Class B (171 cu.ft) (Plug VI: Surface -251').

Inside/Outside plug @ 730'-978' w/ 122 sks Class B (144 cu.ft) [Plug V: Ojo Alamo-Kirtland]

Inside plug @ 1174'-1640' w/ 166 sks Class B (196 Cu.ft) [Plug IV: PC- Fruitland]

Inside plug @ 1875'-2430' w/ 46 sks Class B (54.3 Cu.ft) [Plug III: MV-Chacra]

Cemented in two stages w /250 sks Class B w/ 4% gel followed by 150 sks Class B. (565 cu.ft). Cemented 2^{nd} stage w/ 475 sks 65-35-12 followed by 100 sks Class B plus 4% gel. (1397 cu.ft)

Inside plug @ 4030'-4301' w/ 24 sks Class B (28.32 Cu.ft) [Plug II: Mancos]

CR @ 5082'. Inside plug @ 4791'-5082' w/ 24 sks Class B (28.32 Cu.ft) [Plug I: Gallup]

Gallup Perforated @ 5132'-5280'

Dakota Perforated and Plugged @ 6190'-6298'. CIBP @ 6145'. 50' of cement dumped on top of the plug. PBTD @ 6095'.

4 ½" 10.5 # casing @ 6412'. PBTD @ 6145' 7-7/8" hole