RECEIVED

Form 3160-5 (February 2005)

(Instructions on page 2)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

MAR 1 6 2017

FORM APPROVED

Farmington Field Office Bureau of Land Manage Lease Serial No.

OMB No. 1004-0137 Expires: March 31, 2007

SUNDRY NOTICES AND REPORTS ON WELLS					NMNM 023741		
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.					6. If Indian, Allottee or Tribe Name		
SUBMIT IN TRIPLICATE – Other instructions on page 2.					7. If Unit of CA/Agreement, Name and/or No. NMNM 135216A		
1. Type of Well							
Oil Well Gas Well Other					8. Well Name and No. W Lybrook Unit 745H		
2. Name of Operator					9. API Well N		
WPX Energy Production, LLC 3a. Address 3b. Phone No. (include area code)					30-045-35750		
3a. Address PO Box 640 Aztec, NM 87410 505-333-1816			ude ar	rea code)	10. Field and Pool or Exploratory Area Lybrook Mancos W		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) SHL: 1333' FSL & 2250' FEL, Sec 7, T23N, R8W BHL: 479' FSL & 330' FEL, Sec 17, T23N, R8W					11. Country or Parish, State San Juan, NM		
12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA							
TYPE OF SUBMISSION	N TYPE OF ACTION						
Notice of Intent Alte Casi	Alter Casing Casing Repair		tion idon	Production (Statement of Statement of Statem	Well Integrity Other Spud Surface		
Final Abandonment Notice Convert to Injection		Plug Back	ng Back Water Disposal			Casing	
13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.) NOTE: MO-TE SET SURFACE OIL CONS. DIV DIST. 3							
03/15/17- SPUD @ 07:15hrs. TD 12-1/4" Surface @ 330'.				MAR 2 0 20	MAR 2 0 2017		
RU & run 15 jts 9 5/8" 36# J-55 ST&C csg, set @ 325', float collar @ 299' Pump 10 bbls FW spacer, dump 28.9 bbls (101 sxs) Type I-II cmt w/ 20% flyash @ 14.6 PPG into casing, drop plug & disp w/ 23.1 bbls H2O, bump plug @ 400 psi, circ 10 bbls good cmt to surface							
NOTE: WPX will MI to Install & test BOP at a later date. We will file another sundry at that time.							
14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed) Lacey Granillo				Title Permit Tech III			
Signature Date 03/16/2017 THIS SPACE FOR FEDERAL OR STATE OFFICE USE							
Approved by							
J	V			Title		Date	
Conditions of approval, if any, are attached. Approval of this notice does not warran or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.				Office			
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.							