RECEIVED

Form 3160-5 UNITED STATES FORM APPROVED (February 2005) OMB No. 1004-0137 DEPARTMENT OF THE INTERIOR Expires: March 31, 2007 BUREAU OF LAND MANA GEMENTON Field Office Bureau of Land Management 5. Lease Serial No. NMSF 078777 SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an 6. If Indian, Allottee or Tribe Name abandoned well. Use Form 3160-3 (APD) for such proposals. 7. If Unit of CA/Agreement, Name and/or No. SUBMIT IN TRIPLICATE - Other instructions on page 2. **NMNM 78407E** 1. Type of Well 8. Well Name and No. Rosa Unit 601 Oil Well Gas Well Other 2. Name of Operator 9. API Well No. WPX Energy Production, LLC 30-039-30916 3a. Address 3b. Phone No. (include area code) 10. Field and Pool or Exploratory Area PO Box 640 505-333-1816 Aztec, NM 87410 Basin Mancos / Basin Dakota 4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) 11. County or Parish, State 1475' FNL & 1220' FEL Sec 31, T 31N, R4W Rio Arriba, NM 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Production Acidize Deepen Water Shut-Off (Start/Resume) Notice of Intent Well Integrity Alter Casing Fracture Treat Reclamation Casing Repair New Construction Recomplete Other MIT & TA Request Subsequent Report Temporarily Change Plans Plug and Abandon Abandon Plug Back Water Disposal Final Abandonment Notice Convert to Injection 13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection cons. DIV DIST. 3 WPX requests a one year TA status per the MIT pressure test and wellbore diagram attached. APR 1 4 2017 4/10/17- MIRU. NUBOP, TOOH w/ 2-3/8" tbg, SDFN ACCEPTED FOR RECORD 4/11/17- Set CIBP @ 6875' 4/12/17- CIBP @ 6875', test 4.5" 11.6# P-110 csg to 590# & record on chart for 30 min, had 0 leak off, bleed off pressure. MIT witnessed by J. Durham w/ NMOGCD. Good test FARMINGTON FIELD OFFICE BY: William James 14. I hereby certify that the foregoing is true and correct Name (Printed/Typed) Lacey Granillo Title Permit Tech Signature THIS SPACE FOR FEDERAL OR STATE OFFICE USE Approved by

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the

(Instructions on page 2)


applicant to conduct operations thereon.

Title

Office

Date

ROSA UNIT #601 BASIN MANCOS



HOLE SIZE	CASING	CEMENT	VOLUME	CMT TOP
14-3/4"	10-3/4"	290 s x	522 cu.ft.	Surface
9-7/8"	7-5/8"	750 sx	1866 cu.ft.	Surface
6-3/4"	4-1/2"	615 s x	861cu.ft.	4450' (CBL)

