VI.
N
1.
41
Y
-

CIVED								
Form 3160-5 (February 2005) UNITED STATES DEPARTMENT OF THE INTERIOR SERVICE AND MANAGEMENT					FORM APPROVED OMB No. 1004-0137 Expires: March 31, 2007			
SUNDRY NOTICES AND REPORTS ON WELLS The first of the control of t						5. Lease Serial No.		
SUNDRY NOTICES AND REPORTS ON WELLS					NMNM 109399 6. If Indian, Allottee or Tribe Name			
abandoned well. Use Form 3160-3 (APD) for such proposals.						6. If Indian, Anottee of Tibe Name		
SUBMIT IN TRIPLICATE – Other instructions on page 2.						7. If Unit of CA/Agreement, Name and/or No.		
1. Type of Well								
Oil Well Gas Well Other					8. Well Name and No. WARNER-CALDWELL 3B			
Name of Operator WPX Energy Production, LLC						9. API Well No. 30-045-35506		
3a. Address	3b. Phone No. (include area code)			10. Field and Pool or Exploratory Area				
PO Box 640 Aztec, NI	505-333-1816			Nageezi Gallup				
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) SHL: 384' FNL & 1960' FEL SEC 8 23N 8W					11. Country or Parish, State San Juan, NM			
12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA								
TYPE OF SUBMISSION								
Notice of Intent	Acidize Deepen Production (St				art/Resume) Water Shut-Off			
Notice of Intent	Alter Casing	Casing Fracture Treat Reclamation			Well Integrity			
	Casing Repair	New Construc	ction	Recomplete		Other		
Subsequent Report	Change Plans Plug and Abandon Temporarily A				No Flare- For FLARE EXTENSION			
Final Abandonment Notice	Convert to	Plug Back	g Back Water Disposal					
13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.) Flaring was not necessary during the time of BLM flare approval (4/23/17) and NMOCD flare approval (4/23/17). ACCEPTED FOR RECORD FARMINGTON FIELD OFFICE M. J.								
14. I hereby certify that the foregoing is true and correct.								
Name (Printed/Typed) Lacey Granillo			Title Perr	Title Permit Tech III				
Signature			Date 4/27/		MAY 0 3 2017			
HIS SPACE FOR FEDERAL OR STATE OFFICE USE								
Approved by			Title			Date		

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office