RECEIVED

APR 13 2017

Form 3160-5 UNITED STATES FORM APPROVED (February 2005) OMB No. 1004-0137 DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT OF Land Management DEPARTMENT OF THE INTERIOR Expires: March 31, 2007 5. Lease Serial No. NOG14031948 SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an 6. If Indian, Allottee or Tribe Name abandoned well. Use Form 3160-3 (APD) for such proposals. 7. If Unit of CA/Agreement, Name and/or No. SUBMIT IN TRIPLICATE - Other instructions on page 2. NMNM-135216A 1. Type of Well OIL CONS. DIV DIS 1.83Well Name and No. W Lybrook Unit 716H Oil Well Gas Well Other 9. API Well No. 2. Name of Operator 30-045-35813 WPX Energy Production, LLC 3b. Phone No. (include area code) 10. Field and Pool or Exploratory Area 3a. Address Lybrook Mancos W PO Box 640 505-333-1816 Aztec, NM 87410 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 11. Country or Parish, State SHL: 1835' FSL & 624' FEL, Sec 14, T23N, R9W San Juan, NM BHL: 2179' FSL & 330' FWL, Sec 11 T23N, R9W 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF ACTION TYPE OF SUBMISSION Water Shut-Off Acidize Deepen Production (Start/Resume) Notice of Intent Alter Casing Fracture Treat Reclamation Well Integrity Casing Repair New Construction Recomplete Subsequent Report Spud Surface Change Plans Plug and Abandon Temporarily Abandon Casing Convert to Water Disposal Plug Back Final Abandonment Notice 13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.) **NOTE: MO-TE SET SURFACE** 04/11/17- SPUD @ 07:30hrs. TD 12-1/4" Surface @ 326'. RU & run 15 its 9 5/8" 36# J-55 ST&C csg, set @ 321', float collar @ 299' Pump 10 bbls FW spacer, dump 28.9 bbls (101 sxs) Type I-II cmt w/ 20% flyash @ 14.7 PPG into casing, drop plug & disp w/ 23.1 bbls H2O, bump plug @ 400 psi, circ 10 bbls good cmt to surface NOTE: WPX will MI to Install & test BOP at a later date. We will file another sundry at that time. 14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed) Lacey Granillo Title Permit Tech III Date 04/13/2017 Signature **SPACE FOR FEDERAL OR STATE OFFICE USE** Approved by Title Date Conditions of approval, if any, are attached. Approval of this notice does not warrant

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Office

(Instructions on page 2)

or certify that the applicant holds legal or equitable title to those rights in the subject

lease which would entitle the applicant to conduct operations thereon.