	Submit 1 Copy To Appropriate District	State of N	Iow Mov	ico		Form C-103	
	ffice Energy Minerals and Network Descurate				Revised July 18, 2013		
	<u>District I</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	25 N. French Dr., Hobbs, NM 88240 strict II - (575) 748-1283 1 S. First St., Artesia, NM 88210 strict III - (505) 334-6178 OIL CONSERVATION DIVISION 1220 South St. Francis Dr.				WELL API NO. 30-045-22483	
	District II - (575) 748-1283 811 S. First St. Artesia, NM 88210						
	District III - (505) 334-6178					of Lease	
	1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460	505) 476-3460 Santa Fe, NM 87505			6. State Oil & Ga		
	1220 S. St. Francis Dr., Santa Fe, NM				LG-1917		
	87505 SUNDRY NOTICES AND REPORTS ON WELLS				7. Lease Name of	r Unit Agreement Name	
	(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A					0	
	DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)				Mesa		
	1. Type of Well: Oil Well	pe of Well: Oil Well 📋 Gas Well 🛛 Other			 Well Number 2 		
	2. Name of Operator	Name of Operator			9. OGRID Number		
	Dugan Production Corp.				006515		
	3. Address of Operator				10. Pool name or Wildcat		
	O Box 420, Farmington, NM 87499-0420				Potwin Pictured Cliffs		
4. Well Location Unit Letter <u>C</u> : <u>990</u> feet from the <u>North</u> line and <u>1600</u> feet from the <u>West</u> line							
	Section 10 10	Section 16 Township 24N Range 8W NMPM San Juan County 11. Elevation (Show whether DR, RKB, RT, GR, etc.)					
	12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data						
NOTICE OF INTENTION TO: SUBSEQUENT REPOR							
	PERFORM REMEDIAL WORK						
		MULTIPLE COMPL		CASING/CEMENT	ЈОВ 🗌		
	CLOSED-LOOP SYSTEM [OTHER:			OTHER:			
	 13. Describe proposed or cor 	13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated					
		of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of					
proposed completion or recompletion. Dugan Production intends to plug and abandon well. We are seeking permission to bullhead cement from surface to plug the well due to						he well due to the 2-7/8"	
	casing completion, if we can establish mechanical integrity for the casing. If the casing won't test, we will try to spot plugs to surface.						
-Set retrievable bridge plug at 1963'. Pressure test 2-7/8" 6.4# casing to 600 psi. Run CBL from 1963' to surface. -If casing passes mechanical integrity test, remove RBP and bullhead cement from surface by the following procedure:							
	-Pump 20 bbls water down 2-7/8" casing to establish rate. -Mix and pump 115 sks (132 cu ft) Class G w/2% CaCl2 cement (1.15 cu ft/sk) from surface down the casing. OIL CONS. DIV						
	-WOC 4 hrs. Tag top of cement at surface. -If cement top is not at surface, fill up as needed.					JUL 06 2017	
¥	-Cut wellhead. Fill surface/production casing annulus with cement from 92' up with 1" pipe				2.	JUL VO COM	
	when it CBL for review (Approved prior to comenting. If the casing won't test, we will spot plug across formation tops to surface using 1/4" tog. The well will be P&A'd per the following						
	rocedure if casing wont test:						
		-Set 2-7/8" Plug I @ 1963'. Spot inside plug @ 1963' above BP w/18 sks Class G cement w/CaCl2 (21.2 cu ft) @ 1330'-1963'. Plug I: Fruitland, PC, Kirtland, Ojo Alamo					
	-Perforate @ 142'. Circulate cement from 142' to surface w/20 sks Class G cement (23.6 cu ft) w/2% CaCl2. Plug II:						
	Surface-142'.	surface. Fill compant if needed			Notify	NMOCD 24 hrs	
	-WOC 4 hrs. Tag TOC @ surface. Fill cement if needed. -Cut wellhead.				prior to beginning		
	-Dig cellar around wellhead	d. Install dry hole marker. Fill c	ellar with c	ement	(operations	
	Spud Date:	Rig R	elease Dat	e:			
X	Extend olug #1 in ?	Second Scenario +	0 1300	s' to cover	ONO top.		
	I hereby certify that the information	by certify that the information above is true and complete to the best of my knowledge and belief.					
	SIGNATURE AND M.	THE Engineering Supervisor DATE July 4, 2017					
	SIGNATURE MUL M.	NATURE TITLE Engineering Supervisor DATE July 4, 2017					
Type or print and _Aliph Reena E-mail address: _aliph.reena@duganproduction.com_ PHONE: _505-32						505-325-1821	
	For State Use Only	211	Depu	uty Oil & Gas	Inspector		
	APPROVED BY: <u>BACK</u> Conditions of Approval (if any):	TITL				TE 7/6/17	
	Conditions of Approval (It any):	+ See above IN					


,

.

R

Current Wellbore Schematic

Mesa # 2 30-045-22483 S16 T24N R8W 990' FNL & 1600' FWL



4 .

1

7" 20# ST & C casing @ 92'. Cemented w/ 35 sks to surface.

Cemented with 50 sks 2% lodense followed by 75 sks neat. Calculated cement top approx @ 350' from surface.


1 ¼" tubing set @ 2023'

2-7/8" 6.5 # casing @ 2130. PBTD @ 2039'.

PC Perfs @ 2013'-2023', 10'

Planned P&A Wellbore Schematic

Mesa # 2 30-045-22483 S16 T24N R8W 990' FNL & 1600' FWL



7" 20# ST & C casing @ 92'. Cemented w/ 35 sks to surface.

Bullhead with 115 sks Class G neat cement (132cu.ft) down the casing from surface.


Cemented with 50 sks 2% lodense followed by 75 sks neat. **Calculated cement top** approx @ 350' from surface.

2-7/8" 6.5 # casing @ 2130. PBTD @ 2039'.

Pictured Cliffs Perfs @ 2013'-2023', 10'

Planned P&A Wellbore Schematic

Mesa # 2 30-045-22483 S16 T24N R8W 990' FNL & 1600' FWL



Perf @ 142'. Circulate cement from 142' to surface w/ 20 sks Class G (23Cu.ft), Plug II: 0-142', Surface -142'

Cemented with 50 sks 2% lodense followed by 75 sks neat. **Calculated cement top** approx @ 350' from surface.

2-7/8" 6.5 # casing @ 2130. PBTD @ 2039'.

Set Plug @ 1963'. Spot Plug I from 1963' w/ 18 sks Class G to 1335' (21.2 Cu.ft), Plug I: 1335'-1963', Fruiltland-PC, Kirtland, Ojo Alamo

Pictured Cliffs Perfs @ 2013'-2023', 10'

