Submitted in lieu of Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.

Use "APPLICATION FOR PERMIT" - for such proposals.

RECEIVED

SEP 2 1 2017

FORM APPROVED

Budget Bureau No. 1004-0135

Expires: March 31, 1993

Farmington Field Office Bureau of Land Management

Gas		5. Lease Number: NMSF-078424	
2. Name of Operator: HILCORP ENERGY COMPANY		6. If Indian, allottee or Tribe Name.	
3. Address and Phone No. of Operator: P.O. Box 4700 Farmington, NM 87499 505-599-3400 4. Location of Well, Footage, Sec. T, R, U: FOOTAGE: 1445' FSL & 2610' FWL S: 20 T: 029N R: 007W U: F	(7. Unit Agreement Name: 8. Well Name and Number: SAN JUAN 29-7 UNIT 45B 9. API Well No. 3003926155 10. Field and Pool: MV - BLANCO::MESAVERDE 11. County and State: RIO ARRIBA, NM	OIL CONS. DIV DIS
12. CHECK APPROPRIATE BOX TO INDICATE NA Notice of Intent X Subsequent Report Final Abandonment Abandonment X	Recompletion Plugging Back Casing Repair Altering Casing Other- Re-Delivery	Change of Plans Change of Plans New Construction Non-Routine Fracturing Water Shut Off Conversion to Injection	
13. Describe Proposed or Completed Operations This well was re-delivered on 9/16/2017 and property of the second		ntrained hydrocarbons. DOWNHOLE ISSUES, RETURNED TO PR	
TP: 171	Initial MCF: 205	J27 2 2 2	
TP: 171	Initial MCF: 205		
TP: 171		William	Tambekou