Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an NMNM119289

5. Lease Serial No.

abandoned well. Use form 3160-3 (APD) for such proposals.		6. If Indian, Allottee or Tribe Name		
SUBMIT IN TRIPLICATE - Other instructions on page 2		7. If Unit or CA/Agreement, Name and/or No.		
Type of Well		8. Well Name and No. WILL 2		
Name of Operator Contact: JOHN C ALEXANDER DUGAN PRODUCTION CORPORATION Mail: johncalexander@duganproduction.com		9. API Well No. 30-045-35691-00-X1		
3a. Address 709 E MURRAY DRIVE FARMINGTON, NM 87499	3b. Phone No. (include area code) Ph: 505-325-1821	10. Field and Pool or Exploratory Area BASIN FRUITLAND COAL		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		11. County or Parish, State		
Sec 15 T23N R11W NESE 1553FSL 1101FEL		SAN JUAN COUNTY, NM		
12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA				

TYPE OF SUBMISSION	TYPE OF ACTION				
□ Notice of Intent Subsequent Report Final Abandonment Notice	☐ Acidize ☐ Alter Casing ☐ Casing Repair ☐ Change Plans ☐ Convert to Injection	☐ Deepen ☐ Hydraulic Fracturing ☐ New Construction ☐ Plug and Abandon ☐ Plug Back	☐ Production (Start/Resume) ☐ Reclamation ☐ Recomplete ☐ Temporarily Abandon ☐ Water Disposal	□ Water Shut-Off□ Well Integrity☑ OtherDrilling Operations	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.

Pressure test 5-1/2" casing to 3000 psig for 30 mins, held. Run GR-CCL-CNL logs. Perforate (6/6/17) Fruitland Coal from 390'-420'; 452'-456' w/4 spf (total 34', 136 holes). Acidize w/600 bbls 15% HCl. Frac w/120,000# 20/40 sand; 72,000 gals crosslinked foam (9/15/17). Ran 2-3/8" 4.7# J-55 tbg on 9/19/17. Land @ 518', SN @ 484'.

OIL CONS. DIV DIST. 3

SEP 2 5 2017

14. I hereby certify that the	ne foregoing is true and correct. Electronic Submission #389216 verifie For DUGAN PRODUCTION CORP Committed to AFMSS for processing by ABDEL	DRÁTIO	N, sent to the Farmington	€		
Name (Printed/Typed)	JOHN C ALEXANDER	Title	VICE-PRESIDENT			
Signature	(Electronic Submission)	Date	09/20/2017			
THIS SPACE FOR FEDERAL OR STATE OFFICE USE						
Approved By ACC	CEPTED		BDELGADIR ELMANDANI ETROLEUM ENGINEER	Date 09/22/2017		
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		Office	Farmington			
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United						

States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

