Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB NO. 1004-0137
Expires: January 31, 20

SUNDRY Do not use thi abandoned well	NMNM30586 6. If Indian, Allottee or Tribe Name							
SUBMIT IN	7. If Unit or CA/Agreement, Name and/or No.							
Type of Well Oil Well	8. Well Name and No. CARRACAS 32-5 24-1							
Name of Operator SOUTHLAND ROYALTY COM	9. API Well No. 30-039-31362-00-X1							
3a. Address 400 W 7TH STREET FORT WORTH, TX 76102	3b. Phone No. (include area code) Ph: 817.334.7842			10. Field and Pool or Exploratory Area BASIN DAKOTA				
4. Location of Well (Footage, Sec., T	., R., M., or Survey Description)			11. County or Parish, S	tate		
Sec 24 T32N R5W NWSW 26 36.965641 N Lat, 107.319504				RIO ARRIBA COUNTY, NM				
12. CHECK THE AF	PPROPRIATE BOX(ES)	TO INDICA	TE NATURE OF	F NOTICE,	REPORT, OR OTH	ER DATA		
TYPE OF SUBMISSION		TYPE OF	ACTION					
Notice of Intent	☐ Acidize	□ Dee	pen	☐ Producti	on (Start/Resume)	☐ Water Shut-Off		
☐ Notice of Intent	☐ Alter Casing	☐ Hyd	raulic Fracturing Reclamation		ntion	■ Well Integrity		
Subsequent Report	☐ Casing Repair	□ New	New Construction ☐ Recom		lete	Other		
☐ Final Abandonment Notice	☐ Change Plans	☐ Plug	☐ Plug and Abandon ☐ Tem		arily Abandon	Drilling Operations		
BP	☐ Convert to Injection	Plug	g Back		isposal			
13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. 9/3/2017: 5:00 TAG UP @ 530', DRILL CMT & TOOLS F/530'-620' 7:00 DRL 12 1/4" HOLE F/620'-1955'. 17:00 RIG SERVICE & DERRICK INSPECTION 17:30 DRL 12 1/4" HOLE F/1955'-3095' 9/4/2017: 5:00 CIRC ON BTM WHILE WAITING ON RIG REPAIR, 11:00 DRILL 12 1/4" HOLE F/3095'-3540'. PMP SWEEP, CIRC & ROTATE HOLE CLEAN, TOOH 9/5/2017: 5:00 LD BHA #2, PU MU SURFACE TEST BHA #3 12:00 DRILL 12 1/4 HOLE F/3540'-4533'. PMP 50 BBLS 100 VIS SWEEP, CIRC HOLE CLEAN; 2:00 SHORT TRIP 10 STANDS "NO DRAG" TIH W/SAMES "NO TAG OR FILL"; CIRC HOLE CLEAN; NOTIFY FARMINGTON BLM OFFICE OF RECENT TD, UPCOMING CSG RUN & CEMENT JOB VIA THE 24 HRS LINE @ 4:00 ON								
9/6/2017								
	# Electronic Submission For SOUTHLAND RO mmitted to AFMSS for prod	YALTY COMP	ANY LLC, sent to CK SAVAGE on 10	the Farming 0/19/2017 (18	gton JWS0016SE)			
Name (Printed/Typed) ROBBIE A	A GRIGG	Title SUPVR REGULATORY REPORTING						
Signature (Electronic S	Submission)	Date 10/16/2017						
	THIS SPACE FO	R FEDERA	L OR STATE	OFFICE US	SE			
Approved By ACCEPT	ED	JACK SAV TitlePETROLE		EER	Date 10/19/2017			
Conditions of approval, if any, are attached certify that the applicant holds legal or equivalent would entitle the applicant to conduct to con	itable title to those rights in the	Office Farmingt	on					

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)
** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **

Additional data for EC transaction #392004 that would not fit on the form

32. Additional remarks, continued

9/6/2017: 5:00 TOOH, PULL 25-30K OVER AT 3450'.
7:00 TIH, CIRC HOLE CLEAN, TOOH
14:00 RACK BACK DC, LD BHA #3
9/7/2017 NOTIFY THE FARMINGTON BLM OFFICE OF UPCOMING BOP & CSG PRESS TEST @ 9:00 ON 9/8/2017
9/8/2017: 10:00 SHORT TRIP TO DC'S, LD CLEAN OUT BHA #1; TOOH; RACK BACK DC'S, WASH & REAM
F/3368'-3340'; TIH W SAME NO TAG OR FILL; TOOH; RACK BACK DC'S, LD CLEAN OUT BHA #1, PULL WEAR
BUSHING.
18:30 MIRU CSG CREW, RUN 102 JTS OF 8 5/8" 32# N-80, LT&C INTERMEDIATE CASING, FLOAT SHOE @ 4509',
FLOAT JOINT 44.65, FLOAT COLLAR @ 4462', HYD TOOL @ 3400' CSG ON BTM & CIRC @ 3:00 9/9/2017
9/9/2017: 3:00 RD RELEASE CSG CREW, MIRU CMT CREW; 1st STAGE: PRES TST PMP & LINES TO 5000 PSI, PMP
20 BBLS OF FW AHEAD, START & FINISH 300 SKS OR 105 BBLS OF 12.3#, 1.97 YIELD TAIL CEMENT, SD & DROP
PLUG, DISPLAE SAME W/271 BBLS OF FW, BMP PLUG W/800 PSI, WALK PRESSURE UP TO 1000 PSI, HOLD SAME
FOR 1 MIN, BLEED BACK BBL, PLUG DOWN & HOLD @ 9:30 ON 9/9/2017, DROP DV TOOL OPENING PLUG, WAIT 15
MIN, OPEN DV TOOL WITH 500 PSI. RECOVER 50 BBLS OF 12.3#, 1.95 YIELD LEAD CMT, FOLLOWED BY 34
BBLS OR 145 SKS OF 13.5#, 1.31 YEILD TAIL CEMENT, DROP PLUG & DISPLACE SAME WITH 208 BBLS OF FW
BI,[;iG W1800' PSI, WALK PRESS UP TO 3000 PSI CLOSING DV TOOL SLEEVE, HOLE SAME FOR 1 MIN. BLEED
BACK 1 BBL, PLUG DOWN & HOLDING @ 15:00 ON 9/9/2017. 70 BBLS OF GOOD CEMENT TO SURFACE. RD &
RELEASE CMT CREW

Ç