UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

5.	Lease	Serial No.
	NMS	F078201

Do not use thi abandoned we	6.	6. If Indian, Allottee or Tribe Name							
SUBMIT IN	TRIPLICATE - Other instruc	7.	7. If Unit or CA/Agreement, Name and/or No. NMNM89414						
1. Type of Well	8.	8. Well Name and No.							
☐ Oil Well ☐ Gas Well ☒ Oth		FEDERAL 29-9-12 2							
Name of Operator SOUTHLAND ROYALTY COM	Contact: ROI MPANY LE-Mail: rgrigg@mspart	BBIE A GRI tners.com	9. API Well No. 30-045-28738-00-S1						
3a. Address 400 W 7TH STREET FORT WORTH, TX 76102	h: 817.334.7	rclude area code) 7842	10	10. Field and Pool or Exploratory Area BASIN FRUITLAND COAL					
4. Location of Well (Footage, Sec., T	., R., M., or Survey Description)			11. County or Parish, State					
Sec 12 T29N R9W NENE 107 36.743286 N Lat, 107.723480				SAN JUAN COUNTY, NM					
12. CHECK THE AI	PPROPRIATE BOX(ES) TO	INDICATE	NATURE O	F NOTICE, RE	EPORT, OR OTH	ER DATA			
TYPE OF SUBMISSION			TYPE OF ACTION						
T Nation of Latent	☐ Acidize ☐ Dee		pen Product		(Start/Resume)	☐ Water Shut-	Off		
✓ Notice of Intent	☐ Alter Casing	☐ Hydrau	lic Fracturing	☐ Reclamation		☐ Well Integri	ty		
☐ Subsequent Report	☐ Casing Repair	□ New C	onstruction	☐ Recomplete	e	☐ Other			
☐ Final Abandonment Notice	☐ Change Plans ☑ Plu		g and Abandon		rarily Abandon Disposal				
BP	☐ Convert to Injection ☐ Plug		Back Water I						
following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. PLEASE SEE ATTACHED PLUG & ABANDON PROCEDURE FOR YOUR APPROVAL. OIL CONS. DIV DIST. 3 Notify NMOCD 24 hrs operations									
14. I hereby certify that the foregoing is	true and correct. Electronic Submission #3965 For SOUTHLAND ROYAL mmitted to AFMSS for process	LTY COMPAN	IY LLC, sent to	the Farmingto	n		,		
Name (Printed/Typed) ROBBIE A	GRIGG	T	Title SUPVR REGULATORY REPORTING						
Signature (Electronic S	Submission)	D	Date 11/30/2017						
	THIS SPACE FOR I	FEDERAL	OR STATE (OFFICE USE					
Approved By JACK SAVAGE Conditions of approval, if any, are attache certify that the applicant holds legal or equivalent would entitle the applicant to conduct the conductive of the same and the same attached to the sa	warrant or ject lease	TitlePETROLEUM ENGINEER Date 01/16/20 Office Farmington							
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent				willfully to make	to any department or a	gency of the Unite	d		

NMOCD PY

(Instructions on page 2)
** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **













Southland Royalty Company

Plug & Abandon Procedure

September 11, 2017

Well:

Federal 29-9-12 #2

API:

3004528738

Location:

1070 FNL & 820 FEL

Field:

Basin Fruitland Coal

Sec, T, R:

Sec. 12, T29N, R9W

Elevation:

GL: 6264'

Lat/Long:

Cnty/State: San Juan County, NM

36.7432671,-107.7238998

By:

Aztec Well Servicing

Objective:

Permanently plug & abandon the well from 2,693' to surface containing 3 separate cement plugs.

Prior to Rig:

- Notify BLM & NMOCD
- 2. Note: verify all cement volumes based on actual slurry to be pumped.
- 3. See attached COA's from BLM & NMOCD.

Procedure:

- 1. MIRU unit and cementing equipment
- 2. ND WH, NU BOP stack, RU rig floor and 2 3/8" handling tools
- 3. LD production string, Tally & TIH work string / $5\frac{1}{2}$ " CSG scraper to 2,700' TOOH
- 4. TIH w/5 $\frac{1}{2}$ " CICR and set @ 2693', test TBG, roll well & Test CSG. (WOC to be determined if test holds)
- 5. Plug #1, 2626' 2693' (PC top: 2898', Fruitland top: 2726'). FTC Perfs: 2743' - 2875'): Mix & pump 10 sxs (11.8 cf) of Class B cement (or equivalent) on top of retainer. (note: cement top at 1386', determined by CBL ran 1-23-93).
- 6. Pull above cement & reverse TBG clean
- 7. LD TBG to 2330'
- 8. Plug #2, 2180' 2330' (Ojo Alamo Top: 2280'): Spot 17 sxs (20 cf) Class B cement in a balanced plug inside casing to cover Ojo Alamo top.
- 9. PUH & reverse TBG clean. WOC if needed. TIH to confirm top of plug. Respot if necessary.
- 10. LD all TBG
- 11. RU WL and Perforate @ 300'
- 12. Attempt to circulate up annuals
- 13. Plug #3, (8-5/8" Surface casing shoe, 300' to Surface): If required by BLM, Perforate at 300' and attempt to establish circulation to surface out the bradenhead valve. Mix approximately 85 sxs (100 cf) of cement and pump down













Southland Royalty Company

Plug & Abandon Procedure

September 11, 2017

Well:

Federal 29-9-12 #2

API:

3004528738

Location:

1070 FNL & 820 FEL

Field:

Basin Fruitland Coal

Sec,T, R:

Sec. 12, T29N, R9W

Elevation:

GL: 6264'

Cnty/State: Lat/Long: San Juan County, NM


36.7432671,-107.7238998

By:

Aztec Well Servicing

the 5-1/2" casing to circulate out the BH valve. If unable to circulate, top off as necessary.

- 14. ND BOP and cut off wellhead below surface casing flange per regulation. Install P&A marker with cement to comply with regulations. RD, MOL and cut off anchors.
- 15. Mobilize equipment to next location.





CURRENT WBD

Pulled Rods and Pump

06-02-2008

Prepared by: CArnold Date: 09/05/2017

KB = 13'KB = 6,276'GL = 6,263'API# 30-045-28738

Spud Date: 09/21/1992 Date Completed: 02/01/1993

> Ojo Alamo: 2,280' Kirtland: 2,378' Fruitland: 2,726' Pictured Cliffs: 2,898'

Federal 29-9-12 #2 San Juan County, NM

TD - 3,081'; PBTD - 2,979'

12-1/4" hole to 272' KB. Surface Csg: 6 jts 8 5/8" 23# X42LS Setting Depth: 272'

Cement 200 Sx Class B Circulated 14 bbls cmt to surface

7-7/8" hole to 3,081' Production Csg: 5-1/2" 15.5# J-55 Setting Depth: 3,076'

Cement: Lead: 450 Sx Pacesetter Lite Tail: 100 Sc Class B No Cmt Returns TOC @ 1,386' (CBL 1-23-93)

Prod Tbg 06/02/2008:

1.9" 2.90# J-55 Tbg 16' Tail Jt, 4' PS, SN, 88 Jts Tbg, 2x8' Subs EOT=2,900' KB; SN @ 2,881' Tag Fill @ 2,930'

Fruitland Coal Frac 01/25/1993: 2743-2875' 729 bbls 2% KCL Wtr 1,257,800 scf N2 147,000# 20/40 Brady Sd- 5ppg max ATP 2419 psi; AIR 74 bpm; ISIP/5/10/15: 1800/1603/1546/1502

PBTD: 2,979'

Fruitland Coal Perfs:

4 SPF; 0.45" dia

2743-47', 2751-56', 2782-86' 2802-26' 2863-75'

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

6251 COLLEGE BLVD. FARMINGTON, NEW MEXICO 87402

Attachment to notice of Intention to Abandon:

Re: Penanent Abandonment Well: Federal 29-9-12 #2

CONDITIONS OF APPROVAL

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."
- 2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 564-7750.
- 3. The following modifications to your plugging program are to be made:
 - a) Set plug #1 (2693 2511) ft. to cover the Fruitland top. BLM picks top of Fruitland at 2561ft.
 - b) Bring top of plug #2 to 1701 ft. to cover the Ojo Alamo top. BLM picks top of Ojo Alamo at 1751 ft. Adjust cement volume accordingly.

CBL was run on 1/23/1993. TOC at 1386 ft.

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.