## State of New Mexico Energy, Minerals and Natural Resources Department

dhcSusana Martinez

Governor

Ken McQueen Cabinet Secretary

Matthias Sayer Deputy Cabinet Secretary Heather Riley, Division Director Oil Conservation Division



New Mexico Oil Conservation Division approval and conditions listed below are made in accordance with OCD Rule 19.15.7.11 and are in addition to the actions approved by BLM on the following 3160-4 or 3160-5 form.

Operator Signature Date: 4/6/2018

Well information:

			frmWellFil	terSu	ıb							
API WELL#	Well Name	Well #	Operator Name	Туре	Stat	County	Surf_Owner	UL	Sec	Twp	N/S	Rng W/E
30-039-30120- 00-00	SAN JUAN 28 6 UNIT		HILCORP ENERGY COMPANY	G		Rio Arriba	F	A	9	27	N	6 W

Applic	eation Type:	☐ Drilling/Casing Change ☐ Location Change
0		nplete/DHC (For hydraulic fracturing operations review EPA I injection control Guidance #84

Conditions of Approval:

- Notify OCD 24hrs prior to beginning operations.
- Density exception must be approved prior to producing the Blanco Mesaverde

NMOCD Approved by Signature

4/12/18 Date Form 3160-5 (August 2007)

### UNITED STATES DEPARTMENT OF THE INTERIOR

1	gring .	_	Manage		-	_
R	b- 6		-	1 0	Born	
6 1	Laur V	الا	Page .	1 6	-	2.0

FORM APPROVED OMB No. 1004-0137

	BUREAU OF LAND MAN	NAGEMENT /	PD II	Expires:	July 31, 2010
		× (*	11 11 0	5. Lease Serial No.	
				NIV	ISF079049
SUN	IDRY NOTICES AND REPO	ORTS ON WELLS	ington	6: If Indian, Allottee or Tribe	Name
Do not use	e this form for proposals t	to drill or to re-enter a	In Land		
abandoned	well. Use Form 3160-3 (A	PD) for such proposa	als.	Management	
	IBMIT IN TRIPLICATE - Other ins			7. If Unit of CA/Agreement, N	Jame and/or No.
1. Type of Well					
Oil Well	X Gas Well Other			8. Well Name and No.	
				San Juai	n 28-6 Unit 205E
2. Name of Operator				9. API Well No.	
	Hilcorp Energy Compa	iny		30-0	39-30120
3a. Address		3b. Phone No. (include area c	ode)	10. Field and Pool or Explorat	ory Area
PO Box 4700, Farmingto	on, NM 87499	505-599-3400		Blanco Mesa	verde/Basin Dakota
4. Location of Well (Footage, Sec., T.,F	R.,M., or Survey Description)			11. Country or Parish, State	
Surface Unit A	(NENE) 20'FNL & 370' FEI	L, Sec. 9, T27N, R06W	1	Rio Arriba	, New Mexico
12. CHECK	THE APPROPRIATE BOX(ES)	TO INDICATE NATURE	OF NOT	TICE, REPORT OR OTHE	ER DATA
TYPE OF SUBMISSION		TYPE	OF AC	TION	
X Notice of Intent	Acidize	Deepen	Pı	roduction (Start/Resume)	Water Shut-Off
	Alter Casing	Fracture Treat	R	eclamation	Well Integrity
Subsequent Report	Casing Repair	New Construction	X R	ecomplete	Other
	Change Plans	Plug and Abandon	T	emporarily Abandon	
Final Abandonment Notice	Convert to Injection	Plug Back	W	ater Disposal	
13. Describe Proposed or Completed Op	peration: Clearly state all pertinent deta	ails, including estimated startin	g date of a	any proposed work and approxi	mate duration thereof.
	onally or recomplete horizontally, give			1 1	ent markers and zones.

Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

Hilcorp Energy Company plans to recomplete the subject well in the Mesaverde formation and downhole commingle with the existing Dakota. Attached is the MV C102, recomplete procedure & wellbore schematic. The DHC application will be submitted and approved prior to commingling. A closed loop system will be utilized.

\*\*Please note: MV is pending approval of well density exemption\*\*

BLM'S APPROVAL OR ACCEPTANCE OF THIS ACTION DOES NOT RELIEVE THE LESSEE AND OPERATOR FROM OBTAINING ANY OTHER **AUTHORIZATION REQUIRED FOR OPERATIONS** ON FEDERAL AND INDIAN LANDS

NMOCD

APR 1 2 2018

SEE ATTACHED FOR CONDITIONS OF APPROVAL

DISTRICT III

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)			
Tammy Jones	Title	Operations/Regulatory Technician - Sr.	
Signature Tammy Ones	Date	4/6/2018	
THIS SPACE FOR FED	ERAL C	OR STATE OFFICE USE	

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Title Petroleum Engineer

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

Approved by

District I

1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720

<u>District II</u>

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170 District IV

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

# State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

Form C-102 August 1, 2011

Permit 250566

WEII	CCA	TON.	ACRE	AGE	DEDK	CATION	N PI	ДΤ

1. API Number	2. Pool Code	3. Pool Name
30-039-30120	72319	BLANCO-MESAVERDE (PRORATED GAS)
4. Property Code	5. Property Name	6. Well No.
318710	SAN JUAN 28 6 UNIT	205E
7. OGRID No.	8. Operator Name	9. Elevation
372171	HILCORP ENERGY COMPANY	6236

10. Surface Location

UL - Lot A	Section 9	Township 27N	Range 06W	Lot Idn	Feet From 20	N/S Line N	Feet From 370	E/W Line E	County RIO A	ARRIBA

11. Bottom Hole Location If Different From Surface

			III. DOLLOIII	HOIC ECOUNT	i ii Dinici ciiti	Tom Gariace			
UL - Lot	Section	Township	Range	Lot Idn	Feet From	N/S Line	Feet From	E/W Line	County
12. Dedicated A		<u> </u>	13. Joint or Infill	L	14. Consolidation	on Code	1	15. Order No.	

#### NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION

			100
	:		
	1		
	 1		
		, J	

#### **OPERATOR CERTIFICATION**

I hereby certify that the information contained herein is true and complete to the best of my knowledge and belief, and that this organization either owns a working interest or unleased mineral interest in the land including the proposed bottom hole location(s) or has a right to drill this well at this location pursuant to a contract with an owner of such a mineral or working interest, or to a voluntary pooling agreement or a compulsory pooling order heretofore entered by the division.

E-Signed By: Tammy Jones

Title:

Operations/Regulatory Technician - Sr.

Date:

4/3/2018

#### SURVEYOR CERTIFICATION

I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by me or under my supervision, and that the same is true and correct to the best of my belief.

Surveyed By:

Glen W. Russell

Date of Survey:

8/24/2006

Certificate Number:

15703




# HILCORP ENERGY COMPANY SAN JUAN 28-6 UNIT 205E MESA VERDE RECOMPLETION SUNDRY

#### JOB PROCEDURES

- 1. MIRU service rig and associated equipment; test BOP.
- 2. TOOH with 2 3/8" tubing set at 7,291'.
- 3. Set a 4-1/2" cast iron bridge plug at +/- 5,650' to isolate the Dakota. (Note: TOC at 2,400' by CBL)
- 4. Load the hole and pressure test the casing to frac pressure.
- 5. N/D BOP, N/U frac stack and test frac stack to frac pressure.
- 6. Perforate and frac the Mesa Verde in two or three stages (Top Perforation @ 4,350'; Bottom Perforation @ 5,350').
- 7. Isolate frac stages with a composite bridge plug.
- 8. Nipple down frac stack, nipple up BOP and test.
- 9. TIH with a mill and drill out top isolation plug and Mesa Verde frac plugs.
- 10. Clean out to Dakota isolation plug and, when water and sand rates are acceptable, flow test the Mesa Verde.
- 11. Drill out Dakota isolation plug and cleanout to PBTD of 7,390'. TOOH.
- 12. TIH and land production tubing. Get a commingled Dakota/Mesa Verde flow rate.



## HILCORP ENERGY COMPANY SAN JUAN 28-6 UNIT 205E MESA VERDE RECOMPLETION SUNDRY





## **United States Department of the Interior**

#### **BUREAU OF LAND MANAGEMENT**

Farmington District Office 6251 College Blvd. - Suite A Farmington, New Mexico 87402 www.blm.gov/nm



# CASING REPAIR, WORKOVER, AND RECOMPLETION CONDITION OF APPROVAL

- 1. If casing repair operations are needed, obtain prior approval from this office before commencing repairs.
- 2. If a CBL or other logs are run, provide this office with a copy.
- 3. After any casing repair operations, test cement squeeze to a minimum of 500# for 30 minutes with no more than 10 % pressure fall off in the 30 minutes test period. Provide test chart with your subsequent report of operations
- 4. A properly functioning BOP and related equipment must be installed prior to commencing workover, casing repair, and/or recompletion operations.
- 5. Contact this office at (505) 564-7750 prior to conducting any cementing operations

#### SPECIAL STIPULATIONS:

- 1. Pits will be fenced during work-over operation.
- 2. All disturbance will be kept on existing pad.
- 3. All pits will be pulled and closed immediately upon completion of the recompletion and work-over activities.
- 4. Pits will be lined with an impervious material at least 12 mils thick.