State of New Mexico Energy, Minerals and Natural Resources Department

Susana Martinez Governor

Ken McQueen Cabinet Secretary

Matthias Sayer Deputy Cabinet Secretary Heather Riley, Division Director Oil Conservation Division



New Mexico Oil Conservation Division approval and conditions listed below are made in accordance with OCD Rule 19.15.7.11 and are in addition to the actions approved by BLM on the following 3160-4 or 3160-5 form.

Operator Signature Date: 4-16-18

Well information:

API WELL#	Well Name	Well #	Operator Name	Туре	Stat	County			Sec	Twp	N/S	Rng W/E
30-039-82242-00- 00	SAN JUAN 28 6 UNIT		HILCORP ENERGY COMPANY	G	A	Rio Arriba	F	Ī	9	28	N	6 W

Applio	cation Type: P&A Drilling/Casing Change Location Change
0	Recomplete/DHC (For hydraulic fracturing operations review EPA Underground injection control Guidance #84; Submit Gas Capture Plan form prior to spudding or initiating recompletion operations) Other:

Conditions of Approval:

- Notify OCD 24hrs prior to beginning operations.
- Density exception must be approved prior to producing from the Blanco Mesaverde.
- Submit CBL to the Agencies for review and approval prior to perforating.

NMOCD Approved by Signature

Brandon Danoll

4/25/18 Date Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

RECEIVED

FORM APPROVED OMB No. 1004-0137 Expires: July 31, 2010

APR 17 2013 Lease Serial No.

	Q		NMS	SF080505A			
SUNDRY NOTICES AND REP	ORTS ON WE	LLS	6. If Indian, Allottee or Tribe N	lame			
Do not use this form for proposals	to drill or to re	e-enteranteid	rifice				
abandoned well. Use Form 3160-3 (A	APD) for such	proposals!	gement				
SUBMIT IN TRIPLICATE - Other in	structions on page	2.	7. If Unit of CA/Agreement, Na	ame and/or No.			
1. Type of Well		II.					
Oil Well X Gas Well Other			8. Well Name and No.				
			San Jua	n 28-6 Unit 120			
2. Name of Operator			9. API Well No.				
Hilcorp Energy Comp							
3a. Address	3b. Phone No. (inc		10. Field and Pool or Explorato				
PO Box 4700, Farmington, NM 87499	505-5	599-3400		verde/Basin Dakota			
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description)		ON DOOM	11. Country or Parish, State				
Surface Unit I (NESE) 1530'FSL & 1145' F	EL, Sec. 9, 12	8N, RU6W	Rio Arriba ,	New Mexico			
12. CHECK THE APPROPRIATE BOX(ES	b) TO INDICATE	NATURE OF NOT	TCE, REPORT OR OTHE	R DATA			
TYPE OF SUBMISSION		TYPE OF ACT	ΓΙΟΝ				
X Notice of Intent Acidize	Deepen	Pr	oduction (Start/Resume)	Water Shut-Off			
Alter Casing	Fracture Treat	=	eclamation				
Subsequent Report Casing Repair	New Construc		ecomplete				
Change Plans	Plug and Aba		emporarily Abandon	Other			
Final Abandonment Notice Convert to Injection	Plug Back		ater Disposal				
13. Describe Proposed or Completed Operation: Clearly state all pertinent de							
following completion of the involved operations. If the operation result Testing has been completed. Final Abandonment Notices must be filed determined that the site is ready for final inspection.) Hilcorp Energy Company plans to recomplete the the existing Dakota. Attached is the MV C102, resubmitted and approved prior to commingling. A **Please note: MV is pending approval of well de	e subject well ecomplete prod a closed loop s	in the Mesavere cedure & wellbo system will be u	de formation and dow ore schematic. The D	nd the operator has			
NMO	10	BLM	'S APPROVAL OR ACCE	PTANCE OF THIS			
11110		ACTION DOES NOT RELIEVE THE LE					
APR 19	3 2018	OPE	RATOR FROM OBTAINI	NG ANY OTHER			
; E 2 - 20 10)		AUT	HORIZATION REQUIRE	D FOR OPERATIONS			
FOR CONDITIONS OF APPROVAL DISTRIC	T 111	ON	FEDERAL AND INDIAN I	tt, Name and/or No. Juan 28-6 Unit 120 0-039-82242 pratory Area esaverde/Basin Dakota e , New Mexico THER DATA Water Shut-Off Well Integrity Other Toximate duration thereof. Tritinent markers and zones. be filed within 30 days 160-4 must be filed once ted and the operator has Journal of the commingle with the DHC application will be CCEPTANCE OF THIS IEVE THE LESSEE AND INING ANY OTHER IRED FOR OPERATIONS AN LANDS			
OF APPROVAL BISTING	Approximate the second						
14. I hereby certify that the foregoing is true and correct. Name (Printed/Ty,	ped)						
Tammy Jones	Title	Operations/Re	egulatory Technician - S	r.			
10 10 10 10							
Signature / AMWA DAVED	Date		4/16/2018				
THIS SPACE FO	OR FEDERAL (OR STATE OFF	ICE USE				
Approved by							

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdict

Title letroleum Engineer

Office

entitle the applicant to conduct operations thereon.

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify

that the applicant holds legal or equitable title to those rights in the subject lease which would

District I

1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720

District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170 **District IV**

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr.

Santa Fe, NM 87505

Form C-102 August 1, 2011

Permit 251093

WELL LOCATION AND ACREAGE DEDICATION PLAT

1. API Number	2. Pool Code	3. Pool Name
30-039-82242	72319	BLANCO-MESAVERDE (PRORATED GAS)
4. Property Code	5. Property Name	6. Well No.
318710	SAN JUAN 28 6 UNIT	120
7. OGRID No.	8. Operator Name	9. Elevation
372171	HILCORP ENERGY COMPANY	6485


10. Surface Location

UL - Lot	Section	Township	Range	Lot Idn	Feet From	N/S Line	Feet From	E/W Line	County	
1	9	28N	06W		1530	S	1145	E		RIO ARRIBA

11. Bottom Hole Location If Different From Surface

UL - Lot	Section	Township	Range	Lot Idn	Feet From	N/S Line	Feet From	E/W Line	County
12. Dedicated Acres 284.20 Sec. 9 only		13. Joint or Infill		14. Consolidatio	n Code		15. Order No.		

NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION



OPERATOR CERTIFICATION

I hereby certify that the information contained herein is true and complete to the best of my knowledge and belief, and that this organization either owns a working interest or unleased mineral interest in the land including the proposed bottom hole location(s) or has a right to drill this well at this location pursuant to a contract with an owner of such a mineral or working interest, or to a voluntary pooling agreement or a compulsory pooling order heretofore entered by the division.

E-Signed By:

Tammy Jones

Title:

Operations/Regulatory Technician - Sr.

Date: 4/13/2018

SURVEYOR CERTIFICATION

I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by me or under my supervision, and that the same is true and correct to the best of my belief.

Surveyed By:

James P. Leese

Date of Survey:

4/8/1965

Certificate Number:

1463




HILCORP ENERGY COMPANY SAN JUAN 28-6 UNIT 120 MESA VERDE RECOMPLETION SUNDRY

JOB PROCEDURES

- 1. MIRU service rig and associated equipment; test BOP.
- 2. TOOH with 2 3/8" tubing set at 7,761'.
- 3. Set a 4-1/2" cast iron bridge plug at +/- 5,800' to isolate the Dakota.
- 4. RU Wireline. Run CBL. Record Top of Cement.
- 5. IF NECESSARY (Based on the results of the CBL top of cement) Perform cement squeeze work.
- 6. Load the hole and pressure test the casing to frac pressure.
- 7. N/D BOP, N/U frac stack and test frac stack to frac pressure.
- 8. Perforate and frac the Mesa Verde in two or three stages (Top Perforation @ 5,140'; Bottom Perforation @ 5,700').
- 9. Isolate frac stages with a composite bridge plug.
- 10. Nipple down frac stack, nipple up BOP and test.
- 11. TIH with a mill and drill out top isolation plug and Mesa Verde frac plugs.
- 12. Clean out to Dakota isolation plug and, when water and sand rates are acceptable, flow test the Mesa Verde.
- 13. Drill out Dakota isolation plug and cleanout to PBTD of 7,818'. TOOH.
- 14. TIH and land production tubing. Get a commingled Dakota/Mesa Verde flow rate.



HILCORP ENERGY COMPANY SAN JUAN 28-6 UNIT 120 MESA VERDE RECOMPLETION SUNDRY





United States Department of the Interior

BUREAU OF LAND MANAGEMENT

Farmington District Office 6251 College Blvd. - Suite A Farmington, New Mexico 87402 www.blm.gov/nm



CASING REPAIR, WORKOVER, AND RECOMPLETION CONDITION OF APPROVAL

- 1. If casing repair operations are needed, obtain prior approval from this office before commencing repairs.
- 2. If a CBL or other logs are run, provide this office with a copy.
- 3. After any casing repair operations, test cement squeeze to a minimum of 500# for 30 minutes with no more than 10 % pressure fall off in the 30 minutes test period. Provide test chart with your subsequent report of operations
- 4. A properly functioning BOP and related equipment must be installed prior to commencing workover, casing repair, and/or recompletion operations.
- 5. Contact this office at (505) 564-7750 prior to conducting any cementing operations

SPECIAL STIPULATIONS:

- 1. Pits will be fenced during work-over operation.
- 2. All disturbance will be kept on existing pad.
- 3. All pits will be pulled and closed immediately upon completion of the recompletion and work-over activities.
- 4. Pits will be lined with an impervious material at least 12 mils thick.