Form 3160-5 (June 2015)

1. Type of Well

Name of Operator

400 W 7TH STREET

FORT WORTH, TX 76102

Oil Well Gas Well Other

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

5.	Lease Serial No.
	NMSF079011

8910005340

API Well No.

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an
abandoned well. Use form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on page 2

SOUTHLAND ROYALTY COMPANY LE Mail: rgrigg@mspartners.com

Contact:

_				
ó.	If Indian,	Allottee	or Tribe	Name

Well Name and No. SAN JUAN 32-5 UNIT 7

30-039-07992-00-S1

Field and Pool or Exploratory Area BLANCO MV/ PC

If Unit or CA/Agreement, Name and/or No.

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)				11. County or Parish, State	
Sec 26 T32N R6W NENW 0940FNL 1850FWL 36.956055 N Lat, 107.429504 W Lon			6	RIO ARRIBA COUNTY, NM	
12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA					
TYPE OF SUBMISSION	TYPE OF ACTION				
Notice of Intent	☐ Acidize	□ Deepen	☐ Producti	on (Start/Resume)	☐ Water Shut-Off
Notice of filterit	☐ Alter Casing	☐ Hydraulic Fracturing	☐ Reclama	ation	■ Well Integrity
☐ Subsequent Report	☐ Casing Repair	■ New Construction	☐ Recomplete		☐ Other
☐ Final Abandonment Notice	☐ Change Plans	□ Plug and Abandon	☐ Tempora	arily Abandon	
ુર્	☐ Convert to Injection	☐ Plug Back	☐ Water D	isposal	
13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has					

ROBBIE A GRIGG

Ph: 817.334.7842

3b. Phone No. (include area code)

SEE ATTACHED PLUG AND ABANDON PROPOSAL AND WBD FOR YOUR APPROVAL.

Notify NMOCD 24 hrs prior to beginning operations

determined that the site is ready for final inspection.

DISTRICT III

					-
14. I hereby certify that the foregoing is true and correct. Electronic Submission #407857 verified by the BLM Well Information System For SOUTHLAND ROYALTY COMPANY LLC, sent to the Farmington Committed to AFMSS for processing by JACK SAVAGE on 04/27/2018 (18JWS0118SE)					
Name (Printed/Typed)	ROBBIE A GRIGG	Title	SUPVR REGULATORY REPORTIN	G	
Signature	(Electronic Submission)	Date	03/14/2018		
THIS SPACE FOR FEDERAL OR STATE OFFICE USE					
Approved By_JACK SAVAGE			PETROLEUM ENGINEER		Date 04/27/2018
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.			e Farmington		
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United					

States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **

















Southland Royalty Company

Plug & Abandon Procedure September 11, 2017

Well:

San Juan 32-5 Unit #7

API:

3003907992

Location:

940. FNL & 1850 FWL

Field:

Mesaverde

Sec.T. R:

Sec. 12, T32N, R6W

Elevation:

GL: 6358'

Cnty/State:

Rio Arriba County, NM

Aztec Well Servicing

Lat/Long:

36.9560165,-107.432444

Objective:

Permanently plug & abandon the well from 5,269' to surface containing 4 separate cement plugs.

Prior to Rig:

- Notify BLM & NMOCD
- 2. Note: verify all cement volumes based on actual slurry to be pumped.
- 3. See attached COA's from BLM & NMOCD.

Procedure:

- 1. MIRU unit and cementing equipment
- 2. ND WH, NU BOP stack, RU rig floor and 2 3/8" handling tools
- 3. LD production string, Tally & TIH work string / 5 \(\frac{1}{2}\)" CSG scraper to 5280' TOOH
- 4. TIH w/5 ½" CICR and set @ 5269', test TBG, roll well & Test CSG. (WOC to be determined if test holds.
- 5. Plug #1, 5219' 5269' (Cliff House Top: 5325'). MV Perfs: 5319' 5772'): Sting out of retainer. Mix & pump 6 sxs (7.10 cf) of Class B cement (or equivalent) on top of retainer.
- 6. If required by BLM/NMOCD, run CBL (note: cement top at 5100', determined by temp survey after primary cement job. Also, a squeeze job done in 1993 put cement from 800' to surface - circulated 3 bbls).
- 7. LD TBG to 3155'
- 8. Plug #2, 2850' 3155' (Fruitland Top: 2900', Pictured Cliffs Top: 3105'): Spot 35 sxs (41.3 cf) Class B cement in a balanced plug inside casing to cover Fruitland and Pictured Cliffs formations.
- 9. Pull above cement & reverse TBG clean
- LD TBG to 2350'
- Plug #3, 2200' 2350' (Ojo Alamo Top: 2300'): Spot 20 sxs (23.6 cf) Class B cement in a balanced plug inside casing to cover Ojo Alamo formation.
- Pull above cement & reverse TBG clean 12















Southland Royalty Company

Plug & Abandon Procedure September 11, 2017

Well: Location: Sec, T, R: San Juan 32-5 Unit #7 940, FNL & 1850 FWL

Sec. 12, T32N, R6W

Cnty/State: Lat/Long:

36.9560165,-107.432444

Rio Arriba County, NM

By:

API:

Field:

Elevation:

Mesaverde GL: 6358'

3003907992

Aztec Well Servicing

13. LD all TBG

Plug #4, (Surface plug): Spot 6 sx (7.1 cf) for a surface plug. Top off as necessary. Note: circulated out the bradenhead valve on squeeze done in 1993'.

15. ND BOP and cut off wellhead below surface casing flange per regulation. Install P&A marker with cement to comply with regulations. RD, MOL and cut off anchors. Restore location per BLM/NMOCD stipulations.



San Juan 32-5 Unit #7 Rio Arriba County, NM

CURRENT WBD

Prepared by: CArnold Date: 09/05/2017

KB = 13' KB = 6,371' GL = 6,358' API# 30-039-07992

Spud Date: 04/13/1959 Date Completed: 05/18/1959

Ojo Alamo: 2,300' Kirtland: 2,490' Fruitland: 2,900' Pictured Cliffs: 3,105' Lewis: 3,280'

Pictured Cliffs: 3,105' Lewis: 3,280' Cliff House: 5,325'

Csg Leak Sqz - 10/27/1993: 250 Sx Class B in csg leak @ 665'

Perf 2 Sqz Holes @ 430' 175 Sx Class B Circulate 3 bbl cmt to surface

Cmt f/ Surface-800' and 5100'-TD

SA |

Cement 175 Sx Regular Circulate cmt to surface

Setting Depth: 185'

TD - 5,801'; PBTD - 5,783'

12-1/4" cable tool hole to 186' KB

Surface Csg: 6 jts 9 5/8" 36# J-55

8-3/4" rotary hole to 5,801' Production Csg: 5-1/2" 17# J-55 Setting Depth: 5,800'

Cement: 200 Sx Regular TOC @ 5,100' (B&R Temp Survey)

Mesaverde Frac 05/04/1959:

Upper Section 5319-5512': 27,914 gal wtr 20,000# 20/40 Sd BD 2,050 psi, AIR 66.5 bpm

Lower Section 5604-5772': 39,986 gal wtr 40,000# 20/40 Sd BD 2,000 psi, AIR 53 bpm

IP: 1.3 MMcf

2-3/8" 4.7# J-55 Tbg EOT=5,771' KB; SN @ 5,740'

Prod Tbg 11/06/1993:

Mesaverde Perfs 05/04/1959: 5319-23', 5328-35', 5456-60', 5465-74', 5498-5512', 5604-36', 5680-5702', 5750-72' 4 SPF

PBTD: 5,783'















Southland Royalty Company

Plug & Abandon Procedure September 11, 2017

Well: Location: San Juan 32-5 Unit #7 940, FNL & 1850 FWL

Sec, T, R:

Sec. 12, T32N, R6W

Cnty/State: Lat/Long:

Rio Arriba County, NM

36.9560165,-107.432444

API:

3003907992

Field:

Mesaverde

Elevation:

GL: 6358'

By:

Aztec Well Servicing

Today's Date: 9/11/17 Spud:

Completed:

Elevation: 6358' GL 13° KB

Ojo Alamo @ 2300"

Kirtland @ 2490*


Fruitland @ 2900'

Pictured Cliffs @ 3105"

Lewis 3280"

Hole Size 8.75

Cliff House @ 5325'



PBTD: 5783" TD: 5801"

Hole Size: 12.25"

9-5/8", 36#, Casing set @ 185" Cement circ to surface

Plug #4 (50" - surface) 6 sx (7.10 cf) of Class 8 cement

Cmt f' 800' - surface (squeeze job 1993)

Plug #3 (2200" - 2350") 20 sx (23.6 cf) of Class B cement

Plug #2 (2850" - 3155') 35 sx (41.3 of) of Class B cement

TOC 5100"

CICR - 5289" Plug #1 (5219" - 5269") 6 sx (7.10 cf) of Class B cement MV Perfs: 5319" - 5772"

5-1/2", 17#, J55 at 5800" Cmt w/ 200 sx

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

6251 COLLEGE BLVD. FARMINGTON, NEW MEXICO 87402

Attachment to notice of Intention to Abandon:

Re: Permanent Abandonment Well: San Juan 32-5 Unit #7

CONDITIONS OF APPROVAL

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."
- 2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 564-7750.
- 3. The following modifications to your plugging program are to be made:
 - a) Add a cement plug (4246-4146) ft. inside/outside to cover the Chacra top. BLM picks top of Chacra at 4196 ft.
 - b) Set plug #2 (3143-2756) ft. inside/outside to cover the Pictured Cliffs and Fruitland tops. BLM picks top of Pictured Cliffs at 3093 ft. BLM picks top of Fruitland at 2806 ft.
 - c) Set plug #3 (2555-2258) ft. inside/outside to cover the Kirtland top and the entire Ojo Alamo interval. BLM picks top of Kirtland at 2505 ft. BLM picks top of Ojo Alamo at 2308 ft.
 - d) Add a cement plug (1020-920) ft. inside/outside to cover the Nacimiento top. BLM picks top of Nacimiento at 970 ft.
 - e) Set plug #4 (235-0) ft. to cover the 9-5/8" surface casing shoe. Surface casing shoe set at 185 ft.

Operator must run CBL to surface to identify TOC. Submit the electronic copy of the log for verification to the following addresses: jwsavage@blm.gov Brandon.Powell@state.nm.us

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.