

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB NO. 1004-0137
Expires: January 31, 2018

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on page 2

1. Type of Well <input type="checkbox"/> Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other		5. Lease Serial No. NMSF078903B
2. Name of Operator BP AMERICA PRODUCTION CO Contact: TOYA COLVIN E-Mail: Toya.Colvin@bp.com		6. If Indian, Allottee or Tribe Name EASTERN NAVAJO
3a. Address 200 ENERGY COURT FARMINGTON, NM 87401	3b. Phone No. (include area code) Ph: 281.366.7148	7. If Unit or CA/Agreement, Name and/or No. 892000844E
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Sec 33 T28N R12W NESE 1460FSL 835FEL		8. Well Name and No. GALLEGOS CANYON UNIT 186
		9. API Well No. 30-045-06989-00-S2
		10. Field and Pool or Exploratory Area WEST KUTZ PICTURED CLIFFS
		11. County or Parish, State SAN JUAN COUNTY, NM

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Hydraulic Fracturing	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input checked="" type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompletable horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.

BP requests to P&A the subject well.

Please see the attached procedure, wellbore diagram, and required reclamation plan documents.

In accordance with NMOCD Pit Rule 19.15, 17.9 NMAC, BP will use a closed-loop system during operations.

CONDITIONS OF APPROVAL
Adhere to previously issued stipulations.

Notify NMOCD 24 hrs
prior to beginning
operations

SEE ATTACHED FOR
CONDITIONS OF APPROVAL

NMOCD
MAY 10 2018
DISTRICT III

14. I hereby certify that the foregoing is true and correct. Electronic Submission #411079 verified by the BLM Well Information System For BP AMERICA PRODUCTION CO, sent to the Farmington Committed to AFMSS for processing by ABDELGADIR ELMADANI on 05/07/2018 (18AE0019SE)	
Name (Printed/Typed) TOYA COLVIN	Title REGULATORY ANALYST
Signature (Electronic Submission)	Date 04/10/2018

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved By ABDELGADIR ELMADANI	Title PETROLEUM ENGINEER	Date 05/07/2018
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		Office Farmington

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

**** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED ****

NMOCD

4

PLUG AND ABANDONMENT PROCEDURE

February 14, 2018

GCU #186

West Kutz Pictured Cliffs

1460' FSL, 2120' FEL, Section 28, T28N, R12W, San Juan County, New Mexico

API 30-045-06989

Note: All cement volumes use 100% excess outside pipe and 50' excess inside. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures. All cement will be Class G, mixed at 15.8 ppg with a 1.15 cf/sx yield.

1. This project will use an A-Plus steel tank to handle waste fluids circulated from the well and cement wash up.
2. Install and test location rig anchors. Comply with all NMOCD, BLM, and Operator safety regulations. MOL and RU daylight pulling unit. Conduct safety meeting for all personnel on location. Record casing, tubing and bradenhead pressures. NU relief line and blow down well. Kill well with water as necessary and at least pump tubing capacity of water down the tubing. ND wellhead and NU BOP. Function test BOP.
3. Rods: Yes ☐, No ☐, Unknown ☒.
Tubing: Yes ☒, No ☐, Unknown ☐, Size 2-3/8", Length 1520'.
Packer: Yes ☐, No ☒, Unknown ☐, Type .

NOTE: will need additional 1600' of tubing workstring.

4. **NOTE: BLM requires a CBL log to be run on all wells where the cement did not circulate to surface or a CBL log was not previously run. This procedure is prepared with the understanding that it may be modified based on the TOC from the CBL.**
5. **Plug #1 (Mesaverde and Chacra tops, 3021' – 2250'):** Mix and pump 75 sxs Class G cement (extra cement due to open PC perforations) and spot an underbalanced plug inside casing to cover the Mesaverde and Chacra tops. PUH and WOC. TIH and tag cement; top off if necessary.
6. **Plug #2 (Pictured Cliffs perforations, top and Fruitland tops, 1388' – 982'):** R/T 4.5" gauge ring or mill to 1388'. RIH and set 4.5" CR at 1388'. Pressure test tubing to 1000#. Attempt to pressure test casing to 800#. If casing does not test then spot or tag subsequent plugs as necessary. Mix and pump 35 sxs Class G cement and spot a balanced plug inside casing to cover through the Pictured Cliffs and Fruitland top. TOH.
7. **Plug #3 (Kirtland and Surface shoe, 405' – 0'):** Attempt to pressure test the bradenhead annulus to 300 PSI; note the volume to load. If the BH annulus holds pressure, then establish circulation out casing valve with water. Mix approximately 35 sxs cement and spot a balanced plug from 405' to surface, circulate good cement out casing valve. TOH and LD tubing. Shut well in and WOC. If the BH annulus does not test, then perforate at the appropriate depth and attempt to circulate cement to surface filling the casing and annulus from the squeeze holes to surface. Shut in well and WOC.

GCU #186
Proposed P&A
Basin Dakota

Today's Date: 2/14/18


1460' FSL, 835' FEL, Section 33, T-28-N, R-12-W, San Juan County, NM

API #30-045-06989

Spud: 9/23/64
Completion: 0/13/64
Re-Complete: 3/04/02
Elevation: 5773' GI
5786' KB

Kirtland @ 282'

12.25" hole



Per sundry cement circulated

8.625", 24#, Casing set @ 355'
Cement with 200 sxs, circulate to surface

Plug #3: 405' - 0'
Class G cement, 35 sxs

Fruitland @ 1032'

Plug #2: 1388' - 982'
Class G cement, 35 sxs

Pictured Cliffs @ 1435'

Set CR @ 1388'

Pictured Cliffs Perforations:
1438' - 1484'

Chacra @ 2300'

Mesaverde @ 2971'

Plug #1: 3021' - 2250'
Class G cement, 75 sxs

Gallup @ 5040'

DV Tool @ 4279'
Stage 2: Cemented with 1000 sxs

Dakota @ 5862'

Set CIBP @ 5995' ('02)

Dakota Perforations:
6056' - 6084'

7-7/8" Hole

4.5" 10.5#, casing set @ 6170'
Stage 1: Cemented with 500 sxs

TD 6170'
PBTD 2871'

UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
FARMINGTON DISTRICT OFFICE
6251 COLLEGE BLVD.
FARMINGTON, NEW MEXICO 87402

Attachment to notice of
Intention to Abandon:

Re: Permanent Abandonment
Well: Gallegos Canyon Unit 186

CONDITIONS OF APPROVAL

1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."

2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 564-7750.

Low concentrations of H₂S (12 ppm - <100 ppm GSV) have been reported in wells within a 1 mile radius of this location.

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.