Submit 1 Copy To Appropriate District Office State of New N	
District I (575) 393-6161 Energy, Minerals and Na	tural Resources Revised July 18, 2013 WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283	20.045.07010
811 S. First St., Artesia, NM 88210 OIL CONSERVATIO	5. Indicate Type of Lease
1000 Pio Provos Pd. Aztec. NM 87410	STATE L PEE L
District IV – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM	6. State Oil & Gas Lease No.
87505	
SUNDRY NOTICES AND REPORTS ON WELL (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR I	j
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101)	
PROPOSALS.) 1. Type of Well: Oil Well ☐ Gas Well ☒ Other	8. Well Number
	173
2. Name of Operator	9. OGRID Number
BP America Production Company- L48 3. Address of Operator	000778 10. Pool name or Wildcat
1515 Arapahoe St, Tower 1 Suite 700	10. I containe of window
Denver, CO 80202	Basin Dakota, Basin Fruitland Coal
4. Well Location	
Unit Letter_A:_1025 _feet from the _North lin	e and905feet from theEastline
	nge 12W NMPM San Juan County
11. Elevation (Show whether D	
5.	330'
12. Check Appropriate Box to Indicate	Nature of Notice Penart or Other Data
12. Check Appropriate Box to indicate	Nature of Notice, Report of Other Data
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON	REMEDIAL WORK ALTERING CASING
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS. □ P AND A □
PULL OR ALTER CASING MULTIPLE COMPL	CASING/CEMENT JOB
DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM	
OTHER:	OTHER:
13. Describe proposed or completed operations. (Clearly state al	ll pertinent details, and give pertinent dates, including estimated dat
	AC. For Multiple Completions: Attach wellbore diagram of
proposed completion or recompletion.	NMOCD
Please see the attached P&A operations performed on the subje	ct well May 2018
	of well May 2018. JUN 0 7 2018
	DISTRICT III
PNNONLL	## ## ## ## ## ## ## ## ## ## ## ## ##
Spud Date: 09/12/1964 Rig Release I	Data
Spud Date. Rig Release I	Date:
I hereby certify that the information above is true and complete to the	best of my knowledge and belief.
10000	
SIGNATURE TITLE R	egulatory AnalystDATE06/04/2018
Type or print nameToya Colvin E-mail address:	Toya.Colvin@bp.com PHONE: 281-892-5369
	uty Oil & Gas Inspector,
	D: 1: 1: 1/0
APPROVED BY: DIM I'M TITLE	District #3 / /- a / a
	District #3 DATE 6/28/18
Conditions of Approval (if any):	District #3 DATE 6/28/18

BP AMERICA PRODUCTION COMPANY

Name: GCU 173

API:30-045-07910, 05/25/2018

Well Plugging Report

Work Detail

	•
PUX 05/09/2018	Activity
P	Rode rig & equip to loc
P	JSEA. Spot rig & set on jacks, notify Nathan Deal & Adam Smouse w/BP about moving pump jack. Weatherford will remove PJ in AM. CK PSI; tbg 0, csg 10 psi, BH 150 PSI, secure loc. SDFD
05/10/2018	· · · · · · · · · · · · · · · · · · ·
X	Weatherford removed Pump Jack w/crane
P	Finish RU rig & Pump Truck, CK PSI; tbg 0, csg 10, BH 150 PSI. RU blow down lines & blow down well, BH blew down immediately, X-O to rods tools
Р	Unseat pump. LD rods & tbg.
P	ND WH. NU BOP & F/T. RU floor, PU on tbg. LD hanger, pump 25 bbls in attempt to est. circ out csg, Tbg & csg on vacuum, LD jts 2.375 EUE tbg.
Р	PU on tbg, LD hanger & 39 jts. profile nipple & 1-17 M/A
Р	Swap out floats
Р	Tally & PU 1-new 3 7/8 cone bit. XO 6- 3 1/8 DC's & 36 jts 2 3/8 EUE A Plus workstring. Tag at 1310' w/20' stick up on #36. LD 7 jts. SIW
P	RU flow back line. Secure loc. SDFD
05/11/2018	
P	CK PSI; tbg 10, 4.5 csg 30 psi, BH 0 psi, blow down well, PU 5 jts, LD tongs, PU & RU swivel, PU 1 jt w/swivel & tag at 1310'
P	JSEA w/HI-TECH AIR/FOAM UNIT operator, test lines; 500 psi low; 1400 psi hi. Est cicr. to flow back tank & ck for leaks. Start cleaning out to 1350 & D/O 4.5" CIBP. C/O to 1400' & start D/O 2nd CIBP at 1400'. Very little returns with very little torqueing up on swivel, made 8-10"
Р	Circ. csg clean, HB swivel, PUH. SIW. Secure well. SDFD
05/14/2018	
P	CK PSI; tbg 0, 4.5 csg 30 psi, BH 5 psi' blow down well; finish POOH. Run in & tag fill at 1392'. Est circ w/air, clean out to 1400' w/air, start D/O CIBP at 1400'. D/O CIBP in 1 hr. chase to 1446'. Tagging real hard, returns of fine metal & some sand.
P	POOH & Change out bit to new 3 7/8 cone bit. RIH, tag fill at 1444'. Clean out to 1446'. Est circ w/air, start drilling at 1446'.
P	POOH & TIH w/saw collar & tag at 1446' & attempt to turn w/ tongs, torqued up, POOH
05/15/2018	
P	CK PSI; tbg 0, 4.5 csg 30 psi, BH 5 psi' blow down well; can hear BH gruggling
P	PU 1 3 7/8 WEATHERFORD junk mill. TIH & tag at 1450', est circ circ. w/Hi Tech air package. Start drilling out, swivel torqueing up w/some returns of old cement, fell thru at 1475'. Air package pressured up to 1100 psi ,tbg jump up 1'. Continue circ. PU 3 jts w/swivel, Hang back swivel

	Finited on 5/50/20
Р	Tally & PU 152 jts A Plus 2 3/8 workstring. Chase plugs to 4976'
Р	POOH w/76 stands, LD 6-3 1/8 HI Tech DC's, SIW, RD CNJ blow down line. SDFD
05/16/2018	
P	CK PSI; no tbg , 4.5 csg 30 psi, BH 12 psi' blow down well; can hear BH gruggling
P	
r	RU A Plus W/L; RIH & tag fill at 4560'. Run CBL from 4560' – 1100', send to
	appropriate agencies
X	Wait on OK from NMOCD
Р	TIH w/158 jts, EOT 4950,
P	Pump 20 bbls ahead & est circ. out 4.5 csg. Pumped Plug #1 (Gallup top) Mix &
	pump 16sxs w/2% calc (18.4 CF 3.2 bbls slurry 1.15 yield 15-8#) Type G cement
	from 4950' - 4745'.
D	
P -	LD 8 jts. POOH & SIW
Р	WOC
Р	TIH & tag TOC at 4715' (ok'd by NMOCD Rep) LD up to 4037'
Р	OCD (Brandon Powell) approved Plug #2 depth. Load csg w/3 bbls, Pumped Plug
	#2 (Mancos top) Mix & pump 18sxs (20.7 CF 3.68 bbls slurry 1.15 yield 15-8#)
	Type G cement from 4037' - 3806'.
Р	LD & PUH. SIW SDFD.
	LD & FUR. SIW SDFD.
05/17/2018	
Р	CK PSI; tbg 0, 4.5 csg 16 psi, BH 6 psi' blow down well; TIH & tag at 3883' OK'd
	by NMOCD rep. on loc.
P	LD tbg up to 2994', Est circ out csg w/4.5 bbls, Pumped Plug #3 (MV & Chacra
	top) Mix & pump 41sxs w/2% calc (47.15 CF 8.39 bbls slurry 1.15 yield 15-8#)
	Type G cement from 2994' - 2468'.
Р	LD 17 jts PUH above perfs. SIW
Р	WOC.
•	
P	TIH & tag TOC at 2452'. LD tbg & plugging sub.
Р	TIH w/ 4.5" CR set @ 1140'. PT tbg to 1000 psi. Sting out, circ. csg clean w/24
	bbls, PT 4.5" csg to 800 psi. Test – OK. POOH
Р	JSEA, Run CBL from 1140' to surface, send to appropriate agencies, (Monica
	Kuehling approved Plug #4)
P	TIH w/ tbg. Load csg w/1 bbl. Pumped Plug #4 (PC & Fruitland tops) Mix &
	pump 28sxs (32.2 CF 5.7 bbls slurry 1.15 yield 15-8#) Type G cement from 1140'
	-780'.
Р	LD all tbg. SIW. SDFD
	ED dii tug. Sivv. Suru
05/18/2018	
Р	CK PSI; no tbg , 4.5 csg 0 psi, BH 0 psi BH on light vac. NMOCD requested perf @
	350', unable to establish rate and spot inside plug from 474' – 60'. Perf @ 50'.
Р	JSEA. Perf at 350' w/3 3-1/8 HSC, attempt to est rate, pressured up to 800 psi,
	unable to est rate.
Р	TIH TO 474'. Pumped Plug #5 (Ojo Alamo/Kirtland top) Mix & pump 33sxs
•	(37.95 CF 6.75 bbls slurry 1.15 yield 15-8#) Type G cement from 474' - 50'. LD
	tbg up to 60' & circ clean. LD tbg
V	-
X	JSEA. Perf at 50' w/3 3 1/8 HSC & est circ out BH.
Р	RD tongs, floor & BOP, NU WH
X	Pumped Plug #6 (Surface) Mix & pump 21sxs (24.15 CF 4.30 bbls slurry 1.15
	yield 15-8#) Type G cement from 50' - Surface. Circ. good cement out BH & SIW
	w/300 psi
Р	RD PT & rig
P	-
г	Dig out WH. Had to dig down close to 4' due to spool & wooden cellar, (will cut
_	off on Monday 5-21-18 in AM, will notify Thomas Vermersch w/NMOCD)
Р	Rode rig & equip. back to A Plus yard
05/21/2018	

Printed on 5/30/2018

P HSM on the JSA. Secure location. Write and perform hot work permit. Check PSI

on the well, CSG - 0 PSI, BH - 5 PSI, and 58% LEL.

P Perform 1 hour shut in per Thomas Vermersch with NMOCD. BH built up to 3

PSI. Remove the B-1 and found cement through the TBG hanger. Reinstall the B-

1 adapter.

P PU tools. SDFD.

05/24/2018

P HSM on the JSA, write & perform hot work permit. Cut off the WH, CMT at

surface in both. Weld on the DHM.

On Site Reps:

NameAssociationNotesJONATHON KELLYNMOCDCK ON PROGRESSTHOMAS VERMERSCHNMOCDON LOC.

^{*} P - Procedure Planned; U - Unplanned A+ issue; X - COA, Well Conditions

GCU #173 Plugged WBD

Basin Fruitland Coal / Basin Dakota
UL – A, 1025' FNL & 905' FEL, Sec. 29, T29N, R12W
San Juan County, NM / API # 30-045-07910

