Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					5. Lease Serial No.		
					NMNM6890		
					6. If Indian, Allottee or Tribe Name		
SUBMIT IN TRIPLICATE - Other instructions on page 2					7. If Unit or CA/Agreement, Name and/or No. NMNM108184		
Type of Well ☐ Gas Well ☑ Other: COAL BED METHANE					8. Well Name and No. REESE MESA 7H		
2. Name of Operator Contact: PRISCILLA SHORTY HILCORP ENERGY COMPANY E-Mail: pshorty@hilcorp.com					9. API Well No. 30-045-35135-00-S1		
3a. Address 3b. Phone No 1111 TRAVIS STREET Ph: 505.32 HOUSTON, TX 77002			o. (include area code) 24.5188				
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					11. County or Parish, State		
Sec 10 T32N R8W NESE 121 36.996590 N Lat, 107.656810		SAN JUAN COUNTY, NM		OUNTY, NM			
12. CHECK THE AI	PPROPRIATE BOX(ES)	TO INDICA	TE NATURE OI	F NOTICE,	REPORT, OR OT	HER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION						
☐ Notice of Intent	☐ Acidize	☐ Dee	pen	□ Product	ion (Start/Resume)	■ Water Shut-Off	
	☐ Alter Casing	☐ Hyd	draulic Fracturing		ation	■ Well Integrity	
Subsequent Report	□ Casing Repair	□ Nev	v Construction	☐ Recomplete			
☐ Final Abandonment Notice	☐ Change Plans	☐ Plug and Abandon ☐		□ Tempor	☐ Temporarily Abandon Workover Operation		
30	☐ Convert to Injection	Plug	☐ Plug Back ☐ Water		isposal		
If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. 05/04/18 - MIRU BWD 105. ND WH. NU NOPE. RU Tuboscope. POOH scanning tbg string. SDFWE. 05/05/18 - CK pressures. TIH w/ CO assembly and tbg string to liner top in lateral. RU air unit. Surge well and opened csg to flowback tank to clear lateral prod string. Re-established circ and repeated process three times. Dried wellbore. Cut air unit. TOOH w/ tbg string. LD CO assembly.							
05/08/2018 - CK pressures. M F-Nipple @ 4190'. Perforated head. Prep new rod string for new rod string (72 guided & 9- at F-nipple. Load tbg string. P	jt @ 4193. Pump 20 bbls PU. PU new pump. Stroke 4 sucker rods). Space out	kill and TIH to test at surfa w/ pony rod	o liner top. ND Bo ace. Test good. R s. PU polish rods	OPE. NU ne IIH w/ pump and seat pu	and imp	TRICT III	
14. I hereby certify that the foregoing is	Flectronic Submission #4	122593 verifie	d by the BLM Well	Information	System	· · · · · · · · · · · · · · · · · · ·	
Comm	For HILCORP EN itted to AFMSS for process		ANY, sent to the AM TAMBEKOU or		(18WMT0891SE)		
Name (Printed/Typed) PRISCILLA SHORTY			Title OPERATIONS REGULATORY TECH				
Signature (Electronic S	Date 06/05/20	018 .					
	THIS SPACE FO	R FEDERA	AL OR STATE	OFFICE U	SE		
_Approved By ACCEPTED			WILLIAM T TitlePETROLE	WILLIAM TAMBEKOU TitlePETROLEUM ENGINEER Date 06/0		Date 06/07/2018	
Conditions of approval, if any, are attache certify that the applicant holds legal or equivalent would entitle the applicant to conduct the applicant the applic	Office Farmings	ton	·	1			
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United							

States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Additional data for EC transaction #422593 that would not fit on the form

32. Additional remarks, continued

05/08/2018.