State of New Mexico Energy, Minerals and Natural Resources Department

Susana Martinez

Governor

Ken McQueen Cabinet Secretary

Matthias Sayer Deputy Cabinet Secretary **Heather Riley**, Division Director **Oil Conservation Division**



New Mexico Oil Conservation Division approval and conditions listed below are made in accordance with OCD Rule 19.15.7.11 and are in addition to the actions approved by BLM on the following 3160-4 or 3160-5 form.

Operator Signature Date: 7/11/18

Well information:

API WELL#	Well Name	Well #	Operator Name	Туре	Stat	County	Surf_Owner	UL	Sec	Twp	N/S	Rng W/E
30-039-23910- 00-00	SAN JUAN 27 5 UNIT	1.00-	HILCORP ENERGY COMPANY	G		Rio Arriba	F	М	15	27	Z	5 W

Application Type:	
	ing Change Location Change
	ydraulic fracturing operations review EPA ance #84; Submit Gas Capture Plan form prior to operations)
Other:	
Conditions of Approval:	
• Compliance review pending. The B the approved interval.	lanco MesaVerde was perforated deeper than
Brand Dell	
NIMOCD A 11 C'	7/30/18
NMOCD Approved by Signature	Date

Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR

JUL 1 1 2018

FORM APPROVED OMB No. 1004-0137

Expires: July 31, 2010

BUREAU OF LAND MANAGEMENT 5. Lease Serial No. Farmington Field C NMSF-079403 SUNDRY NOTICES AND REPORTS ON WELLS 6. If Indian, Allottee or Tribe Name Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals. SUBMIT IN TRIPLICATE - Other instructions on page 2. 7. If Unit of CA/Agreement, Name and/or No. 1. Type of Well San Juan 27-5 Unit X Gas Well 8. Well Name and No. Oil Well Other San Juan 27-5 Unit 108E 9. API Well No. 2. Name of Operator Hilcorp Energy Company 30-039-23910 3a. Address 3b. Phone No. (include area code) 10. Field and Pool or Exploratory Area 505-599-3400 Blanco Mesaverde / Basin Dakota 382 Road 3100, Aztec, NM 87410 11. Country or Parish, State 4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) Unit M (SWSW) 530'FSL & 90' FWL, Sec. 15, T27N, R05W Rio Arriba **New Mexico** 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF ACTION TYPE OF SUBMISSION Water Shut-Off Notice of Intent Acidize Production (Start/Resume) Deepen Well Integrity Alter Casing Fracture Treat Reclamation X Subsequent Report Casing Repair New Construction Recomplete Other Change Plans Plug and Abandon Temporarily Abandon Final Abandonment Notice Convert to Injection Plug Back Water Disposal 13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.) ACCEPTED FOR RECORD See Attached. FARMINGTON NMOCD JUL 1 8 2018 DISTRICT III 14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed) Etta Trujillo Operations/Regulatory Technician - Sr. 7/11/2018 THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by Title Date Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction



entitle the applicant to conduct operations thereon

5/24/2018 – MIRU. ND B-2. NU BOP stack. Pull tbg hanger. Tag 15' of fill @ 7799' (PBTD @ 7814'). SIW. SDFN.

5/25/2018 – TTL. TOOH w/2-3/8" tbg. TIH & set 4.5" CIBP @ 6075'. Roll well clean w/100bbls. Test csg, test failed. TOOH w/stinger. Circ INT csg clean w/79 bbls. SIW. SDFW.

5/29/2018 – TTL. RU WL. Run CBL f/6075' to surface. RD WL. Notified AG (BLM) and Brandon Powell (OCD) – Request permission to sqz holes in 4-1/2" csg. Verbal approval received. TIH w/4.5" pkr. Isolate hole in csg f/3687' to 3780'. TOOH w/pkr. TIH w/CIBP & set @ 3800'. TOOH setting tool. TIH w/4.5" CICR & set @ 3675'. Load csg, test tbg to 1000#. Sting in, circ 80bbls up INT csg. Spot in cmt equipment. SIW. SDFN.

5/30/2018 – TTL. Finished spot in cmt equipment. Mix & pump w/440sx Class G Neat cmt @ 15.8PPG. Displaced w/14.5 bbls fresh water. Lost circ w/10bbls displacement left to pump. Finish pump. Sting out. Reverse clean w/20bbls. TOOH w/stinger. SIW. SDFN.

5/31/2018 – TTL. TIH w/3-3/4" bit. Tag 28' of cmt on CICR @ 3675'.D/O cmt & CICR. Tag CIBP @ 3800', circ clean. SIW. RU well check & chart test csg to 560# w/NMOCD witness (Thomas Vermersch). Good test. D/O CIBP @ 3800'. TIH & tag CIBP @ 6075' to confirm csg clear. TOOH & LD 2-3/8" pro tbg. SIW. SDFN.

6/1/2018 - TTL. RU WL. RIH to 4000' w/CBL tool. Run CBL f/6075' to surface (TOC @ 676'). Tag tight spot @ 3900'. Recover metal pieces from CIBP D/O @ 3800'. Make GR run to 6000' to confirm csg clear.

6/4/2018 – TTL. ND BOP Stack. ND 3K Tbg Head. NU 5K tbg head. Test secondary seals to 2500#. NU BOP Stack. RU. RIH w/GR to 5000'. RIH w/perf gun, Perf'd Cliffhouse @ 5910, 5899, 5891, 5888, 5820, 5819, 5803, 5802, 5782, 5781, 5771, 5755, 5732, 5710, 5697, 5688, 5681, 5674, 5668, 5637, 5636, 5612, 5611, 5581, 5580, 5551, 5550, 5535, 5521, 5498, 5490, 5481, 5466, 5459, 5452, 5438, 5422, 5410, 5377, 5352, 5333, 5315, 5310, 5309, 5302, 5290, 5274, 5273, 5257, 5238, 5220, 5219, 5201, 5193, 5183, 5172, 5171, 5154, 5153, 5145, 5131, 5105, 5104, 5103, 5073, 5068, 5061, 5053, 0.34 DIA, 2 RUNS, 1 SPF. RD WL. NU BOP CAP. SIW. SDFN.

6/5/2018 – TTL. MU 4.5" pkr. TIH w/pkr, 2-7/8" frac string, set @ 4700'. ND BOP stack, NU frack stack. PT to 9000#, test good. RU WL. RIH & rupture ceramic disk. RD WL. RD & release unit. SIW. SD.

6/26/2018 – Prime test. Foam frac'd (MesaVerde) w/246,190# 20/40 sand & 69,218gal slickwater & 2.70 million SCF N2. 70Q. Dropped 20 bio-balls with 1/3 and 2/3 of sand pumped. RD & release.

6/30/2018 - RU unit. ND frac stack. NU BOP stack. Chart test rams. SIW. SDFN.

7/1/2018 – Pull hanger & release pkr @ 4700'. TOOH w/frac string. Kill well w/40bbls. TIH w/3-3/4" bit to 5000'. SIW. SDFN.

7/2/2018 – Cont TIH w/bit. Tagged 368' of fill @ 5707 on CIBP. CO to CIBP @ 6075'. DO CIBP. RIH 3jts to confirm plugged dropped. SIW. SDFN.

7/3/2018 – Cont TIH w/bit. Tag 55' of fill on PBTD @ 7814'. CO to PBTD. TOOW w/bit. TIH w/prod BHA. SIW. SDFN.

7/4/2018 – PU RBP w/pro string. Set pkr and load csg. ND BOP stack. Change out tbg head/test secondary to 3000#. Good test. NU BOP stack. TIH / equalize pkr. TOOH pkr. TIH pro BHA. **TIH & land 247jts 2-3/8" 4.7# J-55** @ 7776.3', **SN** @ 7774.27'. ND BOP stack. NU B-2. Pump 5bbls pad/drop ball. Test tbg to 500#. Good test. RD & release unit. SIW.

Well is now producing as MesaVerde/Dakota commingle under DHC 3998AZ

