RECEIVED

• 👽

Form 3160-5 (June 2015)	UNITED STATI DEPARTMENT OF THE I	mington Field C)ffice	FORM APPROVED DMB No. 1004-0137 pires: January 31, 2018		
SUND Do not use t	BUREAU OF LAND MAN RY NOTICES AND REPO this form for proposals rell. Use Form 3160-3 (A	ORTS ON W	ELLS re-enter an	<u>gemen</u> ,5. Lease Serial No. <u>N0G14011865</u> 6. If Indian, Allottee o	or Tribe Name	
SUBMIT IN TRIPLICATE - Other instructions on page			2	7. If Unit of CA/Ag	greement, Name and/or No.	
1. Type of Well Gas Well Other				8. Well Name and M W Lybrook Unit 74		
2. Name of Operator WPX Energy Production, LLC				9. API Well No. 30-045-35750		
3a. AddressPO Box 640Aztec, NM 87	3b. Phone No. <i>(include area code)</i> 505-333-1816			10. Field and Pool or Exploratory Area Lybrook Mancos W		
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) SHL: 1333' FSL & 2250' FEL, Sec 7, T23N, R8W BHL: 335' FSL & 418' FEL, Sec 17, T23N, R8W				11. Country or Parish, State San Juan, NM		
12	. CHECK THE APPROPRIATE B	OX(ES) TO IND	ICATE NATURE O	OF NOTICE, REPORT OR OTH	IER DATA	
TYPE OF SUBMISSION				OF ACTION		
Notice of Intent		Deepen Hydraulic Fracturing		Production (Start/Resume)	Water ShutOff	
	Alter Casing			Reclamation	Well Integrity	
Subsequent Report	Casing Repair				Other Completion	
	Change Plans	Plug and Abandon		Temporarily Abandon	comprenden	
Final Abandonment Notice				Water Disposal		
BP	Convert to Injection	Plug Back		Water Disposal		
Describe Proposed or Completed Operation: ve subsurface locations and measured and true filed within 30 days following completion of	Clearly state all pertinent details, including est	imated starting date of ones. Attach the Bond lts in a multiple comp	any proposed work and ap under which the work will letion or recompletion in a	proximate duration thereof, If, the propos be perfonned or provide thereof, a con- new interval, a Form 3160-4 must be inte	al is to deepen directionally or recomplete horizont Se voluments frequind subsequent reports fronce testing has been objected. Final Abandon 2 0-20 18	
BP Describe Proposed or Completed Operation: we subsurface locations and measured and true filed within 30 days following completion of trices must be filed only after all requirement is ready for final inspection.) 2/15/17- PSI Test 4-1/2 Casing erf MC 1 st stage, 14924'-14924 IIRU for DFIT ressure up, open toe sleeve, p ig up, Run in hole with RBP, w	Clearly state all pertinent details, including est vertical depths of all pertinent markers and zo the involved operations. If the operation resu s, including reclamation, have been completed g @ 6,500#s for 30 Min GOOD 8' RSI TOOL with 8, 0.35" holes	imated starting date of ines. Attach the Bond Its in a multiple comp I and the operator has TEST 5. @ 4110 psi av	any proposed work and ap under which the work will letion or recompletion in a detennined that the site g. Shut down pun	proximate duration thereof. If the propos be perfonned or provide for for for new interval, a Form 3160-4 must be the FEB	Se voir a subsequent reports a concerned subsequent reports a	
BP Describe Proposed or Completed Operation: we subsurface locations and measured and true filed within 30 days following completion of trices must be filed only after all requirement is ready for final inspection.) 2/15/17- PSI Test 4-1/2 Casing erf MC 1 st stage, 14924'-14924 IIRU for DFIT ressure up, open toe sleeve, p ig up, Run in hole with RBP, w D	Clearly state all pertinent details, including est evertical depths of all pertinent markers and zo the involved operations. If the operation resu s, including reclamation, have been completed g @ 6,500#s for 30 Min GOOD 8' RSI TOOL with 8, 0.35" holes pumping DFIT @ 5 bbl min rate	imated starting date of ness Attach the Bond Its in a multiple comp I and the operator has TEST 6. @ 4110 psi av p bottom of the	any proposed work and ap under which the work will letion or recompletion in a detennined that the site g. Shut down pun	proximate duration thereof. If, the proposible perfonmed or provide the for a SM new interval, a Form 3100-4 must be fits FEB nps for 10 min shut down ti sure gauges to Start DFIT	Sevents and the sevent sevent sevents in a sevent s	
BP Describe Proposed or Completed Operation: we subsurface locations and measured and true filled within 30 days following completion of otices must be filed only after all requirement is ready for final inspection.) 2/15/17- PSI Test 4-1/2 Casing erf MC 1 st stage, 14924'-14926 AIRU for DFIT ressure up, open toe sleeve, p ig up, Run in hole with RBP, w D 2/16/17-1/7/18- Monitor DFI 14. I hereby certify that the forego	Clearly state all pertinent details, including est eventical depths of all pertinent markers and zo the involved operations. If the operation resu s, including reclamation, have been completed g @ 6,500#s for 30 Min GOOD 8' RSI TOOL with 8, 0.35" holes pumping DFIT @ 5 bbl min rate / 5' perforated sub attached to	imated starting date of ness Attach the Bond Its in a multiple comp i and the operator has TEST @ 4110 psi av o bottom of the 5.	any proposed work and ap under which the work will letion or recompletion in a detennined that the site g. Shut down pun	proximate duration thereof. If, the proposible perfonmed or provide the for a SM new interval, a Form 3100-4 must be fits FEB nps for 10 min shut down ti sure gauges to Start DFIT	Scrubby Artis Required subsequent reports of above testing that Schworz bleted. Final Abandonr 2 0 - 20 18 me. Pressure bled off to 395 psi.	
BP Describe Proposed or Completed Operation: ve subsurface locations and measured and true filled within 30 days following completion of otices must be filed only after all requirement is ready for final inspection.) 2/15/17- PSI Test 4-1/2 Casing erf MC 1 st stage, 14924'-14926 AIRU for DFIT ressure up, open toe sleeve, p ig up, Run in hole with RBP, w D 2/16/17-1/7/18 - Monitor DFI	Clearly state all pertinent details, including est evertical depths of all pertinent markers and zo the involved operations. If the operation resu s, including reclamation, have been completed g @ 6,500#s for 30 Min GOOD 8' RSI TOOL with 8, 0.35" holes pumping DFIT @ 5 bbl min rate / 5' perforated sub attached to T. TOOH, w/ down hole gauges	imated starting date of ness Attach the Bond Its in a multiple comp i and the operator has TEST @ 4110 psi av o bottom of the 5.	any proposed work and ap under which the work will letion or recompletion in a detennined that the site g. Shut down pun	proximate duration thereof. If the propose be perfonned or provide the or COM new interval, a Form 3160-4 must be the FEB nps for 10 min shut down ti sure gauges to Start DFIT EDEENTIAL ACCEPTE	Scrolly ACHS required subsequent reports of arbitratisting with School pleted. Final Abandonr 2 0-20 18 me. Pressure bled off to 395 psi. D FOR RECORD 3 16 2018	
BP Describe Proposed or Completed Operation: we subsurface locations and measured and true filled within 30 days following completion of otices must be filed only after all requirement is ready for final inspection.) 2/15/17- PSI Test 4-1/2 Casing erf MC 1 st stage, 14924'-14926 AIRU for DFIT ressure up, open toe sleeve, p ig up, Run in hole with RBP, w D 2/16/17-1/7/18- Monitor DFI 14. I hereby certify that the forego	Clearly state all pertinent details, including est evertical depths of all pertinent markers and zo the involved operations. If the operation resu s, including reclamation, have been completed g @ 6,500#s for 30 Min GOOD 8' RSI TOOL with 8, 0.35" holes pumping DFIT @ 5 bbl min rate / 5' perforated sub attached to T. TOOH, w/ down hole gauges	imated starting date of ness Attach the Bond Its in a multiple comp i and the operator has TEST @ 4110 psi av o bottom of the 5.	any proposed work and ap under which the work will letion or recompletion in a detennined that the site g. Shut down pun e plug, & set pres:	proximate duration thereof. If the propose be perfonned or provide the or COM new interval, a Form 3160-4 must be the FEB nps for 10 min shut down ti sure gauges to Start DFIT EDEENTIAL ACCEPTE	Scrubly ACHS required subsequent reports of arbitration of the subsequent reports of 2 0 - 20 18 me. Pressure bled off to 395 psi. D FOR RECORD 3 16 2018	
BP Describe Proposed or Completed Operation: we subsurface locations and measured and true filled within 30 days following completion of obtices must be filed only after all requirement is ready for final inspection.) 2/15/17- PSI Test 4-1/2 Casing erf MC 1 st stage, 14924'-14926 MIRU for DFIT ressure up, open toe sleeve, p ig up, Run in hole with RBP, w D 2/16/17-1/7/18 - Monitor DFI 14. I hereby certify that the foregon Lacey Granillo	Clearly state all pertinent details, including est evertical depths of all pertinent markers and zo of the involved operations. If the operation resu is, including reclamation, have been completed g @ 6,500#s for 30 Min GOOD 8' RSI TOOL with 8, 0.35" holes pumping DFIT @ 5 bbl min rate / 5' perforated sub attached to T. TOOH, w/ down hole gauges	imated starting date of ness Attach the Bond Its in a multiple comp I and the operator has TEST (@ 4110 psi av to bottom of the S. nted/Typed)	any proposed work and ap under which the work will letion or recompletion in a detennined that the site g. Shut down pun e plug, & set press CONN Title Permit Tech Date 2/15/18	proximate duration thereof. If, the propose be perfonned or provide the or FO new interval, a Form 3100-4 must be inter- FEB nps for 10 min shut down ti sure gauges to Start DFIT FIDENTIAL ACCEPTE III	Scrubly ACHS required subsequent reports of arbitration of the subsequent reports of 2 0 - 20 18 me. Pressure bled off to 395 psi. D FOR RECORD 3 16 2018	
BP Describe Proposed or Completed Operation: we subsurface locations and measured and true filled within 30 days following completion of obtices must be filed only after all requirement is ready for final inspection.) 2/15/17- PSI Test 4-1/2 Casing erf MC 1 st stage, 14924'-14926 MIRU for DFIT ressure up, open toe sleeve, p ig up, Run in hole with RBP, w D 2/16/17-1/7/18 - Monitor DFI 14. I hereby certify that the foregon Lacey Granillo	Clearly state all pertinent details, including est evertical depths of all pertinent markers and zo of the involved operations. If the operation resu is, including reclamation, have been completed g @ 6,500#s for 30 Min GOOD 8' RSI TOOL with 8, 0.35" holes pumping DFIT @ 5 bbl min rate / 5' perforated sub attached to T. TOOH, w/ down hole gauges	imated starting date of ness Attach the Bond Its in a multiple comp I and the operator has TEST (@ 4110 psi av to bottom of the S. nted/Typed)	any proposed work and ap under which the work will letion or recompletion in a detennined that the site g. Shut down pun e plug, & set press CONN Title Permit Tech Date 2/15/18	proximate duration thereof. If the propose be performed or provide the or COM new interval, a Form 3100-4 must be the FEB nps for 10 min shut down ti sure gauges to Start DFIT FIDENTIAL ACCEPTE III FARMINGT By: TE OFICE USE	me. Pressure bled off to 395 psi.	

NMOCD

W Lybrook Unit 745H

1/8/18-

PSI Test All Lines Up To 9,500 Lbs, Test Good

Frac MC 1st stage 14924'-14928' - 20, 0.35" holes, 1st stage with 50000 # 20/40 PSA Sand Perf 2nd stage 14720'-14874'-with 20, 0.35" holes. Frac MC 2nd stage with 203000#, 20/40 PSA Sand 1/9/18-Perf 3rd stage 14516'-14670'- with 20, 0.35" holes. Frac MC 3rd stage with 207000#, 20/40 PSA Sand Perf 4th stage 14312'-14466'- with 20, 0.35" holes. Frac MC 4th stage with 204000#, 20/40 PSA Sand Perf 5th stage 14108'-14262'-with 20, 0.35" holes. Frac MC 5th stage with 207,900#, 20/40 PSA Sand Perf 6th stage 13904'-14058'- with 20, 0.35" holes. Frac MC 6th stage with 204,900#, 20/40 PSA Sand Perf 7th stage 13700'-13854'- with 20, 0.35" holes. Frac MC 7th stage with 207,500#, 20/40 PSA Sand 1/10/18-Perf 8th stage 13496'-13650'- with 20, 0.35" holes. Frac MC 8th stage with 205,100#, 20/40 PSA Sand Perf 9th stage 13292'-13446'- with 20, 0.35" holes. Frac MC 9th stage with 204,000#, 20/40 PSA Sand Perf 10th stage 13088'-13242'- with 20, 0.35" holes. Frac MC 10th stage with 204,100#, 20/40 PSA Sand Perf 11th stage 12884'-13038'- with 20, 0.35" holes. Frac MC 11th stage with 204,000#, 20/40 PSA Sand Perf 12th stage 12680'-12834'- with 20, 0.35" holes. Frac MC 12th stage with 205,200#, 20/40 PSA Sand Perf 13th stage 12476'-12630'- with 20, 0.35" holes. Frac MC 13th stage with 205,200#, 20/40 PSA Sand 1/11/18-Perf 14th stage 12272'-12426'- with 20, 0.35" holes. Frac MC 14th stage with 204,500#, 20/40 PSA Sand Perf 15th stage 12068'-12222'- with 20, 0.35" holes. Frac MC 15th stage with 205,000#, 20/40 PSA Sand Perf 16th stage 11864'-12018'- with 20, 0.35" holes. Frac MC 16th stage with 206,000#, 20/40 PSA Sand Perf 17th stage 11660'-11814'- with 20, 0.35" holes. Frac MC 17th stage with 206,000#, 20/40 PSA Sand Perf 18th stage 11456'-11610'- with 20, 0.35" holes. Frac MC 18th stage with 205,900#, 20/40 PSA Sand 1/12/18-Perf 19th stage 11252'-11406'- with 20, 0.35" holes. Frac MC 19th stage with 206,100#, 20/40 PSA Sand Perf 20th stage 11048'-11202'- with 20, 0.35" holes. Frac MC 20th stage with 205,500#, 20/40 PSA Sand Perf 21st stage 10844'-10998'- with 20, 0.35" holes. Frac MC 21st stage with 204,500#, 20/40 PSA Sand Perf 22nd stage 10640'-10794'- with 20, 0.35" holes. Frac MC 22nd stage with 204,200#, 20/40 PSA Sand Perf 23rd stage 10436'-10590'- with 20, 0.35" holes. Frac MC 23rd stage with 204,500#, 20/40 PSA Sand Perf 24th stage 10232'-10386'- with 20, 0.35" holes. Frac MC 24th stage with 205,000#, 20/40 PSA Sand 1/13/18-Perf 25th stage 10028'-10182'- with 20, 0.35" holes. Frac MC 25th stage with 193,000#, 20/40 PSA Sand Perf 26th stage 9824'-9978'- with 20, 0.35" holes. Frac MC 26th stage with 204,000#, 20/40 PSA Sand Perf 27th stage 9620'-9774'- with 20, 0.35" holes. Frac MC 27th stage with 206,000#, 20/40 PSA Sand Perf 28th stage 9416'-9570'- with 20, 0.35" holes. Frac MC 28th stage with 204,500#, 20/40 PSA Sand Perf 29th stage 9212'-9366'- with 20, 0.35" holes. Frac MC 29th stage with 203500#, 20/40 PSA Sand Perf 30th stage 9008'-9162'- with 20, 0.35" holes. Frac MC 30th stage with 203900#, 20/40 PSA Sand 1/14/18-Perf 31st stage 8804'-8958'- with 20, 0.35" holes. Frac MC 31st stage with 210000#, 20/40 PSA Sand Perf 32nd stage 8600'-8754'- with 20, 0.35" holes. Frac MC 32nd stage with 203300#, 20/40 PSA Sand Perf 33rd stage 8396'-8550'- with 20, 0.35" holes. Frac MC 33rd stage with 206400#, 20/40 PSA Sand Perf 34th stage 8192'-8346'- with 20, 0.35" holes. Frac MC 34th stage with 205100#, 20/40 PSA Sand Perf 35th stage 7988'-8142'- with 20, 0.35" holes. Frac MC 35th stage with 205100#, 20/40 PSA Sand 1/15/18-Perf 36th stage 7784'-7938'- with 20, 0.35" holes. Frac MC 36th stage with 205100#, 20/40 PSA Sand Perf 37th stage 7580'-7734'- with 20, 0.35" holes. Frac MC 37th stage with 203500#, 20/40 PSA Sand Perf 38th stage 7376'-7530'- with 20, 0.35" holes. Frac MC 38th stage with 203600#, 20/40 PSA Sand Perf 39th stage 7172'-7326'- with 20, 0.35" holes. Frac MC 39th stage with 205300#, 20/40 PSA Sand 1/16/18-Perf 40th stage 6968'-7122'- with 20, 0.35" holes. Frac MC 40th stage with 205000#, 20/40 PSA Sand Perf 41st stage 6764'-6918'- with 20, 0.35" holes. Frac MC 41st stage with 206200#, 20/40 PSA Sand Perf 42nd stage 6560'-6714'- with 20, 0.35" holes. Frac MC 42nd stage with 205000#, 20/40 PSA Sand Perf 43rd stage 6356'-6510'- with 20, 0.35" holes. Frac MC 43rd stage with 205000#, 20/40 PSA Sand Perf 44th stage 6152'-6306'- with 20, 0.35" holes. Frac MC 44th stage with 205200#, 20/40 PSA Sand Perf 45th stage 5948'-6102'- with 20, 0.35" holes. Frac MC 45th stage with 205300#, 20/40 PSA Sand 1/17/18-Perf 46th stage 5744'-5898'- with 20, 0.35" holes. Frac MC 46th stage with 205000#, 20/40 PSA Sand Set Kill plug @ 5700' RDMO

1/18/18-1/25/18- wait on DO

1/26/18-1/30/18- MIRU- DO Frac plugs. Pull tie back. CO to RSI

1/31/18-Land Production string /Gas lift system. Landed @ 5557'. 169 Jnts of 2 7/8" 6.5# L-80. Packer set @ 5392', 9 Gas Lift Valves 2/1/18- flow back

2/1/18- Oil Delivery

Choke Size= 40/64", Tbg Prsr=150, Csg Prsr= 650 psi, Sep Prsr= 100 psi, Sep Temp= 55 degrees F, Flow Line Temp= 66 degrees F, Flow Rate= 264 mcf/d, 24hr Fluid Avg= 15.13 bph, 24hr Wtr= 104 bbls, 24hr Wtr Avg= 4.33 ph, Total Wtr Accum= 104 bbls, 24hr Oil= 259 bbls, 24hr Oil Avg= 10.79 bph, 24hr Fluid= 363 bbls