Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

5.	Lease Serial No.	
	NIMSE078200B	

	NOTICES AND REPO				NIVISFU16200B		
Do not use thi abandoned we	is form for proposals to II. Use form 3160-3 (API	enter an roposals.		6. If Indian, Allottee or	Tribe Na	ime	
SUBMIT IN	TRIPLICATE - Other inst	ructions on	page 2		7. If Unit or CA/Agree	ment, Nai	ne and/or No.
Type of Well Oil Well	ner				8. Well Name and No. RIDDLE B 10E		6
2. Name of Operator HILCORP ENERGY COMPAN	Contact: NY E-Mail: pshorty@h	PRISCILLA S ilcorp.com	SHORTY		9. API Well No. 30-045-26401-00	D-S1	
3a. Address 1111 TRAVIS STREET HOUSTON, TX 77002	•	3b. Phone No Ph: 505.32	. (include area code 4.5188)	10. Field and Pool or E BASIN DAKOTA		y Area
4. Location of Well (Footage, Sec., T	., R., M., or Survey Description,)			11. County or Parish, S	tate	
Sec 27 T30N R10W SWSE 17 36.779129 N Lat, 107.867401					SAN JUAN COU	INTY, N	М
12. CHECK THE AR	PPROPRIATE BOX(ES)	TO INDICA	TE NATURE O	F NOTICE,	REPORT, OR OTH	ER DA	TA
TYPE OF SUBMISSION			TYPE O	F ACTION			
Notice of Intent	☐ Acidize	☐ Dee	pen	☐ Product	ion (Start/Resume)	☐ Wa	ter Shut-Off
_	☐ Alter Casing	☐ Hyd	raulic Fracturing	☐ Reclama	ation	☐ We	ll Integrity
☐ Subsequent Report	☐ Casing Repair	□ Nev	Construction	Recomp	olete	☐ Oth	er
☐ Final Abandonment Notice	☐ Change Plans	_	and Abandon		rarily Abandon		
13. Describe Proposed or Completed Ope	☐ Convert to Injection	☐ Plug		☐ Water D			
determined that the site is ready for f Hilcorp Energy Company plan commingle the existing Dakota procedure. A DHC application will be used.	s to recomplete the subje a with the Mesaverde. Att	ached is the	Mesaverde plat	and recomple	ete		
				- God	NMOCD		
					AUG 2 4 20	18	
HOLD C104 FOR DHC	=			-	DISTRICT	COMPANY	
14. I hereby certify that the foregoing is	Flectronic Submission #	NERGY COMP	ANY, sent to the	Farmington	-		
Name (Printed/Typed) PRISCILL	A SHORTY		Title OPERA	ATIONS REG	GULATORY TECH		
Signature (Electronic S	Submission)		Date 08/14/2	018			
	THIS SPACE FO	OR FEDERA	L OR STATE	OFFICE US	SE		
Approved By_WILLIAM TAMBEKO	QU		TitlePETROLE	UM ENGINE	EER	D	ate 08/21/2018
Conditions of approval, if any, are attache ertify that the applicant holds legal or equency which would entitle the applicant to condu	uitable title to those rights in the		Office Farming	gton	,		
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent					ake to any department or a	ngency of	the United

NMOCDY

(Instructions on page 2)
** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **



HILCORP ENERGY COMPANY RIDDLE B 10E MESA VERDE RECOMPLETION SUNDRY


JOB PROCEDURES

- 1. MIRU service rig and associated equipment; NU and test BOP.
- 2. TOOH with 1-1/2" tubing set at 7,061'.
- 3. Set a 4-1/2" cast Iron bridge plug at +/- 6,000' to isolate the Dakota.
- 4. Load hole with fluid and run a CBL on the 4-1/2" casing. Verify cement bond within the Mesa Verde'. Review CBL results with NMOCD.
- 5. N/D BOP, N/U frac stack. Pressure test the frac stack and production casing to frac pressure.
- 6. Perforate and frac the Mesa Verde in two or three stages. (Top perforation @ 4,140', Bottom perforation @ 5,090')
- 7. Isolate frac stages with a composite bridge plug and set top isolation plug once frac is completed.
- 8. Nipple down frac stack, nipple up BOP and test.
- 9. TIH with a mill and drill out top isolation plug and Mesa Verde frac plugs.
- 10. Clean out to Dakota isolation plug and, when water and sand rates are acceptable, flow test the Mesa Verde.
- 11. Drill out Dakota isolation plug and cleanout to PBTD of 7,134'. TOOH.
- 12. TIH and land 2-3/8" production tubing. Get a commingled Dakota/Mesa Verde flow rate.

All formation tops for the Riddle B 10E wellbore have been reviewed by Hilcorp Energy. There were no changes made to the existing formation tops on the "OCD Permitting" website for this well.



HILCORP ENERGY COMPANY RIDDLE B 10E MESA VERDE RECOMPLETION SUNDRY



District I

1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720

District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr.

Santa Fe, NM 87505

Form C-102 August 1, 2011

Permit 255039

WELL LOCATION AND ACREAGE DEDICATION PLAT

1. API Number	2. Pool Code	3. Pool Name
30-045-26401	72319	BLANCO-MESAVERDE (PRORATED GAS)
4. Property Code 318683	5. Property Name RIDDLE B	6. Well No. 010E
7. OGRID No. 372171	8. Operator Name HILCORP ENERGY COMPANY	9. Elevation 6028


10. Surface Location

	UL - Lot	П	Section	Т	Township	T	Range		Lot Idn		Feet From		N/S Line		Feet From	E/W Line	T	County
	02 201	ol	2	7	Tomorap	30N	rtango	10W	201,017	15	1 0011 10111	1180		S	1460	E/// Eind	۶l	SAN JUAN
- 1		4	_	1		0014		1000		10		1100		9	1400		-	OAN JOAN
- 1		- 1		-		1				- 1				- 1			- 1	

11. Bottom Hole Location If Different From Surface

UL - Lot	Section	Township	Range	Lot Idn	Feet From	N/S Line	Feet From	E/W Line	County
	12. Dedicated Acres 318.22			I	14. Consolidatio	n Code		15. Order No.	

NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION



OPERATOR CERTIFICATION

I hereby certify that the information contained herein is true and complete to the best of my knowledge and belief, and that this organization either owns a working interest or unleased mineral interest in the land including the proposed bottom hole location(s) or has a right to drill this well at this location pursuant to a contract with an owner of such a mineral or working interest, or to a voluntary pooling agreement or a compulsory pooling order heretofore entered by the division.

E-Signed By: Priscilla Shorty

Title: Operations Regulatory Technician - Sr.

Date: 07/19/2018

SURVEYOR CERTIFICATION

I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by me or under my supervision, and that the same is true and correct to the best of my belief.

Surveyed By:

Fred Kerr

Date of Survey:

4/25/1985

Certificate Number:

3950



United States Department of the Interior

BUREAU OF LAND MANAGEMENT

Farmington District Office 6251 College Blvd. - Suite A Farmington, New Mexico 87402 www.blm.gov/nm



CASING REPAIR, WORKOVER, AND RECOMPLETION CONDITION OF APPROVAL

- 1. If casing repair operations are needed, obtain prior approval from this office before commencing repairs.
- 2. If a CBL or other logs are run, provide this office with a copy.
- 3. After any casing repair operations, test cement squeeze to a minimum of 500# for 30 minutes with no more than 10 % pressure fall off in the 30 minutes test period. Provide test chart with your subsequent report of operations
- 4. A properly functioning BOP and related equipment must be installed prior to commencing workover, casing repair, and/or recompletion operations.
- 5. Contact this office at (505) 564-7750 prior to conducting any cementing operations

SPECIAL STIPULATIONS:

- 1. Pits will be fenced during work-over operation.
- 2. All disturbance will be kept on existing pad.
- 3. All pits will be pulled and closed immediately upon completion of the recompletion and work-over activities.
- 4. Pits will be lined with an impervious material at least 12 mils thick.