	<b>.</b> .						
			SEP 1 3 2013				
Form 3160-5	DIOD			FORM APPROVED			
(August 2007)	BURFALLOF LAND MANAGEMENT				OMB No. 1004-0137 Despires: July 31, 2010		
				5. Lease Serial No. 99 ment			
SUNDRY NOTICES AND REPORTS ON WELLS					NMSF-078496 6. If Indian, Allottee or Tribe Name		
Do not use this form for proposals to drill or to re-enter an							
abandoned well. Use Form 3160-3 (APD) for such proposals.							
SUBMIT IN TRIPLICATE - Other instructions on page 2.					_	7. If Unit of CA/Agreement, Name and/or No.	
1. Type of Well Oil Well X Gas Well Other					San Juan 28-7 Unit 8. Well Name and No.		
					San Juan 28-7 Unit 133G		
2. Name of Operator Hilcorp Energy Company					9. API Well No. <b>30-039-26699</b>		
3a. Address	e No. (include area code) 10. Field and Pool or Exploratory Area						
382 Road 3100, Aztec, I	505-599-3400 Basin Dakota / Blanco Mesaverde						
4. Location of Well <i>(Footage, Sec., T.,)</i> Surface Unit L (N	0 25 T29N D	07\0/	11. Country or Parish, State	Now Movico			
Surface Unit L (NWSW), 2170' FSL & 320' FWL, Sec. 35, T28N, R07W Rio Arriba , New Mexico						New Mexico	
12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA							
TYPE OF SUBMISSION	F SUBMISSION TYPE OF AC				TION		
X Notice of Intent	Acidize	Dee	pen		Production (Start/Resume)	Water Shut-Off	
	Alter Casing		ture Treat		Reclamation	Well Integrity	
Subsequent Report	Casing Repair		v Construction		Recomplete	X Other	
Final Abandonment Notice	Change Plans		g and Abandon g Back		Temporarily Abandon Water Disposal	Revised RC plan	
13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof.							
If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones.							
Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once							
Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has							
determined that the site is ready for final inspection.)							
Hilcorp Energy Company has received NOI approval to isolate the Dakota below a CIBP and perforate the Menefee and							
flow for testing for 6 months. Hilcorp is requesting an 6 months to continue testing before we return to the well to							
complete the rest of the MV recomplete and drill out the CIBP isolating the Dakota. The CIBP to isolate the Dakota is set within 50' of the top perforation of the Dakota.							
					NMOCD		
					Jeo 1 4 2018		
DISTRICT III							
14. I hereby certify that the foregoing is	true and correct. Name (Printed/Type	d)					
Christine Brock			Title Operations/Regulatory Technician - Sr.				
	The Operations/Regulatory recunician - 51.						
Phistern Recork							
Signature III M Studies Date 9/13/2018							
THIS SPACE FOR FEDERAL OR STATE OFFICE USE							
Approved by					2 1 /	1	
Chro/ture	Т	itle 🕻	seologist	Date 9/14/18			
Conditions of apploval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would Office							
entitle the applicant to conduct operations thereon.					SLM-FFO		
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false factitious or fraudulent statements or representations as to any matter within its invidiction							
false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. (Instruction on page 2)							
(Instruction on page 2) NMOCD A							