State of New Mexico Energy, Minerals and Natural Resources Department

Susana Martinez

Governor

Ken McQueen Cabinet Secretary

Matthias Sayer Deputy Cabinet Secretary **Heather Riley**, Division Director **Oil Conservation Division**



New Mexico Oil Conservation Division approval and conditions listed below are made in accordance with OCD Rule 19.15.7.11 and are in addition to the actions approved by BLM on the following 3160-4 or 3160-5 form.

Operator Signature Date: 6/28/18

Well information:

API WELL#	Well Name	Well #	Operator Name	Туре	Stat	County	Surf_Owner	UL	Sec	Twp	N/S	Rng W/E
00 0 10	GALLEGOS CANYON UNIT		BP AMERICA PRODUCTION COMPANY	G	А	San Juan	F	С	24	28	N	12 W

	plication Type: P&A Drilling/Casing Change Location Change
	Recomplete/DHC (For hydraulic fracturing operations review EPA Underground injection control Guidance #84; Submit Gas Capture Plan form prior to spudding or initiating recompletion operations)
	Other:
Cor	nditions of Approval:

- Notify NMOCD 24hrs prior to beginning operations.
- Extend Fruitland plug1532'- 1118'.

NMOCD Approved by Signature

9/12/18 Date Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

5.	Lease Serial No.
	NMSF078904

6.	If Indian, Allottee or Tribe Name
	EACTEDALALALA IO

SUNDRY	NMSF078904							
Do not use thi abandoned wel	If Indian, Allottee or Tribe Name EASTERN NAVAJO							
SUBMIT IN TRIPLICATE - Other instructions on page 2					7. If Unit or CA/Agreement, Name and/or No. 892000844E			
Type of Well					8. Well Name and No. GALLEGOS CANYON UNIT 298			
Name of Operator BP AMERICA PRODUCTION	Contact: CO E-Mail: patti.campt	PATTI CAMI pell@bpx.com	PBELL		9. API Well No. 30-045-23998-00-S1			
3a. Address 380 AIRPORT RD DURANGO, CO 81303	(include area code) 10. Field and Pool or Exploratory Area FULCHER KUTZ PICTURED							
4. Location of Well (Footage, Sec., T	., R., M., or Survey Description)				11. County or Parish, S	tate		
	Sec 24 T28N R12W NENW 0990FNL 1570FWL 36.652150 N Lat, 108.066160 W Lon				SAN JUAN COUNTY, NM			
12. CHECK THE AF	PROPRIATE BOX(ES)	TO INDICA	TE NATURE OI	F NOTICE,	REPORT, OR OTH	ER DATA		
TYPE OF SUBMISSION			TYPE OF	ACTION				
Notice of Intent	☐ Acidize	☐ Dee	pen	☐ Product	ion (Start/Resume)	☐ Water Shut-Off		
	☐ Alter Casing	□ Нус	Iraulic Fracturing	☐ Reclam	ation	☐ Well Int	egrity	
☐ Subsequent Report	☐ Casing Repair	□ Nev	v Construction	☐ Recomp	olete	Other		
☐ Final Abandonment Notice	☐ Change Plans	☑ Plug	g and Abandon	☐ Tempor	arily Abandon			
	☐ Convert to Injection	□ Plug	g Back	□ Water I	Disposal			
following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. BP requests to P&A the subject well. Please see the attached P&A package including the P&a procedure, wellbore diagrams and BLM required reclamation plan documents. In accordance with NMOCD Pit Rule 19.15.17.9 NMAC, BP will use a closed-loop system during operations. AUG 2 0 2018								
14. I hereby certify that the foregoing is	true and correct. Electronic Submission #4	125040	d bookba DI M MA	l la farma di an	Curtain Company			
	For BP AMERICA	PRODUCTIO	N CO, sent to the	Farmingtor	1			
	CK SAVAGE on 08/16/2018 (18JWS0145SE) Title REGULATORY ANALYST							
Name (Printed/Typed) PATTI CA	Title REGUL	ATORY AN	ALYSI					
Signature (Electronic S	Submission)		Date 06/28/20	018				
	THIS SPACE FO	R FEDERA	AL OR STATE	OFFICE U	SE			
_Approved By _JACK SAVAGE_ Conditions of approval, if any, are attached	d. Approval of this notice does	not warrant or	TitlePETROLE	UM ENGINI	EER	Date (08/16/2018	
certify that the applicant holds legal or equ which would entitle the applicant to condu	Office Farming							
Title 18 U.S.C. Section 1001 and Title 43	U.S.C. Section 1212, make it a	crime for any p	erson knowingly and	willfully to ma	ake to any department or a	gency of the U	Inited	







PLUG AND ABANDONMENT PROCEDURE

May 17, 2018

Gallegos Canyon Unit #298

West Kutz Pictured Cliffs 990' FNL & 1570' FWL, Section 24, T28N, R12W San Juan County, New Mexico / API 30-045-23998

Note: All cement volumes use 100% excess outside pipe and 50' excess inside. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures. All cement will be Class B, mixed at 15.6 ppg with a 1.18 cf/sx yield.

1.	Install and test location rig anchors. Comply with all NMOCD, BLM, and Operator safety regulations. MOL and RU daylight pulling unit. Conduct safety meeting for all personnel on location. Record casing, tubing and bradenhead pressures. NU relief line and blow down well. Kill well with water as necessary and at least pump tubing capacity of water down the tubing. ND wellhead and NU BOP. Function test BOP.
2.	Rods: Yes_X, No, Unknown Tubing: Yes_X, No, Unknown, Size2-3/8"_, Length Packer: Yes, No_X, Unknown, Type
3.	Plug #1 (Pictured Cliffs interval and Fruitland top, 1532' – 1267'): Round trip 4.5" gauge ring or mill. RIH and set 4.5" CR at 1532'. Pressure test tubing to 1000#. Circulate well clean. Pressure test casing to 800#. <i>If casing does not test then spot or tag subsequent plugs as appropriate</i> . Mix 25 sxs Class G cement inside casing from 1532' to cover the PC interval through the Fruitland top. PUH.

- 4. Plug #2 (Kirtland, and 8.625" casing shoe, 519' 0'): Attempt to pressure test the bradenhead annulus to 300 PSI; note the volume to load. If the BH annulus holds pressure, then establish circulation out casing valve with water. Mix approximately 41 sxs cement and spot a balanced plug from 519' to surface, circulate good cement out casing valve. TOH and LD tubing. Shut well in and WOC. If the BH annulus does not test, then perforate at the appropriate depth and attempt to circulate cement to surface filling the casing and annulus from the squeeze holes to surface. Shut in well and WOC.
- ND cementing valves and cut off wellhead. Fill annuli with cement as necessary. Install P&A
 marker to comply with regulations. Record GPS coordinate for P&A marker on tower report.
 Photograph P&A marker in place. RD, MOL and cut off anchors. Restore location per BLM
 stipulations

Gallegos Canyon Unit #298

Current

West Kutz Pictured Cliffs 990' FNL & 1570' FWL, Section 24, T-28-N, R-12-W

Today's Date: 5/17/18 Spud: 12/21/79 Completed: 1/28/80 Elevation: 5719' GL

12.25" hole

San Juan County, NM, API #30-045-23998

Ojo Alamo @ 388'

Kirtland @ 469'

Fruitland @ 1317'

Pictured Cliffs @ 1577'

6.75" hole

TD 1840'

PBTD 1788'

Circulated cement to surface

8-5/8" 20# Casing set @ 131' Cement with 100 sxs, circulated

2-3/8" Tubing @ 1618'

Pictured Cliffs Perforations: 1582' - 1598'

4.5",9.5#, Casing set @ 1829' Cement with 400 sxs, TOC @ 200' per TS

Gallegos Canyon Unit #298

Proposed P&A

West Kutz Pictured Cliffs
990' FNL & 1570' FWL, Section 24, T-28-N, R-12-W

Today's Date: **5/17/18** Spud: 12/21/79 Completed: 1/28/80 Elevation: 5719' GL

San Juan County, NM, API #30-045-23998

12.25" hole

Circulated cement to surface

8-5/8" 20# Casing set @ 131' Cement with 100 sxs, circulated

Ojo Alamo @ 388'

Kirtland @ 469'

.....

Plug #2: 519' - 0' Class G cement, 41 sxs

Fruitland @ 1317'

Pictured Cliffs @ 1577'

6.75" hole



TD 1840' PBTD 1788' Plug #1: 1532' – 1267' Class G cement, 25 sxs

Set CR @ 1532'

Pictured Cliffs Perforations: 1582' – 1598'

4.5",9.5#, Casing set @ 1829' Cement with 400 sxs, TOC @ 200' per TS

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

6251 COLLEGE BLVD. FARMINGTON, NEW MEXICO 87402

Attachment to notice of Intention to Abandon:

Re: Permanent Abandonment

Well: GCU 298

CONDITIONS OF APPROVAL

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."
- 2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 564-7750.
- 3. The following modifications to your plugging program are to be made:
 - a) Set Plug 1 (1532 1242) ft. to cover the Fruitland top. BLM picks top of Fruitland at 1292 ft.

Operator must run a CBL to verify cement top. Submit the electronic copy of the log for verification to the following addresses: jwsavage@blm.gov Brandon.Powell@state.nm.us

H2S has not been reported in this section, however, low concentrations of H2S (<100 ppm GSV) have been reported in the NENE/4 Sec. 26, 28N, 12W.

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.