	Submit 1 Copy To Appropriate District Office	State of New Me	xico			Form C-103
	District I – (575) 393-6161	Energy, Minerals and Natu	ral Resources	THE PARTY OF THE P		d July 18, 2013
	1625 N. French Dr., Hobbs, NM 88240			WELL API NO		
	<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION	DIVISION	5. Indicate Typ	30-039-82362	
	District III - (505) 334-6178	1220 South St. Fran	icis Dr.	STATE		
	1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460	Santa Fe, NM 87	505	6. State Oil &		
	1220 S. St. Francis Dr., Santa Fe, NM				E-290-30	
	87505 SUNDRY NOTI	CES AND REPORTS ON WELLS		7. Lease Name	or Unit Agree	ment Name
	(DO NOT USE THIS FORM FOR PROPOS	SALS TO DRILL OR TO DEEPEN OR PLU				
	DIFFERENT RESERVOIR. USE "APPLIC PROPOSALS.)	CATION FOR PERMIT" (FORM C-101) FC	OR SUCH		n Juan 27-5 Un	it
		Gas Well 🛛 Other		8. Well Number		
	2. Name of Operator			9. OGRID Nui	90 mher	
	HILCORP ENERGY COMPAN	NY		7. OGRID IVan	372171	
	3. Address of Operator			10. Pool name		
	382 Road 3100, Aztec, NM 874	-10		Blanco M	esaverde/Basin	Dakota
	4. Well Location					
		75' feet from the North line and				
	Section 16	Township 027N	Range 005W	NMPM	Rio Arriba	County
		11. Elevation (Show whether DR, 656		.)		
-		030		, and the		
	12. Check A	appropriate Box to Indicate N	ature of Notice.	Report or Oth	er Data	
				•		_
	NOTICE OF IN			SEQUENT R		
	PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WOR			CASING
	TEMPORARILY ABANDON	CHANGE PLANS MULTIPLE COMPL		ILLING OPNS.	P AND A	
	PULL OR ALTER CASING DOWNHOLE COMMINGLE	MULTIPLE COMPL	CASING/CEMEN	II JOB		
	CLOSED-LOOP SYSTEM					
	OTHER:	RECOMPLETE	OTHER:			
	13. Describe proposed or compl	eted operations. (Clearly state all p				
		rk). SEE RULE 19.15.7.14 NMAC	C. For Multiple Co	mpletions: Attacl	n wellbore diag	ram of
	proposed completion or reco	ompletion.				
	Hilcorp Energy Company plans to re	complete the subject well in the Me	saverde formation	and downhole co	mmingle with t	he existing
	Dakota. Attached is the MV C102, r	ecomplete procedure & wellbore so				
1	prior to commingling. A Closed Loop	p system will be utilized.				
,	**Please note: MV is pending approv	val of wall density bearing**	Notify N	MOCD 24 hrs		
	release note. Wiv is pending approv	val of well density hearing.		o beginning crations		
				42.00	MMOCI	· Americanist principle
		Density ex	ception		MMOCI	,
	+ Submit CBL for reviewed in tion.	OLD CTU4 POR			NOV 05	2018
	+ Submit CBL for review	ew and approval prior	to pertoration	ns or	1404 00	2010
	remediation.				DISTRICT	
	Spud Date:	Rig Release Da	te:			
		This release bu				
	hereby certify that the information a	above, is true and complete to the be	st of my knowledg	ge and belief.		
	SILOT-		(D)			
	SIGNATURE SHALLS	TITLE Operati	ons / Regulatory T	echnician DATE	E11/01/2	2018
,	Гуре or print nameEtta Trujillo	E-mail address:et	trujillo@hilcorp.co	om PHONI	E: 505-324-	5161
	For State Use Only					
	APPROVED BY: Pranalin	Deput Deput	y Oil & Gas II	nspector,	DATE 11/13	1,0
	APPROVED BY: Dylandim Conditions of Approval (if any):	TITLE	District #3		DATE MID	10
,	conditions of Approval (II ally).	, V				1

Form C-102 August 1, 2011

Permit 259143

District I

1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720

District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

WELL LOCATION AND ACREAGE DEDICATION PLAT

1. API Number 30-039-82362	2. Pool Code 72319	3. Pool Name BLANCO-MESAVERDE (PRORATED GAS)
4. Property Code 318920	5. Property Name SAN JUAN 27 5 UNIT	6. Well No. 090
7. OGRID No. 372171	8. Operator Name HILCORP ENERGY COMPANY	9. Elevation 6564

10. Surface Location

UL - Lot	Section	Township	Range	Lot Idn	Feet From	N/S Line	Feet From	E/W Line	County
G	16	27N	05W		2375	N	2200	E	RIO ARRIBA

11. Bottom Hole Location If Different From Surface

_										
l	JL - Lot	Section	Township	Range	Lot Idn	Feet From	N/S Line	Feet From	E/W Line	County
	2. Dedicated A	cres .00 E/2		13. Joint or Infill		14. Consolidation	n Code		15. Order No.	

NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION

OPERATOR CERTIFICATION

I hereby certify that the information contained herein is true and complete to the best of my knowledge and belief, and that this organization either owns a working interest or unleased mineral interest in the land including the proposed bottom hole location(s) or has a right to drill this well at this location pursuant to a contract with an owner of such a mineral or working interest, or to a voluntary pooling agreement or a compulsory pooling order heretofore entered by the division.

E-Signed By: Etta Trujillo

Title: Operations/Regulatory Tech Sr

Date: 10/31/2018

SURVEYOR CERTIFICATION

I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by me or under my supervision, and that the same is true and correct to the best of my belief.

Surveyed By:

David Kilven

Date of Survey:

9/10/1962

Certificate Number:

1760



HILCORP ENERGY COMPANY SAN JUAN 27-5 UNIT 90 MESA VERDE RECOMPLETION SUNDRY

JOB PROCEDURES

- 1. MIRU service rig and associated equipment; test BOP.
- 2. TOOH with 2 3/8" tubing set at 7,765'.
- 3. Set a 4-1/2" plug at +/- 7,515' to isolate the Dakota.
- 4. RU Wireline. Run CBL. Record Top of Cement.
- 5. IF NECESSARY (Based on the results of the CBL top of cement) Perform cement squeeze work.
- 6. Set a 4-1/2" plug at +/- 6,085'.
- 7. Load the hole and pressure test the casing.
- 8. N/D BOP, N/U frac stack and pressure test frac stack.
- 9. Perforate and frac the Mesa Verde formation (Top Perforation @ 5,041'; Bottom Perforation @ 6,020').
- 10. Isolate frac stages with a plug.
- 11. Nipple down frac stack, nipple up BOP and test.
- 12. TIH with a mill and drill out top isolation plug and Mesa Verde frac plugs.
- 13. Clean out to Dakota isolation plug.
- 14. Drill out Dakota isolation plug and cleanout to PBTD of 7,814'. TOOH.
- 15. TIH and land production tubing. Get a commingled Dakota/Mesa Verde flow rate.



HILCORP ENERGY COMPANY SAN JUAN 27-5 UNIT 90 MESA VERDE RECOMPLETION SUNDRY

