State of New Mexico Energy, Minerals and Natural Resources Department

Susana Martinez

Governor

Ken McQueen Cabinet Secretary

Matthias Sayer Deputy Cabinet Secretary **Heather Riley, Division Director Oil Conservation Division**



New Mexico Oil Conservation Division approval and conditions listed below are made in accordance with OCD Rule 19.15.7.11 and are in addition to the actions approved by BLM on the following 3160-4 or 3160-5 form.

Operator Signature Date: 10/29/18 Well information: HILCORP ENERGY COMPANY SAN JUAN 28 6 UNIT #125, API#30-039-20060
Application Type: P&A Drilling/Casing Change Location Change Recomplete/DHC (For hydraulic fracturing operations review EPA Underground injection control Guidance #84; Submit Gas Capture Plan form prior to spudding or initiating recompletion operations) Other: Conditions of Approval: Notify the NMOCD 24hrs prior to beginning operations. Submit the CBL to the agencies for review and approval prior to any remediation or perforations.
MMOCD Americal by Signature 11/29/18
NMOCD Approved by Signature Date

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED

OMB No. 1004-0137

OCT 3 1 20:3


Expires: July 31, 2010

5. Lease Serial No.

NMSF079193

Do not use	DRY NOTICES AND REPOR this form for proposals to well. Use Form 3160-3 (AP	drill or to re-ent		6. If Indian, Allottee or Tribe Name	e O
	BMIT IN TRIPLICATE - Other instru		00010.	7. If Unit of CA/Agreement, Name	and/or No.
1. Type of Well					
Oil Well	Gas Well Other			8. Well Name and No. San Juan 2	28-6 Unit 125
2. Name of Operator	Hilaara Enargy Compan			9. API Well No.	
3a. Address	Hilcorp Energy Compan	y o. Phone No. (include a	roo aada)	30-039	
382 Road 3100, Aztec, N		505-599-3			rde/Basin Dakota
4. Location of Well (Footage, Sec., T.,R Surface Unit H (S	.,M., or Survey Description) ENE) 1740'FNL & 1190' FEL	., Sec. 21, T28N,	R06W	11. Country or Parish, State Rio Arriba ,	New Mexico
12. CHECK T	HE APPROPRIATE BOX(ES) T	O INDICATE NATU	IRE OF NOT	TICE, REPORT OR OTHER	DATA
TYPE OF SUBMISSION		TY	PE OF AC	TION	
X Notice of Intent	Acidize Alter Casing	Deepen Fracture Treat		roduction (Start/Resume)	Water Shut-Off Well Integrity
Subsequent Report	Casing Repair	New Construction		Lecomplete	Other
	Change Plans	Plug and Abandon	Т	emporarily Abandon	
Final Abandonment Notice	Convert to Injection	Plug Back	W W	Vater Disposal	
the existing Dakota. Att	y plans to recomplete the s ached is the MV C102, reco I prior to commingling. A c disturbing activities.	mplete procedu	re & wellb	ore schematic. The DHC	application will be
	NMOCD NOV 2 6 2018	AUTHO ON FE	ORIZATION DERAL ANI	OR ACCEPTANCE OF THIS OT RELIEVE THE LESSEE A MOBITAINING ANY OTHER REQUIRED FOR OPERATI D INDIAN LANDS	ONS
14. I hereby certify that the foregoing is	true and correct. Name (Printed Typea	Vanue.			
Tammy Jones		Title O	perations/R	egulatory Technician - Sr.	
Signature Tammy	Ines	Date		10/29/2018	
	THIS SPACE FOR	FEDERAL OR S	TATE OFF	ICE USE	/ /
Approved by Conditions of approval, if any, are ditacle	ned Approval of this notice does not w	arrant or certify	Title)E	Date #1/17/18
that the applicant holds legal or equitable entitle the applicant to conduct operation	title to those rights in the subject lease		Office	FTO	/ '

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.



District I

1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720

District II

811 S. First St., Artesia, NM 88210 Phone: (575) 748-1283 Fax: (575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr.

Form C-102 August 1, 2011

Permit 259193

WELL LOCATION AND ACREAGE DEDICATION PLAT

Santa Fe, NM 87505

1. API Number 30-039-20060	2. Pool Code 72319	3. Pool Name BLANCO-MESAVERDE (PRORATED GAS)
4. Property Code 318710	5. Property Name SAN JUAN 28 6 UNIT	6. Well No. 125
7. OGRID No. 372171	8. Operator Name HILCORP ENERGY COMPANY	9. Elevation 6456

10. Surface Location

UL - Lot	Section 21	Township 28N	Range 06W	Lot Idn	Feet From 1740	N/S Line N	Feet From 1190	E/W Line E	County RIO ARRIBA

11. Bottom Hole Location If Different From Surface

UL - Lot	Section	Township	Range	Lot Idn	Feet From	N/S Line	Feet From	E/W Line	County
12. Dedicated A			13. Joint or Infill		14. Consolidatio	n Code		15. Order No.	

NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION

OPERATOR CERTIFICATION

I hereby certify that the information contained herein is true and complete to the best of my knowledge and belief, and that this organization either owns a working interest or unleased mineral interest in the land including the proposed bottom hole location(s) or has a right to drill this well at this location pursuant to a contract with an owner of such a mineral or working interest, or to a voluntary pooling agreement or a compulsory pooling order heretofore entered by the division.

E-Signed By:

Tammy Jones

Title:

Operations/Regulatory Technician - Sr.

Date:

10/29/2018

SURVEYOR CERTIFICATION

I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by me or under my supervision, and that the same is true and correct to the best of my belief.

Surveyed By:

David Kilven

Date of Survey:

4/5/1967

Certificate Number:

1760



HILCORP ENERGY COMPANY SAN JUAN 28-6 UNIT 125 MESA VERDE RECOMPLETION SUNDRY

JOB PROCEDURES

- 1. MIRU service rig and associated equipment; test BOP.
- 2. TOOH with 2 3/8" tubing set at 7,704'.
- 3. Set a 4-1/2" plug at +/- 7,470' to isolate the Dakota.
- 4. RU Wireline. Run CBL. Record Top of Cement.
- 5. IF NECESSARY (Based on the results of the CBL top of cement) Perform cement squeeze work.
- 6. Set a 4-1/2" plug at +/- 6,040'.
- 7. Load the hole and pressure test the casing.
- 8. N/D BOP, N/U frac stack and pressure test frac stack.
- 9. Perforate and frac the Mesa Verde formation (Top Perforation @ 4,860'; Bottom Perforation @ 5,975').
- 10. Isolate frac stages with a plug.
- 11. Nipple down frac stack, nipple up BOP and test.
- 12. TIH with a mill and drill out top isolation plug and Mesa Verde frac plugs.
- 13. Clean out to Dakota isolation plug.
- 14. Drill out Dakota isolation plug and cleanout to PBTD of 7,805'. TOOH.
- 15. TIH and land production tubing. Get a commingled Dakota/Mesa Verde flow rate.



HILCORP ENERGY COMPANY SAN JUAN 28-6 UNIT 125 MESA VERDE RECOMPLETION SUNDRY

