State of New Mexico Energy, Minerals and Natural Resources Department

Susana Martinez
Governor

Ken McQueen
Cabinet Secretary

Matthias Sayer
Deputy Cabinet Secretary

New Mexico Oil Conserva
listed below are made in ac
and are in addition to th
following 3

Operator Signature Date: 11/2/18
Well information:
HILCORP ENERGY COMPANY
SAN JUAN 28 6 UNIT #111, API# 3

Heather Riley, Division Director Oil Conservation Division



New Mexico Oil Conservation Division approval and conditions listed below are made in accordance with OCD Rule 19.15.7.11 and are in addition to the actions approved by BLM on the following 3160-4 or 3160-5 form.

HILCORP ENERGY COMPANY SAN JUAN 28 6 UNIT #111, API# 30-039-82368
Application Type: P&A Drilling/Casing Change Location Change Recomplete/DHC (For hydraulic fracturing operations review EPA Underground injection control Guidance #84; Submit Gas Capture Plan form prior to spudding or initiating recompletion operations) Other:
Conditions of Approval:
 Notify the NMOCD 24hrs prior to beginning operations. Submit the CBL to the agencies for review and approval prior to any remediation or perforations.
Tesheric Parks 11/29/18
NMOCD Approved by Signature Date

Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB No. 1004-0137

Expires: July 31, 2010

NMSF079365

5. Lease Serial No.

SUNDRY NOTICES AND REPO	ter an	6. If Indian, Allottee or Tribe	e Name				
abandoned well. Use Form 3160-3 (A	oosais.						
SUBMIT IN TRIPLICATE - Other inst		7. If Unit of CA/Agreement,	Name and/or No.				
Oil Well X Gas Well Other			8. Well Name and No. San Juan 28-6 Unit 111				
2. Name of Operator			9. API Well No.				
Hilcorp Energy Compa				-039-82368			
382 Road 3100, Aztec, NM 87410	3b. Phone No. (include 505-599- ;	,	10. Field and Pool or Exploratory Area Blanco Mesaverde/Basin Dakota				
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) Surface Unit M (SWSW) 890'FSL & 790' FW	L, Sec. 15, T27N,	R06W	11. Country or Parish, State Rio Arriba	, New Mexico			
12. CHECK THE APPROPRIATE BOX(ES)	TO INDICATE NAT	URE OF NOT	ICE, REPORT OR OTH	HER DATA			
TYPE OF SUBMISSION	T	YPE OF AC	TION				
X Notice of Intent Acidize Alter Casing	Deepen Fracture Treat		roduction (Start/Resume)	Water Shut-Off Well Integrity			
Subsequent Report Casing Repair	New Construction		ecomplete	Other			
Change Plans	Plug and Abandon		emporarily Abandon				
Final Abandonment Notice Convert to Injection	Plug Back		ater Disposal				
Hilcorp Energy Company plans to recomplete the the existing Dakota. Attached is the MV C102, rec submitted and approved prior to commingling. A performed after surface disturbing activities.	complete procedi	ure & wellbo em will be u	ore schematic. The utilized. Interim recla	DHC application will be amation will be			
Please note: MV is pending approval of well der	nsity hearing		HOLD GIBA FOR	Density exception			
NMOCD NOV 2 6 2018	, ,	ACTION DO OPERATOR AUTHORIZ.	ROVAL OR ACCEPT AN SES NOT RELIEVE THE FROM OBTAINING A ATION REQUIRED FO AL AND INDIAN LAND	E LESSEE AND NY OTHER R OPERATIONS			
DISTRICT III							
14. I hereby certify that the foregoing is true and correct. Name (Printed/Typ							
	ped)						
Tammy Jones		perations/R	egulatory Technician				
Tammy Jones Signature Tammy Imag		perations/R	egulatory Technician 11/2/20	- Sr.			
Signature Tammy Imes	Title C		11/2/20	- Sr.			

(Instruction on page 2)

false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

District I

1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720

District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170 **District IV**

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources

Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

WELL LOCATION AND ACREAGE DEDICATION PLAT

1. API Number 30-039-82368	2. Pool Code 72319	3. Pool Name BLANCO-MESAVERDE (PRORATED GAS)
4. Property Code 318710	5. Property Name SAN JUAN 28 6 UNIT	6. Well No.
7. OGRID No. 372171	8. Operator Name HILCORP ENERGY COMPANY	9. Elevation 6501


10. Surface Location

10.001.000															
UL - Lot		Section		Township		Range		Lot Idn	Feet From	N/S Line	T	Feet From	E/W Line	County	
	M		15		27N		06W		890		S	790	V	/	RIO ARRIBA

11. Bottom Hole Location If Different From Surface

UL - Lot	Section	Township	Range	Lot Idn	Lot Idn Feet From N/S Line Feet From		Feet From	E/W Line	County
12. Dedicated A			13. Joint or Infill		14. Consolidation	on Code		15. Order No.	

NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION



OPERATOR CERTIFICATION

I hereby certify that the information contained herein is true and complete to the best of my knowledge and belief, and that this organization either owns a working interest or unleased mineral interest in the land including the proposed bottom hole location(s) or has a right to drill this well at this location pursuant to a contract with an owner of such a mineral or working interest, or to a voluntary pooling agreement or a compulsory pooling order heretofore entered by the division.

E-Signed By: Tammy Jones

Title: Operations/Regulatory Technician - Sr.

Date: 11/2/2018

SURVEYOR CERTIFICATION

I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by me or under my supervision, and that the same is true and correct to the best of my belief.

Surveyed By:

David Kilven

Date of Survey:

9/25/1962

Certificate Number:

1760

Form C-102 August 1, 2011

Permit 259295



HILCORP ENERGY COMPANY SAN JUAN 28-6 UNIT 111 MESA VERDE RECOMPLETION SUNDRY

JOB PROCEDURES

- 1. MIRU service rig and associated equipment; test BOP.
- 2. TOOH with 2 3/8" tubing set at 7,549'.
- 3. Set a 4-1/2" plug at +/- 6,035' to isolate the Dakota.
- 4. RU Wireline. Run CBL. Record Top of Cement.
- 5. Load the hole and pressure test the casing.
- 6. N/D BOP, N/U frac stack and pressure test frac stack.
- 7. Perforate and frac the Mesa Verde formation (Top Perforation @ 4,800'; Bottom Perforation @ 5,785').
- 8. Isolate frac stages with a plug.
- 9. Nipple down frac stack, nipple up BOP and test.
- 10. TIH with a mill and drill out top isolation plug and Mesa Verde frac plugs.
- 11. Clean out to Dakota isolation plug.
- 12. Drill out Dakota isolation plug and cleanout to PBTD of 7,610'. TOOH.
- 13. TIH and land production tubing. Get a commingled Dakota/Mesa Verde flow rate.



HILCORP ENERGY COMPANY SAN JUAN 28-6 UNIT 111 MESA VERDE RECOMPLETION SUNDRY

