								20		
Form 3160-5 UNITED STATES					F	ORM APPI	ROVED	SCEN.		
(August 2007) DEPARTMENT OF THE INTERIOR						MB No. 10	0.17	EL		
BUREAU OF LAND MANAGEMENT					5. Lease Serial No.	pires: July	31,2010	19 20		
			5. Lease Serial No.	NMSF	079193	<0:3				
	NDRY NOTICES AND REPORT				6. If Indian, Allottee or 7			la.		
	e this form for proposals to dr I well. Use Form 3160-3 (APD)						Nig	Orr		
	JBMIT IN TRIPLICATE - Other instruction			5.	7. If Unit of CA/Agreem	ant Nama	and/or No	-Johner		
1. Type of Well		uns un page	ζ.		7. If Offit of CA/Agreen		1 28-6 Unit	14		
	X Gas Well Other				8. Well Name and No.					
						Juan 2	8-6 Unit 119			
2. Name of Operator	Hilcorp Energy Company				9. API Well No.	30-039-	-08063			
3a. Address		Phone No. (inc	lude area cod	e)	10. Field and Pool or Ex					
382 Road 3100, Aztec, I		505-5	99-3400		Blanco N	Blanco Mesaverde / Basin Dakota				
4. Location of Well (Footage, Sec., T.,					11. Country or Parish, S		New Mexic			
Surface Unit H (S	SE/NE) 1500'FNL &1090' FEL, \$	Sec. 22 12	8N, R06W	V	Rio Arriba	ι,	New Mexic	0		
12. CHECK	THE APPROPRIATE BOX(ES) TO		NATURE O	FNC	OTICE, REPORT OR	OTHER I	DATA			
TYPE OF SUBMISSION			TYPE O							
			I IPE U				7			
X Notice of Intent		Deepen Fracture Treat		\square	Production (Start/Resume) Reclamation		Water Shut-Off Well Integrity			
Subsequent Report		New Construc			Recomplete		Other			
		Plug and Abar			Temporarily Abandon					
Final Abandonment Notice	Convert to Injection	Plug Back			Water Disposal					
	peration: Clearly state all pertinent details, in	-	-							
	onally or recomplete horizontally, give subs work will be performed or provide the Bond									
	ved operations. If the operation results in a r									
	l Abandonment Notices must be filed only a									
determined that the site is ready for	r final inspection.)									
O Hilcorn Energy Compa	ny plans to recomplete the sub	night woll	in the Mo	cave	ordo formation and	downh	olo commin	alo tho		
	e Mesaverde. Attached is the M									
application will be subr	nitted and approved before the	e work pro	oceeds. A							
reclamation will be per	g activities	s.		HOLD C104	FOR	Instruction	reption			
					HULD CITY					
**Please note: MV is pe	nding approval of well density	hearing*								
			BLM'S AF	PPR	OVAL OR ACCEPTAN S NOT RELIEVE THE	LI PERI	EAND			
Notify NMOCD 24 hrs		OPERAT	ORF	ROM OBTAINING AN	VY OTHE	ER				
prior to beginning operations DEC 2 0 2018			AUTHORIZATION REQUIRED FOR OPERATIONS							
				L AND INDIAN LANDS						
	INTRIAT IN				BMIT CBL TO					
14 I hereby certify that the foregoing i	s true and correct. Name (Printed/Typed)		_ AGE	NC	IES FOR REVI	EW A	ND			
14. Thereby certify that the folegoing f	s file and correct. Ivanic (1 rimew Typed)				APPROVAL					
Etta Trujillo		Title	Operati	ons/	Regulatory Technici	an - Sr.				
Signature	Ting	Date			11/9/	2018				
Signature Uth			- 01		2010					
	U THIS SPACE FOR FI	EDERAL (DRSTATE		-FICE USE		-			
Approved by								11		
1 Holk no	ug		Title	9	PE		Date 12/1	17/18		
	hed. Approval of this notice does not warra							1		
that the applicant holds legal or equitate entitle the applicant to conduct operation	the to those rights in the subject lease when	hich would	Offi	ce	Fto			/		
	43 U.S.C. Section 1212, make it a crime for	any person kn	lowingly and	willfu	ally to make to any departme	ent or agen	cy of the United S	tates any		
	s or representations as to any matter within it		0,		,,					
(Instruction on page 2)		NIAAC	ODPN	(4		
		1 VIVIO	00							

1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

B11 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170 District IV

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

WELL LOCATION AND ACREAGE DEDICATION PLAT

1. API Number	2. Pool Code	3. Pool Name
30-039-08063	72319	BLANCO-MESAVERDE (PRORATED GAS)
4. Property Code	5. Property Name	6. Well No.
318710	SAN JUAN 28 6 UNIT	119
7. OGRID No.	8. Operator Name	9. Elevation
372171	HILCORP ENERGY COMPANY	6558

10. Surface Location

UL - Lot H	Section 22	Township 28N	Range 06W	Lot Idn	Feet From 1500	N/S Line N	Feet From 1090	E/W Line E	County RIO	ARRIBA

11. Bottom Hole Location If Different From Surface

UL - Lot	Section	Township	Range	Lot Idn	Feet From	N/S Line	Feet From	E/W Line	County
	12. Dedicated Acres 320.00 E/2		13. Joint or Infill		14. Consolidation Code			15. Order No.	

NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION

OPERATOR CERTIFICATION I hereby certify that the information contained herein is true and complete to the best of my knowledge and belief, and that this organization either owns a working interest or unleased mineral interest in the land including the proposed bottom hole location(s) or has a right to drill this well at this location pursuant to a contract with an owner of such a mineral or working					
interest, or to a voluntary pooling agreement or a compulsory pooling order heretofore entered by the division.					
E-Signed By: <i>Etta Trujillo</i> Title: Operations/Regulatory Tech Sr Date: 11/13/2018					
SURVEYOR CERTIFICATION I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by me or under my supervision, and that the same is true and correct to the best of my belief.					
Surveyed By: David Kilven					
Date of Survey: 10/21/1965					
Certificate Number: 1760					

Permit 259638

Hilcorp

٢

HILCORP ENERGY COMPANY San Juan 28-6 Unit 119 MESA VERDE RECOMPLETION SUNDRY

(JOB PROCEDURES
1.	MIRU service rig and associated equipment; test BOP.
2.	TOOH with 2 3/8" tubing set at 7,807'.
3.	Set a 4-1/2" cast iron bridge plug at +/- 7,600' to isolate the Dakota.
4.	Load the hole and run a CBL from the CIBP to surface.
5.	Set a 4-1/2" cast iron bridge plug at +/- 5,760' to isolate the Stage Tool.
6.	Perforate the Mesa Verde (Top Perforation @ 5,050'; Bottom Perforation @ 5,710').
7.	RIH with a packer and 2-7/8" Frac string set at 5,000'. NU Test Frac stack and frac string.
8.	Frac the Mesa Verde
9.	Nipple down frac stack, nipple up BOP and test.
10.	TOOH 2-7/8" Frac String.
11.	TIH with a mill.
12.	Clean out to Dakota isolation plug.
13.	Drill out Dakota isolation plug and cleanout to PBTD of 7,883' . TOOH.
14.	TIH and land production tubing at 7,807'.



HILCORP ENERGY COMPANY San Juan 28-6 Unit 119 MESA VERDE RECOMPLETION SUNDRY

.

