Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

SUNDRY NOTICES AND REPORTS ON WELLS

5. Lease Serial No. NMNM40638

Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.				6. If Indian, Allottee or Tribe Name	
SUBMIT IN TRIPLICATE - Other instructions on page 2				7. If Unit or CA/Agreement, Name and/or No. NM015P3586C516	
1. Type of Well				8. Well Name and No. COBH 1	
Oil Well ☑ Gas Well ☐ Other 2. Name of Operator Contact: ALIPH REENA				9. API Well No.	
DUGAN PRODUCTION CORPORATIŒMail: aliph.reena@duganproduction.com				30-039-23743-00-S1	
3a. Address FARMINGTON, NM 87499	To. (include area code) 325-1821		Field and Pool or Exploratory Area S BLANCO		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)				11. County or Parish, St	ate
Sec 22 T24N R2W SWSE 1150FSL 1630FEL 36.292120 N Lat, 107.033604 W Lon				RIO ARRIBA COUNTY, NM	
12. CHECK THE AI	PPROPRIATE BOX(ES) TO INDICA	ATE NATURE OF	F NOTICE, I	REPORT, OR OTHI	ER DATA
TYPE OF SUBMISSION	TYPE OF ACTION				4)
☐ Notice of Intent	☐ Acidize ☐ De	epen		on (Start/Resume)	☐ Water Shut-Off
	☐ Alter Casing ☐ Hy	draulic Fracturing	□ Reclamat	tion	■ Well Integrity
Subsequent Report	☐ Casing Repair ☐ Ne	ew Construction	□ Recompl	ete	☐ Other
☐ Final Abandonment Notice		ag and Abandon	_	rily Abandon	
CV/	☐ Convert to Injection ☐ Plug Back ☐ Wat		☐ Water Di	r Disposal y proposed work and approximate duration thereof.	
If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or completion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. The well was P&A'd on 9/17/18-9/20/18 as per the following procedure: 1) Set 4-1/2" CIBP @ 3189'. Load and circulate hole. Pressure test casing to 600 psi. Casing won't pressure test. 2) Spot Plug I above CIBP @ 3189' inside 4-1/2" casing w/45 sks (53.1 cu ft - 15.6#/gal, 1.18 cu ft/sk, 5.2 gals/sk mix water) Class G neat cement. Displace w/10 bbls water. WOC overnight. Tag TOC @ 2557'. Good tag, Plug I: 2557'-3189' - PC-Fruitland-Kirtland-ojo Alamo: 2557'-3189'. 3) Run CBL from 2557' to surface. 4) Perforate @ 1600'. Set 4-1/2" CR @ 1558'. Pressure test casing above CR @ 1558' to 700 psi. Held good. Sting inside CR. Cannot establish rate below CR into the perfs. Checked w/OCD/BLM. spot 250' inside plug w/18 sks (21.2 cu ft) Class G neat cement to 1308' (15.6#/gal, 1.18 cu ft/sk). Displace w/4.5 bbls water. Plug II: Nacimiento 1308' 1558'. 5) Perforate below casing shoe @ 200'. Establish circulation to surface w/4 bbls water. Mix 82					
14. I hereby certify that the foregoing is true and correct. Electronic Submission #437868 verified by the BLM Well Information System For DUGAN PRODUCTION CORPORATION, sent to the Rio Puerco Committed to AFMSS for processing by JACK SAVAGE on 11/09/2018 (18JWS0005SE)					
Name (Printed/Typed) ALIPH RE	Title PRODU	CTION ENG	INEER		
Signature (Electronic S	Date 10/01/20	018			
THIS SPACE FOR FEDERAL OR STATE OFFICE USE					
Approved By ACCEPTED		JACK SAV TitlePETROLE		ER -	Date 11/09/2018
Conditions of approval, if any, are attache certify that the applicant holds legal or equivalent would entitle the applicant to conduct the conductive transfer of the conductive trans		Office Rio Puerco			
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.					

(Instructions on page 2)
** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **




Additional data for EC transaction #437868 that would not fit on the form

32. Additional remarks, continued

sks (96.7 cu ft) Class G cement. Circulate cement to surface from 200' (casing shoe @ 141') w/65 sks (76.7 cu ft) Class G cement (15.6#/gal, 1.18 cu ft/sk) - Surface - Plug III: 0-200'.
6) Dig cellar around wellhead. Cut wellhead off. Tag TOC at surface inside casing and inside annulus. Install dryhole marker. Top off cellar w/3.5 bbls cement (17 sks, 20.06 cu ft). Clean location.
7) Well P&A'd on 9/20/18.

Completed P & A Schematic

Cobh # 1 Sec 22 T24N R2W 1150' FSL & 1630' FEL Rio Arriba NM



8-5/8" J-55 24# casing @ 141'. Cemented with 100 sks Cement. Circulated 1.5 bbls cement. Hole size 12-1/4"

Perforate @ 200'. Circulate plug to surface w/ 65 sks Class G Cement (76.7 cu.ft) (Plug III, Surface -200')

4 ½" 11.6 # casing @ 3370'. Hole size: 6-1/4"

Top of cement from CBL @ 1300'

Cement production casing w/ 100 sks 65/35/12 gel w/ 12% gilsonite followed by 100 sks 50/50 poz w/ 2% gel. **Total Slurry 426 cu.ft.**

Inside Plug @ 1558' with 18 sks (21.2 cu.ft) @ 1308'-1558' Class G cement. (Plug II, Nacimento, 1308'-1558')

CIBP @ 3189'. Set Inside Plug with 45 sks (53.1 cu.ft) Class G cement. (Plug I, Pictured Cliff-Fruitland-Kirtland-Ojo Alamo, 2557'-3189')

Pictured cliffs Perforated @ 3233' - 3239', 3246'-3250'

PBTD @ 3314', TD @ 3370'