Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM	APPROVED
OMB	No. 1004-0137
Expires:	January 31, 2018

	Expires.	January	31, 2010	
Lease Serial N	0. 1111.2	2038		

SUNDRY NOTICES AND REPORTS ON W Do not use this form for proposals to drill or to abandoned well. Use Form 3160-3 (APD) for suc	re-enter an			
SUBMIT IN TRIPLICATE - Other instructions on page	7. If Unit of CA/Agreement, Name and/or No. CA# NMNM117329			
1. Type of Well	8. Well Name and No. Price Federal #1			
Name of Operator Benson-Montin-Greer Drilling Corp.	9. API Well No. 30-039-29249			
	include area code) 10. Field and Pool or Exploratory Area			
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) 1770 FNL & 1105 FWL E-34-T25N-R2W	11. Country or Parish, State Rio Arriba, NM			
12. CHECK THE APPROPRIATE BOX(ES) TO INI	DICATE NATURE OF NOTICE, REPORT OR OTHER DATA			
TYPE OF SUBMISSION	TYPE OF ACTION			
Subsequent Report Casing Repair New	aulic Fracturing Reclamation Well Integrity Construction Recomplete Other and Abandon Temporarily Abandon			
the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be perfonned or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has detennined that the site is ready for final inspection.) Benson-Montin-Greer Drilling Corp. intends to permanently plug and abandon Price Federal #1 (API 30-039-29249) using the attached procedure. Also attached are the current and proposed wellbore diagrams. A closed-loop system will be used.				
	NMOCD			
BLM'S APPROVAL OR ACCEPTANCE OF THIS ACTION DOES NOT RELIEVE THE LESSEE AND	FEB 0 8 2019			
OPERATOR FROM OBTAINING ANY OTHER AUTHORIZATION REQUIRED FOR OPERATIONS ON FEDERAL AND INDIAN LANDS	DISTRICT 111			
Notify NMOCD 24 hrs prior to beginning operations SEE ATTACHED FOR CONDITIONS OF APPROVAL				
14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed) Zach Stradling	Vice President			
Signature	Date 06/26/2018			
THE SPACE FOR FEDERAL OR STATE OFICE USE				
Approved by Conditions of approval, if any, are attached. Approval of this notice does not warrar certify that the applicant holds legal or equitable title to those rights in the subject to	Title PF Date 12/6/18			
which would entitle the applicant to conduct operations thereon.	ny person knowingly and willfully to make to any department or agency of the United States			

(Instructions on page 2)



BENSON-MONTIN-GREER DRILLING CORP. P&A Procedure

Operator: Benson-Montin Greer Drilling Corp.

Date: July/August 2018 Field: Gavilan PC/Basin FC Contractor: Llaves Well Service Supervisor: Ben Gonzales Well Name: Price Federal #1 API Number.: 30-039-29249 Location: E-34-T25N-R2W Foreman: Jaime Serna

Note: Calculated cement volumes use 100% excess outside pipe and 50 ft excess inside pipe. Cement with be Class B or equivalent and have a yield of 1.18 cf/sk. Stabilizing wellbore fluid will be 8.33 ppg.

- 1. MIRU. Prepare blow pit. ND wellhead, NU BOP. Kill well with water if necessary.
- 2. TOOH (3) 3/4" x 4' pony rods, (1) 3/4" x 6' pony rod, (136) 3/4" plain rods, and pump. Tally out (106) 2-3/8" tubing joints, SN at 3429', (1) 4' perf sub, (1) 2-3/8" x 25' mud anchor, (EOT at 3458'). Round trip 5-1/2" casing scraper to 3312'.
- 3. Plug #1: (Pictured Cliffs/Fruitland/Kirtland/Ojo Alamo, 3262'-2983'). TIH with 5-1/2" CR and set at 3262'. Pressure test tubing. Load casing with water and circulate well clean. Pressure test casing to 500 psi. Mix 38 sx cement and spot a balanced plug inside 5-1/2" casing above CR at 3262' to 50' above Ojo Alamo top. PUH to 1663'.
- 4. Plug #2 (Nacimiento, 1663'-1563'). Mix 17 sx cement and spot balanced plug inside 5-1/2" casing to cover from 50' below to 50 above Nacimiento top. PUH to 673'.
- 5. Plug #3 (Surface casing shoe, 673'-573'). Mix 17 sx cement and spot a balanced plug inside 5-1/2" casing to cover from 50' below surface casing shoe to 50' above surface casing shoe.
- 6. Plug #4 (Surface, 50'-0). Attempt to pressure test the bradenhead annulus to 300 psi, note the volume to load. If the BH annulus holds pressure, then establish circulation out casing valve with water. Mix approximately 6 sx cement and spot a balanced plug inside 5-1/2" casing to cover from 50' below surface to surface, circulate good cement out casing valve. TOOH and LD tubing. If the BH annulus does not test, then perforate at the appropriate depth and attempt to circulate cement to surface.
- 7. ND BOP and cut off casing below surface. Install P&A marker with cement to comply with regulations. RDMO, cut off anchors and restore location.

Benson-Montin-Greer Drilling Corp.

Wellbore Diagram

Well Name/Number:

Price Federal #1

Spud Date:

10/1/2004

API Number:

30-039-29249

County:

Rio Arriba, NM

Elevations:

Well Location:


Unit Letter:

Footage: 1770' FNL, 1105' FWL

7248' GL

25N

2W



Benson-Montin-Greer Drilling Corp.

Wellbore Diagram

Well Name/Number:

Price Federal #1

Spud Date:

10/1/2004

API Number:

30-039-29249

County: Rio Arriba, NM Elevations:

Well Location:

1770' FNL, 1105' FWL

7248' GL

Unit Letter:

Section;


E

Footage: Township:

25N

Range:

2W





4900 College Boulevard Farmington, NM 87402 Office: 505.325.8874

Cell: 505.327.9207

8102 6 I VON

October 2, 2018

Mr. Clifton Price P.O. Box 25 Lindrith, New Mexico 87029

Regarding:

Price Federal #1 (API# 30-039-29249)

E-34-25N-2W

1770' FNL & 1105' FWL

Rio Arriba County, New Mexico

Mr. Price,

As previously discussed, Benson-Montin-Greer Drilling Corp. will plan to remove tanks, equipment, and risers from the Price Federal #1 well location following permanent plug and abandonment operations. The berms will be leveled off and the entrance, gravel, and cattle guard will be left in place.

Please sign and date below and return to Benson-Montin-Greer Drilling Corp. to confirm agreement with the work to be completed. Should you have any questions or concerns please contact me at 505-325-8874.

Sincerely

Zach Stradling

Benson-Montin-Greer Drilling Corp.

Clifton Price

Typed or Printed Name

Clifton Z. Price Signature

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

6251 COLLEGE BLVD. FARMINGTON, NEW MEXICO 87402

Attachment to notice of Intention to Abandon:

Re: Permanent Abandonment

Well: Price Federal #1

CONDITIONS OF APPROVAL

- 1. Plugging operations authorized are subject to the attached "General Requirements for Permanent Abandonment of Wells on Federal and Indian Lease."
- 2. Farmington Office is to be notified at least 24 hours before the plugging operations commence (505) 564-7750.
- 3. The following modifications to your plugging program are to be made:
 - a) Set Plug #1 (3262 2964) ft. to cover the Pictured Cliffs, Fruitland, Kirtland, and Ojo Alamo tops. BLM picks top of Ojo Alamo at 3014 ft.
 - b) Set Plug #2 (1723 1623) ft. to cover the Nacimiento top. BLM picks top of Nacimiento at 1673 ft.

You are also required to place cement excesses per 4.2 and 4.4 of the attached General Requirements.

Office Hours: 7:45 a.m. to 4:30 p.m.