DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

WELL COMPLETION OR RECOMPLETION REPORT AND LOG

1:07 0 9 20

FORM APPROVED OMB NO. 1004-0137

	Expires: January	31,	2018	
5.	Lease Serial No.			

NO-G-1312-1823

1a. Type of W	_	Oil Well	Well		Other		_			1	lf Indian,	Allottee or	Tribe Name
b. Type of Co	ompletion $ \boxtimes $	New Well	☐ Work Ove	r Deepen F	Plug Back Diff.	Zones		Hydrau	lic Fracturing		Unit or Ca	A Agreeme	ent Name and No.
		Other: _								NN	NM1308	12X	
2. Name of Op	perator									1		ne and We	
Enduring Reso	ources IV, LLC				3a. Phone N	In An	aluda a		da)	_	API Well	Init #353H	
3. Address 200 Energy Co	urt Farmington	NM 8740	01		505-636-974		спиае а	irea coi	ie)		043-2132		
				ordance with Federa	al requirements) *						Field and	Pool or Ex	xploratory
At surface					NMOC	n	Charles Lie and Charles Control	Billion			Sec., T.,	R., M., on	Block and
SHI: 1724' F	NL & 2332' FWL	SEC 26 2	2N 7W		MMOG	U				26	Survey o 22N 7W	r Area	
	SL & 1844' FEL S				DEC 04	201	0				County	or Parish	13. State
					CLC 0 4	201	0			Sa	ndoval		NM
	nterval reported				DISTRICT								
14. Date Spud 7/31/18	lded	9/8/	Date T.D. Reach	ned	16. Date Comp		10 / 30/1 ⊠Read		nd	17.	Elevation	ns (DF, RK	B, RT, GL)*
	otal Depth: 11			19. Plug Back T.			-	-	ridge Plug S	Set: M	D		
10. 1	4735' TVD	001 1110		4733′				1			ΓVD		
21. Type Elect	tric & Other Med	chanical I	ogs Run (Subm	it copy of each)			22. W	as well	cored?	×	No [Yes (Subn	nit analysis)
								as DS7			-	Yes (Subn	
									nal Survey?	L	No 🗵	Yes (Subn	nit copy)
F 2160 4					CON		-11	TIP	//				
Form 3160-4 (June 2015)	•		U	NITED STATES	1110	TIT	11-1	1111	11				
(buile 2015)					CUN	111	اسار						
23. Casing and	Liner Record (A	Report all	strings set in w	ell)	00.	T			T				
Hole Size	Size/Grade	Wt. (#	#ft.) Top (MI	D) Bottom (MD)	Stage Cemente		o. of Sk pe of	(s. &	Slurry Vol.		Cemer	nt Top*	Amount Pulled
17-1/2"	13-3/8", J-55	54.5	0	254' MD	Service		320		162		surface		
12-1/4"	9-5/8", J-55	36	0	2705' MD			760		1566		surface		
8-1/2"	5-1/2", P-110	17	0	11004' MD			1940		994		surface		
24. Tubing F													
Size	Dept Set (MD) Pa	acker Dept (MD)	Size	Depth Set (MD)	Pack	er Deptl	h (MD)	Siz	re	Dept	h Set (MD)	Packer Depth (MD)
2-7/8",6.5#,L 80 EUE 8rd	4004												
25. Producin	ig Intervals				26. Perforation R	ecord							
14 218	Formation		Тор	Bottom	Perforated	Interva	1		Size		Holes	Pipel page page	Perf. Status
Mancos 31st			5438′	10875′	5438'-5578'			.42			CCEP	IEDF	OR RECORD
Mancos 30th					5617'-5758'			.42		35		1011	
Mancos 29th					5797'-5937'			.42		35		MUA 3	1208
Mancos 28th				_	5976'-6117'		-	.42		35		/	1
Mancos 26th				-	6156'-6296' 6335'-6476'			.42		35 F	ARMIN	STON	IDIA OFFICE
Mancos 25th					6515'-6655'			.42		35	y:/		7
Mancos 24th				-	6694'-6835'			.42		35	-		0
Mancos 23 rd					6874'-7014'			.42		35		//-	
Mancos 22 nd					7053'-7194'			.42		35 35		1	
Mancos 21st					7233'-7373'			.42		35 35		1	
Mancos 20th				-	7412'-7553'			.42		35 35		-	
Mancos 19th					7592'-7732'			.42		35 35		-	
Mancos 18th				+	7771'-7912'			.42		35 35		-	
Mancos 17th					7951'-8091'			.42		35 35		-	
Mancos 16th				-	8130′-8271′			.42		35 35		-	
Mancos 15th				+	8310′-8450′			.42		35 35			
Mancos 14th					8489'-8630'			.42		35 35		-	
Mancos 13th				NMOC	8669'-8809'			.42		35 35			
					- 0000			1.42		55		I	

Mancos 12th	8848'-8989'	.42	35	
Mancos 11th	9028'-9170'	.42	35	
Mancos 10th	9207'-9348'	.42	35	
Mancos 9 th	9387'-9527'	.42	35	
Mancos 8 th	9566'-9707'	.42	35	
Mancos 7th	9746'-9887'	.42	35	
Mancos 6 th	9925'-10066'	.42	35	
Mancos 5 th	10105'-10245'	.42	35	
Mancos 4 th	10284'-10426'	.42	35	
Mancos 3 rd	10464'10605'	.42	35	
Mancos 2 nd	10644'-10784'	.42	35	
Mancos 1 st	10823'-10875'	.42	35	

Mancos 1 st	10823'-10875' 1.42 35
27. Acid, Fracture, Treatment,	Cement Squeeze, Post hydraulic fracturing chemical disclosures on FracFocus.org
Depth Interval	Amount, Type of Material and Date of Chemical Disclosure upload on FracFocus.org
5438'-5578'	MC 31st stage with 330000#, 20/40 & 30/50 PSA Sand
5617'-5758'	MC 30 th stage with 330500#, 20/40 & 30/50 PSA Sand
5797'-5937'	MC 29 th stage with 330100#, 20/40 & 30/50 PSA Sand
5976'-6117'	MC 28 th stage with 331200#, 20/40 & 30/50 PSA Sand
6156'-6296'	MC 27 th stage with 329400#, 20/40 & 30/50 PSA Sand
6335'-6476'	MC 26 th stage with 330800#, 20/40 & 30/50 PSA Sand
6515'-6655'	MC 25 th stage with 329000#, 20/40 & 30/50 PSA Sand
6694'-6835'	MC 24 th stage with 328800#, 20/40 & 30/50 PSA Sand
6874'-7014'	MC 23 rd stage with 329900#, 20/40 & 30/50 PSA Sand
7053'-7194'	MC 22 nd stage with 331500#, 20/40 & 30/50 PSA Sand
7233'-7373'	MC 21st stage with 331000#, 20/40 & 30/50 PSA Sand
7412'-7553'	MC 20 th stage with 330300#, 20/40 & 30/50 PSA Sand
7592'-7732'	MC 19 th stage with 330500#, 20/40 & 30/50 PSA Sand
7771'- 7 912'	MC 18 th stage with 330800#, 20/40 & 30/50 PSA Sand
7951'-8091'	MC 17 th stage with 329900#, 20/40 & 30/50 PSA Sand
8130'-8271'	MC 16 th stage with 330000#, 20/40 & 30/50 PSA Sand
8310'-8450'	MC 15 th stage with 330300#, 20/40 & 30/50 PSA Sand
8489'-8630'	MC 14 th stage with 329900#, 20/40 & 30/50 PSA Sand
8669'-8809'	MC 13 th stage with 330900#, 20/40 & 30/50 PSA Sand
8848'-8989'	MC 12 th stage with 328250#, 20/40 & 30/50 PSA Sand
9028'-9170'	MC 11 th stage with 329550#, 20/40 & 30/50 PSA Sand
9207'-9348'	MC 10 th stage with 331500#, 20/40 & 30/50 PSA Sand
9387'-9527'	MC 9 th stage with 330400#, 20/40 & 30/50 PSA Sand
9566'-9707'	MC 8 th stage with 328750#, 20/40 & 30/50 PSA Sand
9746'-9887'	MC 7 th stage with 332100#, 20/40 & 30/50 PSA Sand
9925'-10066'	MC 6 th stage with 329575#, 20/40 & 30/50 PSA Sand
10105'-10245'	MC 5 th stage with 329500#, 20/40 & 30/50 PSA Sand
10284'-10426'	MC 4 th stage with 330000#, 20/40 & 30/50 PSA Sand
10464'10605'	MC 3 rd stage with 330100#, 20/40 & 30/50 PSA Sand
10644'-10784'	MC 2 nd stage with 309350#, 20/40 & 30/50 PSA Sand
10823'-10875'	MC 1st stage with 260000# 20/40 & 30/50 PSA Sand

Produced 11/6/18	Test Date 11/6/18	Hours Tested 24 hr	Test Production	Oil BBL 456	Gas MCF 170	Water BBL 864	Oil Gravity Corr. API.	Gas Gravity	Flowing	
	Total Control		24 Hr.			Water	Gas/Oil	Well Status		
Choke Size 19/64"	Tbg. Press. Flwg.	Csg. Press. 98	Rate	Oil BBL	Gas MCF	BBL	Ratio	Producing		
,,,,,,	SI 167		-							
28a. Produ	action - Inter	val B								
	Test Date	Hours	Test Production	Oil BBL	Gas MCF	Water BBL	Oil Gravity Corr. API.	Gas Gravity	Production Method	
Produced		Tested	Production	BBL	MCF	BBL	Coll. AFI.	Glavity		
Choke	Tbg. Press. Flwg.	Csg. Press.	24 Hr. Rate	Oil BBL	Gas MCF	Water BBL	Gas/Oil Ratio	Well Status		***
	SI		additional da				Rudo			
	action - Inter		auditional da	ta on pag	(5,0,2)					
	Test Date	Hours	Test	Oil	Gas	Water	Oil Gravity	Gas	Production Method	
Produced		Tested	Production	BBL	MCF	BBL	Corr. API.	Gravity		
Choke	Tbg. Press.		24 Hr.	Oil	Gas	Water	Gas/Oil	Well Status		
Size	Flwg. SI	Press.	Rate	BBL	MCF	BBL	Ratio			
	Test Date	val D Hours	Test	Oil	Gas	Water	Oil Gravity	Gas	Production Method	
roduced	Test Bute	Tested		BBL	MCF	BBL	Corr. API.	Gravity		
Choke		Csg.	24 Hr.	Oil	Gas	Water	Gas/Oil	Well Status		
ize	Flwg. SI	Press.	Rate	BBL	MCF	BBL	Ratio			
		/C 1: 1	and for fuel ve	nted etc	.)				4	
8 Disno	sition of Gas	(Nona us			•/					
	sition of Gas							21 Competie	n (Log) Morlsons	
			nclude Aquife					31. Formatio	n (Log) Markers	
30. Summ	ary of Porou	s Zones (I	nclude Aquifo	ers):	ereof: Cored i		drill-stem tests,	31. Formatio	n (Log) Markers	
0. Summ Show a includi	ary of Porou	s Zones (I	nclude Aquife	ers):	ereof: Cored i		drill-stem tests,	31. Formatio	n (Log) Markers	
0. Summ	ary of Porou	s Zones (I	nclude Aquifo	ers):	ereof: Cored i			31. Formatio	n (Log) Markers	Ton
Show a includi recover	ary of Porou	s Zones (I	nclude Aquifo	ers): ntents the 1, time to	ol open, fl		n pressures and	31. Formatio	n (Log) Markers Name	Top Meas. Depth
Show a includi recover	ary of Porous all important ing depth interies.	s Zones (I zones of p rval tested	orosity and co	ers): ntents the 1, time to	ol open, fl	and shut-ir	n pressures and	31. Formatio		
O. Summ Show a includi recover	ary of Porou	s Zones (I zones of p rval tested	orosity and co	ers): ntents the 1, time to	ol open, fl	and shut-ir	n pressures and	31. Formatio		
Show a includi recover	ary of Porous all important and depth interies. ALAMO	s Zones (I zones of p rval tested Top	orosity and co l, cushion used Botton	ers): ntents the 1, time to	ol open, fl	and shut-ir	n pressures and	31. Formatio		
O. Summ Show a includi recover	ary of Porou. Ill important and depth interies. Interior and depth interies.	zones (I zones of prval tested Top 521 786	Botton 786	ers): ntents the 1, time to	ol open, fl	and shut-ir	n pressures and	31. Formatio		
O. Summ Show a includi recover Form OJO KIF PICTU	ary of Porous all important and depth interies. ALAMO ATLAND RED CLIFFS EWIS	Top 521 786 835	Botton 521 786 835	ers): ntents the 1, time to	ol open, fl	and shut-ir	n pressures and	31. Formatio		
O. Summ Show a includi recover. Form OJO KIF PICTU L	ary of Porous all important and depth interies. ALAMO RILAND RED CLIFFS EWIS HACRA	Top 521 786 835 1151	Botton 521 786 835 1150	ers): ntents the 1, time to	ol open, fl	and shut-ir	n pressures and	31. Formatio		
O. Summ Show a includi recover Form OJO KIF PICTU L CH	ary of Porous all important and depth interies. ALAMO ALAMO ATLAND RED CLIFFS EWIS HACRA F HOUSE	Top 521 786 835 1151 1365	Botton 521 786 835 1150 1363	ers): ntents the 1, time to	ol open, fl	and shut-ir	n pressures and	31. Formatio		
Show a including recover Form OJO KIF PICTU L CLIF MI	ary of Porous all important and depth interies. ALAMO RED CLIFFS EWIS HACRA F HOUSE	Top 521 786 835 1151 1365 1512	Botton 521 786 835 1150 1363 1508 1886	ers): ntents the 1, time to	ol open, fl	and shut-ir	n pressures and	31. Formatio		
Show a includi recover	ary of Porous all important in glepth interies. ALAMO ALAMO RED CLIFFS EWIS HACRA F HOUSE ENEFEE LOOKOUT	Top 521 786 835 1151 1365 1512 1899 2608	Botton 521 786 835 1150 1363 1508 1886 2576	ers): ntents the 1, time to	ol open, fl	and shut-ir	n pressures and	31. Formatio		
Show a includi recover Form OJO KIF PICTU CI CLIF MI POINT	ary of Porous all important and depth interies. ALAMO RTLAND RED CLIFFS EWIS HACRA F HOUSE ENEFEE LOOKOUT ANCOS	Top 521 786 835 1151 1365 1512 1899 2608	Botton 521 786 835 1150 1363 1508 1886 2576 3494	ers): ntents the 1, time to	ol open, fl	and shut-ir	n pressures and	31. Formatio		
So. Summ Show a includi recover Form OJO KIF PICTU L CI CLIF MI POINT	ary of Porous all important in glepth interies. ALAMO ALAMO RED CLIFFS EWIS HACRA F HOUSE ENEFEE LOOKOUT	Top 521 786 835 1151 1365 1512 1899 2608	Botton 521 786 835 1150 1363 1508 1886 2576	ers): ntents the 1, time to	ol open, fl	and shut-ir	n pressures and	31. Formatio		Top Meas. Depth
Form OJO KIF PICTU L CI CLIF MI	ary of Porous all important and depth interies. ALAMO RTLAND RED CLIFFS EWIS HACRA F HOUSE ENEFEE LOOKOUT ANCOS	Top 521 786 835 1151 1365 1512 1899 2608	Botton 521 786 835 1150 1363 1508 1886 2576 3494	ers): ntents the 1, time to	ol open, fl	and shut-ir	n pressures and	31. Formatio		·
Form OJO KIF PICTU L CI CLIF MI POINT M. G.	ary of Porous all important in get depth interies. ALAMO ALAMO RED CLIFFS EWIS HACRA F HOUSE ENEFEE LOOKOUT ANCOS ALLUP	Top 521 786 835 1151 1365 1512 1899 2608 3655 3846	Botton 521 786 835 1150 1363 1508 1886 2576 3494	ers): ntents the i, time to	ol open, fl	and shut-ir	n pressures and	31. Formatio		·
Form OJO KIF PICTU L CI CLIF MI POINT M. G.	ary of Porous all important and depth interies. ALAMO ATLAND RED CLIFFS EWIS HACRA F HOUSE ENEFEE LOOKOUT ANCOS ALLUP	Top 521 786 835 1151 1365 1512 1899 2608 3655 3846	Botton 521 786 835 1150 1363 1508 1886 2576 3494 3673	ers): Intents the distribution of the dindividution of the distribution of the distribution of the distri	Des	and shut-ir	tents, etc.	31. Formatio		
Form OJO KIF PICTU L CH POINT M G 2. Additi	ary of Porous all important in g depth interies. ALAMO ALAMO RED CLIFFS EWIS HACRA F HOUSE ENEFEE LOOKOUT ANCOS ALLUP onal remarks te which item	Top 521 786 835 1151 1365 1512 1899 2608 3655 3846	Botton 521 786 835 1150 1363 1508 1886 2576 3494 3673	ers): Intents the little to t	Des	and shut-in	tents, etc.		Name	
Form OJO KIF PICTU L CI CLIF MI POINT M. G. 22. Additi	ary of Porous all important and depth interies. ALAMO RTLAND RED CLIFFS EWIS HACRA F HOUSE ENEFEE LOOKOUT ANCOS ALLUP onal remarks te which item	Top 521 786 835 1151 1365 1512 1899 2608 3655 3846	Botton 521 786 835 1150 1363 1508 1886 2576 3494 3673 plugging proceen attached but full set req'd.)	ers): Intents the distribution of the dindividution of the distribution of the distribution of the distri	ol open, fl Des	and shut-in	tents, etc.			
Form OJO KIF PICTU L CI CLIF MI POINT M. G. 2. Additi 3. Indica	ary of Porous all important and depth interies. ALAMO RTLAND RED CLIFFS EWIS HACRA F HOUSE ENEFEE LOOKOUT ANCOS ALLUP onal remarks te which item	Top 521 786 835 1151 1365 1512 1899 2608 3655 3846	Botton 521 786 835 1150 1363 1508 1886 2576 3494 3673	ers): Intents the distribution of the dindividution of the distribution of the distribution of the distri	ol open, fl Des	and shut-in	tents, etc.		Name	·
Form OJO KIF PICTU L CI CLIF MI POINT M. G. 2. Additi 3. Indica	ary of Porous all important and depth interies. ALAMO RTLAND RED CLIFFS EWIS HACRA F HOUSE ENEFEE LOOKOUT ANCOS ALLUP onal remarks te which item	Top 521 786 835 1151 1365 1512 1899 2608 3655 3846	Botton 521 786 835 1150 1363 1508 1886 2576 3494 3673 plugging proceen attached but full set req'd.)	ers): Intents the distribution of the dindividution of the distribution of the distribution of the distri	ol open, fl Des	and shut-in	tents, etc.		Name	
Form OJO KIF PICTU L CI CLIF MI POINT M. G. 22. Additi 33. Indica	ary of Porous all important and depth interies. ALAMO	Top 521 786 835 1151 1365 1512 1899 2608 3655 3846	Botton 521 786 835 1150 1363 1508 1886 2576 3494 3673 plugging proceen attached but full set req'd.) and cement verification of the content of th	ers): Intents the distribution of the dindividution of the distribution of the distribution of the distri	ol open, fl Des	and shut-in	boxes:	rt	Name ☑Directional Survey	Meas. Depth
Form OJO KIF PICTU L CH CLIF MI POINT M. G. 33. Indica □Sun	ary of Porous all important and depth interies. ALAMO ALAMO RED CLIFFS EWIS HACRA F HOUSE ENEFEE LOOKOUT ANCOS ALLUP Onal remarks te which item ctrical/Mechan dry Notice for	Top 521 786 835 1151 1365 1512 1899 2608 3655 3846 (include as have be ical Logs (include plugging a plugging	Botton 521 786 835 1150 1363 1508 1886 2576 3494 3673 plugging proceen attached by a full set req'd.) and cement verifications and attageoing	ers): Intents the little to t	ol open, fl Des	and shut-in	boxes: DST Repo Other:	ort	Name	Meas. Depth
Form OJO KIF PICTU L CI CLIF MI POINT M. G. 33. Indica □Sun	ary of Porous all important and depth interies. ALAMO ALAMO RED CLIFFS EWIS HACRA F HOUSE ENEFEE LOOKOUT ANCOS ALLUP Onal remarks te which item ctrical/Mechan dry Notice for	Top 521 786 835 1151 1365 1512 1899 2608 3655 3846 (include as have be ical Logs (include plugging a plugging	Botton 521 786 835 1150 1363 1508 1886 2576 3494 3673 plugging proceen attached but full set req'd.) and cement verification of the content of th	ers): Intents the little to t	ol open, fl Des	and shut-in	boxes:	ort	Name ☑Directional Survey	Meas. Depth