State of New Mexico Energy, Minerals and Natural Resources Department

Michelle Lujan Grisham Governor

Sarah Cottrell Propst **Cabinet Secretary**

Todd E. Leahy, JD, PhD **Deputy Secretary**

Gabriel Wade, Acting Director Oil Conservation Division



New Mexico Oil Conservation Division approval and conditions listed below are made in accordance with OCD Rule 19.15.7.11 and are in addition to the actions approved by BLM on the following 3160-4 or 3160-5 form.

Operator Signature Date: 2/22/2019

Well information:
HILCORP ENERGY COMPANY
30-039-25961 San Juan 27-4 Unit #102M
ou des aesur dun ar 4 dine rizoaria
Application Type:
P&A Drilling/Casing Change Location Change
Recomplete/DHC (For hydraulic fracturing operations review EPA Underground injection control Guidance #84; Submit Gas Capture Plan form prior to spudding or initiating recompletion operations)
Other:
Conditions of Approval:
• Notify the OCD 24hrs prior to beginning operations.
Hold the C-104 for the DHC Tri-mingle.
• The initial CIBP must be placed no higher than 50' above the existing perforations.
 A Mechanical integrity test (MIT) must be performed from the initial CIBP to verify the integrity of the well. The pressure test must meet the requirements of 19.15.25.14 NMAC.
o 24hr notice is required to be provided to the agencies prior to performing the MIT.
 After the MIT is performed a second temporary isolating device may be set up near the requested recomplete interval without additional OCD approval to protect the casing
from the completion pressures.
 From the initial CIBP perform and submit a cement bond log (CBL) to the agencies for review and approval prior to perforating the formation.

If needed, submit a proposed remediation plan to the agencies for review and approval prior to starting remediation.

NMOCD Approved by Signature

4/3/19 Date

Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB No. 1004-0137 Express: July 31, 2010

	BUREAU OF LAND MAN	NAGEMENT		Expires: J	fily 31, 2010	10
				5. Lease Serial No.	SF080675	200
SUN	DRY NOTICES AND REPO	ORTS ON WELLS		6. If Indian, Allottee or Tribe N	()	19
	e this form for proposals t				Manor	
	well. Use Form 3160-3 (A		sals.		- Popular	
	BMIT IN TRIPLICATE - Other ins	tructions on page 2.		7. If Unit of CA/Agreement, Na	me and/or No.	
1. Type of Well Oil Well	Gas Well Other			8. Well Name and No.		
On Wen	Cas well Other			26 - 3- 3- 4- 3- 4- 4- 4- 4- 4- 4- 4- 4- 4- 4- 4- 4- 4-	27-4 Unit 102M	
2. Name of Operator	Uilaarn Enargy Compa			9. API Well No.	39-25961	
3a. Address	Hilcorp Energy Compa	3b. Phone No. (include area	a code)	10. Field and Pool or Explorato		
382 Road 3100, Aztec, N	IM 87410	505-599-340	00	Tapacito PC/E	Blanco MV/Basin I	DK
4. Location of Well (Footage, Sec., T.,F		NU 0 - 00 TOTAL F		11. Country or Parish, State	Nam Maria	
Surface Unit D (N)	WNW) 840' FNL & 1110' F\	WL, Sec. 33, 12/N, F	(U4VV	Rio Arriba ,	New Mexico	
12. CHECK	THE APPROPRIATE BOX(ES)	TO INDICATE NATUR	E OF NOT	TICE, REPORT OR OTHE	R DATA	
TYPE OF SUBMISSION		TYP	E OF AC	TION		
X Notice of Intent	Acidize	Deepen	Pı	roduction (Start/Resume)	Water Shut-Off	
	Alter Casing	Fracture Treat	R	eclamation	Well Integrity	
Subsequent Report	Casing Repair	New Construction		ecomplete	Other	
Final Abandonment Notice	Change Plans Convert to Injection	Plug and Abandon Plug Back		emporarily Abandon Vater Disposal		
13. Describe Proposed or Completed Op					nate duration thereof	
Testing has been completed. Final determined that the site is ready for Hilcorp Energy Comparthe existing Mesaverde application will be subm	red operations. If the operation results Abandonment Notices must be filed a final inspection.) The plans to recomplete the and Dakota. Attached is smitted and approved prior formed after surface disturbed to the complete the	e subject well in the the PC C102, recom to commingling. A	Pictured plete pro	Cliffs formation and occdure & wellbore scoop system will be utili	downhole comminuments. The DHO	
	HOLD CTO4 FOR_	311-				
	• 400				MINDED	
				14	MIR 15 2010	
14 T1 - 1	No. of District			D13	TRIST 111	
14. I hereby certify that the foregoing is	s true and correct. Name (Printed Typ	bea)				numbers.
Etta Trujillo		Title Ope	rations/R	egulatory Technician - S	ir.	
Signature AR	toph	Date		2/22/2019)	
	THIS SPACE FO	OR FEDERAL OR ST	ATE OFF	ICE USE		
Approved by	Markews		Title	AEM	3/B//	19
Conditions of approval, if any, are attac	thed. Approval of this notice does no	warrant or certify	2	•		

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.



Office

entitle the applicant to conduct operations thereon.

that the applicant holds legal or equitable title to those rights in the subject lease which would

District I

1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 **District II**

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 **District III**

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170 **District IV**

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462 State of New Mexico
Energy, Minerals and Natural
Resources
Oil Conservation Division
1220 S. St Francis Dr.

Form C-102 August 1, 2011

Permit 263658

WELL LOCATION AND ACREAGE DEDICATION PLAT

Santa Fe, NM 87505

1. API Number 30-039-25961	2. Pool Code 85920	3. Pool Name TAPACITO PICTURED CLIFFS (PRO GAS)
4. Property Code 319210	5. Property Name SAN JUAN 27 4 UNIT	6. Weil No. 102M
7. OGRID No. 372171	8. Operator Name HILCORP ENERGY COMPANY	9. Elevation 7185


10. Surface Location

UL - Lot	Section	Township	Range	Lot Idn	Feet From	N/S Line	Feet From	E/W Line	County
D	33	27N	04W		840	N	1110	W	RIO ARRIBA
!									

11. Bottom Hole Location If Different From Surface

UL - Lot	Section	Township	Range	Lot Idn	Feet From	N/S Line	Feet From	E/W Line	County
	12. Dedicated Acres 320.00 W/2		13. Joint or Infill	L	14. Consolidation Code			15. Order No.	

NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION



OPERATOR CERTIFICATION

I hereby certify that the information contained herein is true and complete to the best of my knowledge and belief, and that this organization either owns a working interest or unleased mineral interest in the land including the proposed bottom hole location(s) or has a right to drill this well at this location pursuant to a contract with an owner of such a mineral or working interest, or to a voluntary pooling agreement or a compulsory pooling order heretofore entered by the division.

E-Signed By: Etta Trufillo

Title: Operations/Regulatory Tech

Date: 2/15/2018

SURVEYOR CERTIFICATION

I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by me or under my supervision, end that the same is true and correct to the best of my belief.

Surveyed By:

Gary D. Vann

Date of Survey:

2/23/1998

Certificate Number:

7016



HILCORP ENERGY COMPANY SAN JUAN 27-4 UNIT 102M PICTURED CLIFFS RECOMPLETION SUNDRY

JOB PROCEDURES

- 1. MIRU service rig and associated equipment; test BOP.
- 2. TOOH with 2-3/8" tubing set at 8,418'.
- 3. Set a 4-1/2" plug at +/- 4,350' to isolate the Mesaverde and Dakota formations.
- 4. RU Wireline. Run CBL and record Top of Cement.
- 5. IF NECESSARY (Based on the results of the CBL top of cement) Perform cement squeeze work.
- 6. Load the hole and pressure test the casing.
- 7. N/D BOP, N/U frac stack and pressure test frac stack.
- 8. Perforate and frac the Pictured Cliffs formation (Top Perforation @ 3,998'; Bottom Perforation @ 4,085').
- 9. Isolate frac stage with a plug.
- 10. Nipple down frac stack, nipple up BOP and test.
- 11. TIH with a mill and drill out top Pictured Cliffs isolation plug.
- 12. Clean out to Mesaverde and Dakota formations isolation plug.
- 13. Drill out Mesaverde and Dakota formations isolation plug and cleanout to PBTD of 8,472'. TOOH.
- 14. TiH and land production tubing. Get a commingled Dakota/Mesaverde/Pictured Cliffs flow rate.



ألمذيته يرابعهن

HILCORP ENERGY COMPANY SAN JUAN 27-4 UNIT 102M PICTURED CLIFFS RECOMPLETION SUNDRY

