Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB No. 1004-0137 Expires: July 31, 2010

5. Lease Serial No

4/26/2019

Date

6. If Indian, Allottee or Tribe Name

armington Field Office NMSF078874u of Land Management

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals. SUBMIT IN TRIPLICATE - Other instructions on page 2. 7. If Unit of CA/Agreement, Name and/or No. 1. Type of Well Oil Well X Gas Well Other 8. Well Name and No. Canyon Largo Unit 328 2. Name of Operator 9. API Well No. 30-039-23266 Hilcorp Energy Company 10. Field and Pool or Exploratory Area 3a Address 3b. Phone No. (include area code) 382 Road 3100, Aztec, NM 87410 505-599-3400 Devils Fork Gallup 11. Country or Parish, State 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Surface Unit E (SWNW) 2000'FNL & 820' FWL, Sec. 05, T24N, R06W Rio Arriba **New Mexico** 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION X Notice of Intent Acidize Deepen Production (Start/Resume) Water Shut-Off Well Integrity Alter Casing Fracture Treat Reclamation **New Construction** Subsequent Report Casing Repair Recomplete Other Change Plans Plug and Abandon Temporarily Abandon MIT Final Abandonment Notice Convert to Injection Plug Back Water Disposal 13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.) Hilcorp Energy Company requests permission to perform an MIT on the subject well per the attached procedure. Notify NMOCD 24 hrs prior to beginning NMOCD operations MAY n 2 2019 Notify NMOCD 24 hrs prior to beginning SEE ATTACHED DISTRICT III operations FOR CONDITIONS OF APPROVAL 14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed) Etta Trujillo Operations/Regulatory Technician - Sr.

that the applicant holds legal or equivable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction



Title

Office

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify

Signature

Approved by



HILCORP ENERGY COMPANY CANYON LARGO UNIT 328 Mechanical Integrity Test (MIT) Notice of Intent

JOB PROCEDURES


- 1. Hold pre-job safety meeting. Verify cathodic is off. Comply with all NMOCD, BLM, and HEC safety and environmental regulations.
- 2. Check casing, tubing, and bradenhead pressures. If there is pressure on the BH, contact Operations Engineer.
- 3. Remove edeting ploing on casing valve. RU blow lines from casing valves and begin blowing down casing pressure (if any is present).
- 4. MIRU pump truck. Load the casing with 2% KCL water and corresion inhibitor,
- Perform Mechanical Integrity Test (MIT) by pressure testing the 4.5° casing above the CIBP set @ 5,105' to 560 psig for 30 minutes on a 2 hour chart with a 1,000 lb spring.
- 6. If the test passes, shut in the well, RD pump truck, and move off of the location. If the test fails, contact the Operations Engineer.

Hilcorp Energy Company

Current Schematic

Well Name: CANYON LARGO UNIT #328

API/UWI 3003923266	Surface Legal Location E-5-24N-6W	Field Name			State/Provinc NEW MEX		Well Configuration Type Vertical
Ground Elevation (ft) 6,496.00	Original KB/RT Elevation (ft) 6,509.00		KB-Ground Distance (ft) 13.00	KB-Casing Flange Dis	tence (ft)	KB-Tubing Hange	Platance (fi)



UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

6251 COLLEGE BLVD. FARMINGTON, NEW MEXICO 87402

Attachment to notice of Intent to Mechanical Integrity Test Well: Canyon Largo Unit 328

CONDITIONS OF APPROVAL

- 1. Farmington Office is to be notified at least 24 hours prior to conducting MIT operations @ (505) 564-7750.
- 2. The following are modifications to your MIT program:

Submit an electronic copy of the MIT Chart to the following addresses: jlovato@blm.gov and Brandon.Powell@state.nm.us

3. If the MIT fails, provide your remedial plans within 30 days of conducting MIT operations.

Office Hours: 7:45 a.m. to 4:30 p.m.