

State of New Mexico
Energy, Minerals and Natural Resources Department

Michelle Lujan Grisham
Governor

Sarah Cottrell Propst
Cabinet Secretary

Todd E. Leahy, JD, PhD
Deputy Secretary

Adrienne Sandoval, Division Director
Oil Conservation Division



May 20, 2019

Edgar Tovias
Enervest Operating LLC
1001 Fannin Street Suite 800
Houston, TX 77002

Re: 2018 Bradenhead Test

Well: Apache # 154, UL O Sec. 3 Twn. 24N Rge. 4W, API # 30-039-23886

Dear Mr. Tovias:

The 2018 Bradenhead test on the above well indicates a failure. In order to comply with Rule 19.15.16.11, prevent waste and protect fresh water, you are hereby directed to submit a plan of action before **June 20, 2019**, and to initiate remedial activity before **August 20, 2019**. At time of test: Initial Surface Casing psi was 12. Initial Production Casing psi was 135. Five-minute shut-in pressure on Surface Casing was 0. However, the bradenhead pressures back to 100 lbs.

Samples were taken from production casing and bradenhead prior to testing on May 6, 2017. Analysis have not been received.

Enervest Operating LLC is directed to find source of gas and fix within 90 days of the date of this letter.

Reference: iMPK1913527132 on future correspondence for this issue.

Notify the Aztec OCD 24 hours before work is initiated.

If you have any questions, please call me at 505-334-6178, ext. 123.

Sincerely yours,

Monica Kuehling
Deputy Oil and Gas Inspector
District III - Aztec

CC: Jicarilla Apache Nation
Well File