Form 3160-5 (June 2015)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

RECEIVED

FORM APPROVED OMB No. 1004-0137 Expires: January 31, 201

Expires: January 31, 2018

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such-proposals

5. Lease Serial No.	NMNM136672	
6. If Indian, Allottee	or Tribe Name	

abandoned well.	Use Form 3160-3 (A	PD) for suc	ch proposals	Field Of	lice	
SOBILITING THIFLICATE - Other instructions on page 2					MNM 138467	
1. Type of Well						
Oil Well Gas Well Other			8. Well Name and No. Federal 2307 07P Com 3H			
2. Name of Operator LOGOS Operating, LLC					9. API Well No. 30-039-31368	
3a. Address 2010 Afton Place 31		3b. Phone No. (include area code)		10. Field and Pool or Exploratory Area		
Farmington, NM 87401		(505) 787-2218		Basin Mancos / Lybrook Gallup		
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description)				11. Country or Parish, State		
1288' FSL & 337' FEL, SE/SE, P Sec 07 T23N R07W			Rio Arriba County, NM			
12. CHE	CK THE APPROPRIATE B	OX(ES) TO INI	DICATE NATURE	OF NOTI	CE, REPORT OR OTHE	ER DATA
TYPE OF SUBMISSION			TY	PE OF AC	TION	
Notice of Intent	Acidize	Deep	en	Prod	uction (Start/Resume)	Water Shut-Off
	Alter Casing	Hydr	aulic Fracturing	Recl	amation	Well Integrity
Subsequent Report	Casing Repair	New	Construction	Reco	omplete	<b>✓</b> Other
	Change Plans	Plug	and Abandon	Tem	porarily Abandon	Completion Report
Final Abandonment Notice	Convert to Injection	Plug	Back	Wate	er Disposal	osinpicaon respon
completed. Final Abandonment No is ready for final inspection.)  11/17/18-11/18/18 MIRU. Make wellhead. Pressure test 4-1/2" 11/25/2018-12/10/18 RU Hallib Test Lines- good. Frac'd thru A Gallup w/ 2SPF 0.38" diam. @ 70% Linear gel N2 Foam & 94, 12/11/18 MIRU completion rig 12/12/18 Continue to RU equip 12/13/18-12/14/18 Continue D 12/15/18 Circulate & CO to alp	e up seal assembly. TIH, v @ 1500psi/30min, good to urton & WL. Open Alpha slpha Sleeve @ 13342'- 139452'- 6590' = 432holes v 796,457(scf) N2. Set kill p & equipment. ND Frac valument and lines. TIH, w/Pi O of all plugs. Rig repair. V ha sleeve. TOOH, PH-6 the Production tubing of 6jts. of gas lift valves. RDMO.	w/ tieback stringest. RD complesteeve w/ 802338' MD = 8 hw/ a total of 10 flug @ 6490'. Feve. NU BOP et H-6 tbg. RU power wash & ream. 19. Change out of 2 3/8", J-55, MM 0 C D	g 150jts, 4-1/2", etion rig and equ 3#, brought up raioles. Perf'd Man 16 holes. Frac'd RD Halliburton Frauipment. Changower swivel. Tag t tools. POOH, w.4.7#.tbg @ 6396	11.6#, P-1 lipment. P lite to 10br cos w/ 2S 43 stages ac equipm ge over to ged & DO  // 4-1/2" tie b' w/ mule	and tieback @ 628 frep to move off loc. om 4830#, pumped 201 PF 0.38" diam. @ 133 of 12,026,917# 20/40 ment & frac stack.  4-1/2" handling tools. kill plug. Circulate, Company of the com	obls & shut down. Continue to RU. 09'- 9482' = 576 holes. Perfd Arizona Sand, 2,536,175gals of PU BHA, Function test- Good.
14. I hereby certify that the foregoing is		B 0 5 20'	18	LJ y	7	
Marie E. Florez	DIST	RICT I	Regulator	y Specialis	st /	
Signature Date Date					01/29/2019	
THE SPACE FOR FEDERAL OR STATE OFICE USE						
Approved by  Conditions of approval, if any, are attac	hed. Approval of this notice	does not warran	Title		Da	ite
certify that the applicant holds legal or a which would entitle the applicant to cor	equitable title to those rights					
Title 18 U.S.C Section 1001 and Title 4 any false, fictitious or fraudulent statem				ly and will	fully to make to any dep	artment or agency of the United States

(Instructions on page 2)

