Form 3160-5 (August 2007)

#### UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB No. 1004-0137

Expires: July 31, 2010

5. Lease Serial No. rmington Field Office NMSF078874 of Land Management SUNDRY NOTICES AND REPORTS ON WELLS 6. If Indian, Allottee or Tribe Name Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals. SUBMIT IN TRIPLICATE - Other instructions on page 2. 7. If Unit of CA/Agreement, Name and/or No. 1. Type of Well Oil Well X Gas Well Other 8. Well Name and No. Canyon Largo Unit 308 2. Name of Operator 9. API Well No. Hilcorp Energy Company 30-039-23650 3a. Address 3b. Phone No. (include area code) 10. Field and Pool or Exploratory Area 382 Road 3100, Aztec, NM 87410 **Devils Fork Gallup** 505-599-3400 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 11. Country or Parish, State Surface Unit G (SWNE) 2010'FNL & 1720' FWL, Sec. 05, T24N, R06W Rio Arriba **New Mexico** 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION X Notice of Intent Water Shut-Off Acidize Deepen Production (Start/Resume) Well Integrity Alter Casing Fracture Treat Reclamation **New Construction** Subsequent Report Casing Repair Recomplete Other Change Plans Plug and Abandon Temporarily Abandon MIT Final Abandonment Notice Convert to Injection Plug Back Water Disposal 13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.) Hilcorp Energy Company requests permission to perform an MIT on the subject well per the attached procedure. Notify NMOCD 24 hrs prior to beginning operations MMOCD MAY 2 1 2/13 DISTRICT 111 SEE ATTACHED FOR CONDITIONS OF APPROVAL 14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed) Etta Trujillo Operations/Regulatory Technician - Sr. 4/26/2019 Signature Date THIS SPACE FOR FEDERAL OR STATE OFFICE USE Approved by Title Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instruction on page 2)

entitle the applicant to conduct operations thereon.

that the applicant holds legal or equitable title to those rights in the subject lease which would



Office



## HILCORP ENERGY COMPANY CANYON LARGO UNIT 308 Mechanical Integrity Test (MIT) Notice of Intent

### JOB PROCEDURES


- 1. Hold pre-job safety meeting. Verify cathodic is off. Comply with all NMOCD, BLM, and HEC safety and environmental regulations.
- 2. Check casing, tubing, and bradenhead pressures. If there is pressure on the BH, contact Operations Engineer.
- 3. Remove existing piping on casing valve. RU blow lines from casing valves and begin blowing down casing pressure (if any is present).
- 4. MIRU pump truck. Load the casing with 2% KCL water and corrosion inhibitor.
- 5. Perform Mechanical integrity Test (MIT) by pressure testing the 4.5" casing above the CIBP set @ 5,390" to 560 psig for 30 minutes on a 2 hour chart with a 1,000 ib spring.
- 6. If the test passes, shut in the well, RD pump truck, and move off of the location. If the test falls, contact the Operations Engineer.



## Current Schematic - Version 3

Well Name: CANYON LARGO UNIT #308

	Surface Legal Location G-5-24N-6W			State/Province NEW MEX		Well Configuration Type Vertical
Ground Elevation (ft) 6,470.00	Original KB/RT Elevation (ft) 6,483.00	KB-Ground Distance (ft)	KB-Casing Flange Dis	lance (fi)	KB-Tubing Hange	Distance (ft)



# UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

6251 COLLEGE BLVD. FARMINGTON, NEW MEXICO 87402

Attachment to notice of Intent to Mechanical Integrity Test Well: Canyon Largo Unit 308

## **CONDITIONS OF APPROVAL**

- 1. Farmington Office is to be notified at least 24 hours prior to conducting MIT operations @ (505) 564-7750.
- 2. The following are modifications to your MIT program:

Submit an electronic copy of the MIT Chart to the following addresses: jlovato@blm.gov and Brandon.Powell@state.nm.us

3. If the MIT fails, provide your remedial plans within 30 days of conducting MIT operations.

Office Hours: 7:45 a.m. to 4:30 p.m.