Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

FORM APPROVED OMB No. 1004-0137

Expires: July 31, 2010

5. Lease Serial No.

6. If Indian, Allottee or Tribe Name

NMSF077648

Do not use this formabandoned well. Us	m for proposals e Form 3160-3 (A	to drill or to revented an APD) for such proposals	Field Man	Office agement			
SUBMIT IN TRIPLICATE - Other instructions on page 2.			7. If Unit of CA/Agreement, Name and/or No.				
1. Type of Well							
Oil Well Sas Well Other			8. Well Name and No. Davis 11				
2. Name of Operator				9. API Well No.			
Hilcorp Energy Company			30-045-10998				
3a. Address		3b. Phone No. (include area code)		10. Field and Pool or Exploratory Area			
382 Road 3100, Aztec, NM 87410		505-599-3400		Blanco Mesaverde		esaverde	
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) Surface Unit O (SW/SE) 790' FSL & 1450' FEL, Sec. 03, T31N, R12W		٧	11. Country or Parish, State San Juan	,	New Mexico		
12. CHECK THE APPRO	OPRIATE BOX(ES)	TO INDICATE NATURE OF	F NOT	TICE, REPORT OR OTH	IER DA	ATA	
TYPE OF SUBMISSION	TYPE OF ACTION						
Notice of Intent Acidi	ze Casing	Deepen Fracture Treat		roduction (Start/Resume)		Water Shut-Off Well Integrity	
X Subsequent Report Casin	g Repair	New Construction	X R	complete Other			
Chang	ge Plans	Plug and Abandon	Te	emporarily Abandon			
	ert to Injection	Plug Back		ater Disposal	_		
13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)							
4/22/2019 – MIRU BWD 103. TBG - 70 PSI; CSG - 70 PSI; BH - 0 PSI. BD WELL, ND TREE, NU BOP & TEST. LD HANGER. TIH & TAG 15' FILL @ 7427'. TOOH SCANNING TUBING. LD ENTIRE STRING DUE TO INTERNAL PITTING. SWI. SDFN.							
4/23/2019 - PJSM / CREW. SICP 80 PSIG, BH 0 PSIG. PU & TIH SELECT 3-7/8" BIT, CSG SCRAPER & 2-3/8" TBG. TG @ 7,337'. ATT TO ROTATE W/TONGS. FEEL TBG JUMP ONCE & TORQUE UP. TOH 2-3/8" TBG & BHA. PU & TIH 3-7/8" IMPRESSION BLOCK, XO & 2-3/8" TBG. TG TI SPOT @ 7,337'. FIRST ATT BLOCK BUMPED TI SPOT & SLID THRU. MAKE 1/2 TURN ON TBG. TG TI SPOT. SET 5K ONTO BLOCK. TOH 2-3/8" TBG, XO & IMPRESSION BLOCK. SWI. SDFN.							

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)

(continued on next page)

entitle the applicant to conduct operations thereon.

DISTRICT III

NMOCD

JUN 2 0 2019

	1		
Priscilla Shorty	Title O	perations/Regulatory Te	chnician - Sr.
Signature Husella Storty	Date	6/3/2019	ACCEPTED FOR RECORD
THIS SPACE FOR FED	ERAL OR S	STATE OFFICE USE	
Approved by			JUN 1 9 2019
		Title	FARMINGTON FIELD OFFIC
Conditions of approval, if any, are attached. Approval of this notice does not warrant of	or certify		BY:
that the applicant holds legal or equitable title to those rights in the subject lease which	Office		
and all the second and all the second			

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.



4/24/2019 - PJSM / CREW. SICP 80 PSIG, BH 0 PSIG. PU & TIH SELECT 4-1/2" CIBP, SETTING TL & 2-3/8" TBG. SET CIBP @ 7,315'. TOH & LD 1 JT 2-3/8" TBG. CIRC CSG W/105 BBLS. ATT TO PT CSG W/NO RESULTS. EIR @ 300 PSI & 2 BPM W/5 BBLS. TOH 2-3/8" TBG & SETTING TL. MIRU BASIN WL. FOUND FLUID LEVEL W/WL @ 3,500' FS. RUN CBL FR/7,316' (WLM) - SURF. CONT TO TOP OFF CSG W/70 BBLS. SEND CBL TO HEC REPS. RDMO WL. TIH PKR & 2-3/8" TBG. SET PKR @ 7,282'. PT CIBP TO 550 PSIG FOR 10 MIN. TST OK. RLS PKR. SET PKR @ 6,781'. ATT TO PT CSG. PRESS FR/550 - 0 IN 5 SEC. ATT TO ISOLATE LEAK. PROBLEMS W/PKR SETTING. SWI. SDFN.

4/25/2019 - PJSM / CREW. SICP 0 PSIG, SITP 0 PSIG, BH 0 PSIG. SET PKR @ 7,282'. PT TO 550 PSIG. PRESS FR/550 - 450 IN 10 MIN. BELIEVE PKR IS LEAKING. TOH 2-3/8" TBG & PKR. FOUND PKR MISSING 1 RUBBER ELEMENT. TIH RBP, PKR & 2-3/8" TBG. SET RBP @ 6,012'. LD CSG W/61 BBLS & CIRC CLN. PT CSG TO 575 PSIG. PRESS INC TO 620. BLEED OFF PRESS TWICE TO 500 & MONITOR PRESS INC. PRESS STABLIZED @ 520 PSIG FOR 30 MIN. W/O ENGINEER / NMOCD EVAL. RLS RBP. TOH 2-3/8" TBG, PKR & RBP. SWI. SDFN.

4/26/2019 – PJSM / CREW. SICP 0 PSIG, BH 0 PSIG. HEC ENGINEER SENT BRANDON POWELL, NMOCD, AND JIM LOVATO, BLM, THE CBL AND SUMMARY OF PATH FORWARD TO P&A THE DAKOTA DUE TO COMPROMISED CSG AT 7337' (VERIFIED BY IMPRESSION BLOCK) AND HIC LOCATED BETWEEN 6012' AND 7282'. APPROVAL WAS GIVEN BY BOTH AGENCIES TO P&A THE DAKOTA. MIRU BASIN WL. RIH & DUMP 3 SX BAIL CMT FR/7,315' - 7,275'. RDMO WL. SWI. WOC. SDFWE.

4/29/2019 - PJSM / CREW. SICP 0 PSIG, BH 0 PSIG. TIH BP, PERF SUB & TBG. TG CMT @ 7,275'. TOH & LD TBG & BHA. PU & TIH 4-1/2" CICR & 2-3/8" TBG. PMP DWN TBG & CICR W/25 BBLS. SET CICR @ 5,831'. STING OUT OF CICR. LD & CIRC CSG. MIRU DRAKE ENERGY SERVICES CMT. ATT TO STING INTO CICR. TAGGING 7" HIGH. CIRC ON TOP OF CICR & ATT TO WASH DOWN W/NO RESULTS. UNABLE TO STING INTO CICR. RDMO DRAKE CMT TRKS. TOH 2-3/8" TBG & STINGER. TIH 3-7/8" JUNK MILL & 2-3/8" TBG. RU PWR SWIVEL. TG CICR @ 5,831'. DO CICR. CIRC CLN. SWI. SDFN.

4/30/2019 - PJSM / CREW. SICP 0 PSIG, SITP 0 PSIG, BH 0 PSIG. PU & TIH 2-3/8" TB. TG REMAINDER OF CICR @ 7,274'. TOH & LD TBG. PU & TIH 4-1/2" CICR & 2-3/8" TBG. PMP DWN TBG & CICR W/25 BBLS. SET CICR @ 5,831'. LD TCA. MIRU DRAKE ENERGY SERVICES CMT EQUIP. PT PMP & LINES TO 3,500 PSIG. TST OK. SQZ CSG W/412 SX TYPE G CMT (MIXED @ 15.8 PPG, 1.18 CU FT/SX, 486.16 CU FT). STING OUT OF CICR. TOH 2 JTS 2-3/8" TBG. EOT @ 5,637'. REVERSE CIRC CLN W/30 BBLS. REC 1.5 BBLS CMT. DAKOTA P&A'D. RDMO DRAKE CMT TRKS. TOH & LD TBG & STINGER. SWI. SDFN.

5/1/2019 - PJSM / CREW. SICP 0 PSIG, BH 0 PSIG. JONATHAN KELLY W/NMOCD ON LOCATION TO WITNESS OPS. MIRU WELLCHECK. PT CSG TO 568 PSIG. TST OK. RDMO WELLCHECK. ND BOP. ND 2K WH. STUB UP 4-1/2" CSG. NU 5K WH. NU BOP. MIRU BASIN WLU. PERF PT. LOOKOUT W/3-1/8" SELECTFIRE CSG GUNS FR/5,054' - 5,224' (50 HOLES) 5224', 5223', 5222', 5221', 5220', 5198', 5197', 5196', 5180', 5179', 5178', 5177', 5176', 5175', 5174', 5150', 5149', 5148', 5147', 5146', 5145', 5144', 5143', 5142', 5141', 5140', 5121', 5120', 5119', 5118', 5117', 5102', 5101', 5100', 5099', 5098', 5097', 5096', 5095', 5094', 5076', 5075', 5074', 5073', 5072', 5058', 5057', 5056', 5055', 5054'. PERF MENEFEE W/3-1/8" SELECTFIRE CSG GUN FR/4,832' - 5,017' (40 HOLES) 5017', 5016', 5015', 5014', 5013', 4988', 4987', 4986', 4985', 4984', 4983', 4982', 4981', 4980', 4936', 4934', 4933', 4931', 4930', 4929', 4928', 4884', 4883', 4882', 4881', 4880', 4879', 4878', 4877', 4876', 4845', 4844', 4843', 4836', 4835', 4834', 4833', 4832'. RDMO WLU. PU & TIH AS-1X PKR W/WL RE-ENTRY GUIDE, XO, PUMP OUT PLG W/RUPTURE DISC IN PLACE, XO, 153 JTS 2-7/8" P-110 SEAMLESS BTS-8 TBG, XO, 2-7/8" X 2' TBG SUB & RECOMPLETION HNGR. SET PKR @ 4,733' W/15K COMPRESSION. SWI. SDFN.

5/2/2019 - PJSM W/RIG CREW. SICP 0 PSIG, SITP 0 PSIG, BH 0 PSIG. ND BOP. NU FRAC STACK. MIRU WELLCHECK. PT & CHART TBG, PKR & FRAC VLV TO 6,000 PSIG FOR 5". INCR TO 7,000' FOR 5". INCR TO 8,000 FOR 30". TST OK. RDMO WELLCHECK. MIRU EXPERT DOWHOLE SLU. RIH W/SPEAR & RUPTURE DISC. RDMO SLU. SWI. RD RR MWD 103 @ 10:00 HRS.

5/24/2019 – RU HALLIBURTON FRAC. COOL DOWN, PRIME, TEST LINES, CHANGE OUT N2 FM AND CABLES. BROKE DOWN WELL W/ WATER AND 1000 GAL 15% HCL. **FOAM FRAC'D MESAVERDE W/ 306,320 LBS 40/70 AND 70,814 GAL SLICKWATER AND 2.48 MILLION SCF N2. 70 QUALITY.** AVG RATE = 55 BPM, AVG PSI = 4553. ISIP WAS 613 PSI. 15 MINUTE SIP WAS 84 PSI. DROPPED 20 BIO-BALLS W/ 1/2 OF SAND PUMPED. RIG DOWN HALLIBURTON FRAC. TURN WELL OVER TO FLOWBACK CREW.

5/28/2019 — MIRU BWD 103. SITP 300 PSIG, SICP 0 PSIG, BH 0 PSIG. ND FRAC STACK. NU BOP. MIRU WELLCHECK. PT & CHART BOP & WH. LOW 250 PSIG, HIGH 2,000 PSIG. TST OK. RLS PKR. RU LUBRICATOR. SITP 150 PSIG. LUBRICATE OUT 2-WAY CHK. BD TBG. RD LUBRICATOR. REMOVE HNGR. TOH & LD TBG & PKR. PU & TIH. TG FILL @ 5,726' (48' FILL, TOC @ 5,786', CICR @ 5,831'). TOH. SWI. SDFN.

5/29/2019 - SICP 330 PSIG, SITP 0 PSIG W/STRNG FLT, BH 0 PSIG. BD WELL. TIH 16 JTS 2-3/8" TBG. TG FILL @ 5,726' (60' FILL). BRK CIRC W/AFU. CO FILL FR/5,726' - 5,786' (TOC/PBTD). CIRC CLN. TOH 183 JTS 2-3/8" TBG & LD BHA. KW W/15 BBL W/TOH. TIH **EXPENDABLE CHK W/MULE SHOE, SN, 1 JT 2-3/8" TBG, 2-3/8" X 2' TBG SUB, 155 JTS 2-3/8" 4.7#, J-55 TBG, 4 - 2-3/8" X 4' TBG SUBS & 1 JT 2-3/8" TBG. DRIFT TBG W/TIH. LD TBG. EOT @ 4,960'. SN @ 4,958'.** ND BOP. NU WH W/B-2 ADPT. PMP 6 BBL PAD. DROP BALL. PT TBG TO 500 PSIG. TST OK. PMP OFF CHK @ 850 PSIG. RD RR BWD 103 @ 16:30 HRS.

THE DAKOTA HAS BEEN P&A'D AND WELL IS PRODUCING AS A MESAVERDE STANDALONE UNDER DENSITY EXCEPTION ORDER R-20183.

