* Form 3160-5 (June 2015)		UNITED STATE					ORM APPR		
DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT						OMB NO. 1004-0137 Expires: January 31, 2018 5. Lease Serial No.			
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.						NMSF078543			
						6. If Indian, Allottee or Tribe Name			
SUBMIT IN TRIPLICATE - Other instructions on page 2					7. If Unit or CA/ 891000441	7. If Unit or CA/Agreement, Name and/or No. 891000441B			
1. Type of Well	s Well 🔲 Oth	ner				8. Well Name and SAN JUAN 3		69	
2. Name of Operator HILCORP ENERG	GY COMPAN	Contact: NY E-Mail: mwalker@	AMANDA W	ALKER (san juan nort		9. API Well No. 30-045-247	77-00-S1		
3a. Address 1111 TRAVIS STI HOUSTON, TX 7			3b. Phone No Ph: 505.32	o. (include area code) 24.5122		10. Field and Poo BASIN DAK		atory Area	
4. Location of Well (F	ootage, Sec., T	. R., M., or Survey Description)			11. County or Pa	rish, State		
Sec 35 T32N R7V 36.941528 N Lat,				SAN JU			IUAN COUNTY, NM		
12. CHE	CK THE AI	PPROPRIATE BOX(ES)	TO INDICA	TE NATURE O	F NOTICI	E, REPORT, OR	OTHER I	DATA	
TYPE OF SUBMI	TYPE OF SUBMISSION								
Notice of Intent		Acidize	Dee	pen	Produ	ction (Start/Resume	e)	Water Shut-Off	
_		□ Alter Casing	🗖 Нус	Iraulic Fracturing	Reclar	mation		Well Integrity	
Subsequent Repo		Casing Repair	_	v Construction	🛛 Recon	1		Other	
Final Abandonm	ent Notice	Change Plans				orarily Abandon			
	bt	Convert to Injection		g Back 🔲 Water Disposal ding estimated starting date of any proposed work and approximate duration th					
downhole commin	ompany requised with the ure plan. A urface distur	lests permission to recom existing Dakota. Please closed loop system will b bing activities.	see the attac e used. Inter	hed procedure, y	vellbore di	agram, prior	NMOCD r to begin operation	ning	
	но	LD CTON FOR DHC					NMO	CD	
approval with attached COA							JUL 17 20		
				COA	DIS			TRICT 111	
14. I hereby certify that to Name (Printed/Typed)	c	Electronic Submission # For HILCORP E committed to AFMSS for pr	NERGY COMP	ANY, sent to the OE KILLINS on 0	Farmingto 7/11/2019 (n	СН		
Simulture	(Electronic S	Nutration (D-t- 07/04/0	040				
Signature	(Electronic S	THIS SPACE FO		Date 07/01/2		JSE			
Approved By JOE KIL				TitleENGINEE	R			Date 07/11/2019	
	lds legal or equ	d. Approval of this notice does uitable title to those rights in the act operations thereon.		Office Farming	ton				
Title 18 U.S.C. Section 100 States any false, fictitious	1 and Title 43 or fraudulent	U.S.C. Section 1212, make it a statements or representations as	crime for any po to any matter w	erson knowingly and ithin its jurisdiction.	willfully to 1	nake to any departme	ent or agency	y of the United	
(Instructions on page 2) **	BLM REV	ISED ** BLM REVISE	D ** BLM R	EVISED ** BLN		D ** BLM REVI	ISED **		
		N	NOCD	R					

R

5

6/23/2019

District |

1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 . .

_

. .

. .

District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

OCD Permitting

Form C-102 August 1, 2011

Permit 269225

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

WELL LOCATION AND ACREAGE DEDICATION PLAT				
1. API Number	2. Pool Code	3. Pool Name		
30-045-24777	72319	BLANCO-MESAVERDE (PRORATED GAS)		
4. Property Code	5. Property Name	6. Well No.		
318434	SAN JUAN 32 7 UNIT	069		
7. OGRID No.	8. Operator Name	9. Elevation		
372171	HILCORP ENERGY COMPANY	6730		

10. Surface Location UL - Lot Section Township Range Lot Idn Feet From N/S Line Feet From E/W Line County В 07W SAN JUAN 35 32N 860 1570 N Ε

.....

_

. .

. .

11. Bottom Hole Location If Different From Surface									
UL - Lot	Section	Township	Range	Lot Idn	Feet From	N/S Line	Feet From	E/W Line	County
}		•	l °						•
12. Dedicated Acres		13. Joint or Infill		14. Consolidation Code			15. Order No.		
320.00									

NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION

53	OPERATOR CERTIFICATION I hereby certify that the information contained herein is true and complete to the best of my knowledge and belief, and that this organization either owns a working interest or unleased mineral interest in the land including the proposed bottom hole location(s) or has a right to drill this well at this location pursuant to a contract with an owner of such a mineral or working interest, or to a voluntary pooling agreement or a compulsory pooling order heretofore entered				
	by the division.				
	E-Signed By: Amanda Walker				
	Title Operations/Regulatory Tech. Sr.				
	Date: 6/28/2019				
	SURVEYOR CERTIFICATION I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by me or under my supervision, and that the same is true and correct to the best				
	of my belief.				
	Surveyed By: Fred B. Kerr Jr.				
	Date of Survey: 11/17/1980				
	Certificate Number: 3950				

https://wwwapps.emnrd.state.nm.us/OCD/OCDPermitting/Report/C102/C102Report.aspx?BHID=44760




HILCORP ENERGY COMPANY SAN JUAN 32-7 UNIT 69 MESA VERDE RECOMPLETION SUNDRY

	JOB PROCEDURES			
1.	MIRU workover rig and associated equipment; NU and test BOP.			
2.	TOOH with 2 3/8" tubing set at 8,143'.			
3.	Prior to prepping the well, removal of the packer/tubing fish at ~8,165' will be attempted. RIH with tapered mill and ream through tight spot at 4,030'. TOOH. TIH with washover mill, wash over and mill through packer elements. Remove fish from wellbore if possible, otherwise chase to bottom below Dakota perforations.			
4.	Set a 4-1/2" cast iron bridge plug at +/- 8,150' to isolate the Dakota.			
5.	Load hole with fluid and run a CBL on the 4-1/2" casing. Verify cement bond within the Mesa Verde and confirm TOC (estimated at 3,300' by temperature survey). Review CBL results with engineering/NMOCD and perform cmt remediation, if required (min TOC @ 5,159' unless otherwise approved). PT csg to 650 psi.			
6.	Set a second 4-1/2" cast iron bridge plug at +/- 6,475 ^t to provide a base for the frac. Load the 7" x 4.5" annulus with packer fluid. If a casing frac is pursued, install 5K tubing head and pressure test casing to anticipated frac pressure, but do not exceed 80% of casing burst pressure. *Burst pressure of 4-1/2" x 10.5# casing is 4,790 psig. 80% of burst is 3832 psig.			
7.	Perforate the Mesa Verde. (Top perforation @ 5,659', Bottom perforation @ 6,427')			
8.	Frac will be completed via existing casing or a frac string depending on TOC and casing integrity. If running a frac string set pkr at ~5,610'.			
9.	N/D BOP, N/U frac stack (if necessary) and test frac stack to frac pressure. Open well and PT frac string (if used) to 9000#.			
10.	If necessary, RU slickline. RIH and break ceramic disc. RD slickline.			
11.	Frac the Mesa Verde in a single or multiple stages.			
12.	RU flowback eqmt if necessary. Flowback well until tubing pressure drops to working level and sand subsides or well loads up. RD flowback eqmt.			
13.	MIRU workover rig. Nipple down frac stack (if used), nipple up BOP and test.			
14.	. Release pkr (if used) and POOH LD workstring (if used).			
15.	TIH with a mill and clean out to the top of the DK isolation plug at 8,150 ¹ . Take Mesa Verde gas samples and analyze.			
16.	Drill out Dakota isolation plug and cleanout to PBTD of 8,305'. TOOH.			
17.	TIH and land production tubing. Get a commingled Dakota/Mesa Verde flow rate.			



HILCORP ENERGY COMPANY SAN JUAN 32-7 UNIT 69 MESA VERDE RECOMPLETION SUNDRY



UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE 6251 COLLEGE BLVD. FARMINGTON, NEW MEXICO 87402

Attachment to notice of Intent to Recomplete & Commingle

Well: San Juan 32-7 Unit 69 API: 3004524777

CONDITIONS OF APPROVAL

1. Contact BLM Inspection and Enforcement @ (505) 564 – 7750, 24 hours prior to conducting MIT work so an inspector can be present to witness the MIT.

Contact Joe Killins, Petroleum Engineer @ (505) 564 – 7736 to discuss failed MIT results and/or your remedial action and isolation plans.

Submit the electronic copy of the MIT Test Chart and CBL for verification to the following addresses: jkillina@BLM.gov and Brandon.Powell@state.nm.us.

2. The following modifications to your recompletion program are to be made:

- a) Upon rigging up, record Bradenhead pressure and monitor same during recompletion operations. Notify BLM and NMOCD if anomalous pressure changes occur. Provide monitoring results in the subsequent Report of Operations.
- b) Casing pressure test for fracture stimulation operations cannot exceed the internal yield strength of the casing including a 20% safety factor unless a waiver is granted. Stimulation operations cannot exceed this test pressure.
- c) CIBP for the base of fracture stimulation is to be no more than 50' above the top of tubing stub at 8165' MD.

3. File well test and recompletion results within 30 days of completing recompletion operations.