Form 3160-5 (June 2015)

## **UNITED STATES** DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

JUN 1 8 2019

FORM APPROVED OMB No. 1004-0137 xpires: January 31, 2018

	Е	Expires: January 31, 20			
	5. Lease Serial No.	NMSF 077972			
٦	5 C				

	Farmington Fi	eld O	ffice
	SUNDRY NOTICES AND REPORTS ON WELLS of Land N	Manag	6. If Indian, Allottee or Tribe Name
20	o not use this form for proposals to drill or to re-enter an	· idiid	STITE.

SUNDRY NOTICES AND REPORTS Of Do not use this form for proposals to drill abandoned well. Use Form 3160-3 (APD) for	or to re-enter an	6. If Indian, Allottee or T	ribe Name				
SUBMIT IN TRIPLICATE - Other instructions of	n page 2	7. If Unit of CA/Agreeme	ent, Name and/or No.				
1. Type of Well Oil Well Gas Well Other		8. Well Name and No. Ri	chardson 002				
2. Name of Operator LOGOS Operating, LLC		9. API Well No. 30-045-	06621				
3a. Address 2010 Afton Place 3b. Phon	e No. (include area code)	10. Field and Pool or Exp					
Farmington, NM 87401 (505) 78	37-2218	Basin Fruitland Coal					
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) 890 FSL & 990 FEL, SE/SE, P Sec 011 T27N R13W	,	11. Country or Parish, State San Juan County, NM					
12. CHECK THE APPROPRIATE BOX(ES) T	O INDICATE NATURE OF NOT	ICE, REPORT OR OTHER	R DATA				
TYPE OF SUBMISSION	TYPE OF AC	TION					
✓ Notice of Intent  Acidize  Alter Casing  Occions Rapping	Hydraulic Fracturing Rec	luction (Start/Resume) amation omplete	Water Shut-Off Well Integrity Other				
Subsequent Report Casing Repair  Change Plans  Final Abandonment Notice Convert to Injection		porarily Abandon er Disposal	BH remediation				
the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be perfonned or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has detennined that the site is ready for final inspection.)  LOGOS is requesting a Temporary Abandon (TA) on the above well, per attached MIT chart completed on 6/14/2019.  6/13/2019 MIRU. Remove horses head. TOOH, w/ rods. ND wellhead. NU and function test BOP. TOOH, w/ 2 3/8" tubing. TIH w/ CIBP set @ 1202'. Top of perf @ 1238'. Load casing w/ packer fluid. Bled off pressure. TOOH, laying down 2 3/8" tubing and setting tool. ND BOP. NU WH. Top off casing with packer fluid. SDFN.  6/14/2019 Pressure test 4-1/2" casing to 560# for 30 minutes - Good test. MIT witnessed & monitored Bradenhead during pressure test(zero psi) by Jonathan Kelly (OCD).							
14. I hereby certify that the foregoing is true and correct. Name (Printed/Type Marie E. Florez	Regulatory Speciali	st	OCOWN				
Signature MH HWA	Date	06/17/2019	346				
THE SPACE FOR FEDERAL OR STATE OFICE USE							
Approved by  Conditions of approval, if any, are attached. Approval of this notice does not we certify that the applicant holds legal or equitable title to those rights in the sub		Date Date	TOR RECORD				
which would entitle the applicant to conduct operations thereon.  Title 18 U.S.C Section 1001 and Title 43 U.S.C Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.							
(Instructions on page 2)			1 24				

