					Shirtson and					
•	i.				TED					
	Do not us	UNITED STATES DEPARTMENT OF THE IN BUREAU OF LAND MANA NDRY NOTICES AND REPOR e this form for proposals to	NTERIOR AGEMENT RTS ON WEL drill or to re-	enter an						
		Well. Use Form 3160-3 (APL IBMIT IN TRIPLICATE - Other instruct	7. If Unit of CA/Agreement, N	ame and/or No						
	1. Type of Well				uan 28-6 Unit					
		X Gas Well Other			8. Well Name and No. San Juan 28-6 Unit 213					
	2. Name of Operator	Hilcorp Energy Company	y		9. API Well No. <b>30-0</b>	39-20844				
	3a. Address 382 Road 3100, Aztec, N		Phone No. (inclu 505-59	ude area code) 9-3400	10. Field and Pool or Explorate Blanco Mesa	ory Area verde/Basin Dakota				
	4. Location of Well <i>(Footage, Sec., T., I</i> Surface Unit A (N	R.,M., or Survey Description) IENE) 1180 'FNL & 1000' FEL	8N, R06W	11. Country or Parish, State Rio Arriba , New Mexico						
	12. CHECK	THE APPROPRIATE BOX(ES) TO	ATURE OF NO	TICE, REPORT OR OTHE	ER DATA					
	TYPE OF SUBMISSION			TYPE OF AC	TION					
8	X Notice of Intent	Acidize Alter Casing Casing Repair Change Plans Convert to Injection	Deepen Fracture Treat New Constructi Plug and Aband Plug Back	on X R lon T	roduction (Start/Resume) Reclamation Recomplete Yemporarily Abandon Vater Disposal	Water Shut-Off Well Integrity Other				
	If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.) Hilcorp Energy Company plans to recomplete the subject well in the Mesaverde formation and downhole commingle with the existing Dakota. Attached is the MV C102, recomplete procedure & wellbore schematic. The DHC application will be submitted and approved prior to commingling. A closed loop system will be utilized. Interim reclamation will be performed after surface disturbing activities. Notify NMOCD 24 hrs prior to beginning									
	This well is pending ap	proval of well density exemp								
	HOLD C104 FOR	NMOC Leption JUL 19	<b>D</b> 2019	SEE ATTACHED FOR CONDITIONS OF APPROVAL						
	14. I hereby certify that the foregoing is true and correct. Name (Printed Typed)									
	Cherylene Weston		Title	Title Operations/Regulatory Technician - Sr.						
	Signature Meryle	he Whaton	Date	· (20)9						
	THIS SPACE FOR FEDERAL OR STATE OFFICE USE									
		thed. Approval of this notice does not wa ble title to those rights in the subject lease ons thereon.		Title Office	A CONTRACTOR	ALL ON ON				
		43 U.S.C. Section 1212, make it a crime is or representations as to any matter within		wingly and willfull	y to make to any department or a	agency of the United States any				
	(Instruction on page 2)	or representations as to any matter within	NMOCD (	V						

District I 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 **District II** 

811 S. First St., Artesla, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170 **District IV** 

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

# **State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. Santa Fe, NM 87505

Form C-102 August 1, 2011

Permit 269101

WELL LOCATION AND ACREAGE DEDICATION PLAT

1. API Number	2. Pool Code 72319	3. Pool Name BLANCO-MESAVERDE (PRORATED GAS)					
30-039-20844	· /···································						
4. Property Code	5. Property Name	6. Well No.					
318710	SAN JUAN 28 6 UNIT	213					
7. OGRID No.	8. Operator Name	9. Elevation					
372171	HILCORP ENERGY COMPANY	6483					

	10. Surface Location																
U	Lot		Section		Township		Range	Lot Idn	Feet From	N/S Line		Feet From		E/W Line		County	
		A		31		28N	06W	1	1180		N		1000		E		RIO
																ARRIBA	
_	11 Bottom Hole Location If Different From Surface																

	11. Bottom Hole Location if Different From Surface										
	UL - Lot	Section	Township	Range	Lot Idn	Feet From	N/S Line	Feet From	E/W Line	County	
ľ	12. Dedicated A 326	cres .29 - E/2	<b></b>	13. Joint or Ir	13. Joint or Infill		ion Code	15. Order No.			

NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION Т

OPERATOR CERTIFICATION I hereby certify that the information contained herein is true and complete to the best of my knowledge and belief, and that this organization either owns a working interest or unleased mineral interest in the land including the proposed bottom hole location(s) or has a right to drill this well at this location pursuant to a contract with an owner of such a mineral or working interest, or to a voluntary pooling agreement or a compulsory pooling order heretofore entered by the division. E-Signed By: Title: Cherylene Weston, Ops/Regulatory Tech-Sr. Date: 06/26/2019
SURVEYOR CERTIFICATION I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by me or under my supervision, and that the same is true and correct to the best of my belief. Surveyed By: DAVID KILVEN
Certificate Number: 1760



# HILCORP ENERGY COMPANY


# **SAN JUAN 28-6 UNIT 213**

## MESA VERDE RECOMPLETION SUNDRY

#### API #: 30-039-20844

#### JOB PROCEDURES

- 1. MIRU Service rig and associated equipment, test BOP. Check Bradenhead pressures daily and record throughout the recomplete project. Notify NMOCD and BLM if any anomalous pressures changes occur on the Bradenhead.
- 2. TOOH w/ 2 3/8" tubing set at 7604'.
- 3. Set initial CIBP at 7424' or deeper (no higher than 50' above existing perforations)
- 4. Perform MIT from initial CBP, providing 24 hr notice to BLM and NMOCD. Once completed, review and submit the MIT charted test results to both the NMOCD and BLM If the MIT fails, discuss and gain approval with both the NMOCD and BLM with a plan of action to remediate the wellbore. Perform a 2nd MIT once remediated.
- 5. Run CBL and submit it to NMOCD and BLM.
- 6. Optionally set bridge plug below intended recomplete interval.
- 7. ND BOP, NU frac stack. Pressure test the production casing or frac string and frac stack to maximum frac pressure. The pressure test will not exceed 85% of the internal yield pressure rating of the primary treatment string.
- 8. Perforate and frac the Mesa Verde within 4846'-5908'.
- 9. Optionally set a kill plug above recomplete interval for casing fracs.
- 10. ND the frac stack, NU the BOP and test.
- 11. MU and TIH with a mill. Tag and drill out the top isolation plug and Mesa Verde frac plugs if applicable.
- 12. Clean out the wellbore to the top of the Dakota isolation plug.
- 13. Once water and sand rates are acceptable, drill out the Dakota isolation plug and cleanout to PBTD of 7703'. TOOH.
- 14. TIH and land production tubing. Get a commingled Dakota/MV flow rate.



\_\_\_\_

### UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

6251 COLLEGE BLVD. FARMINGTON, NEW MEXICO 87402

Attachment to notice of Intent to Recomplete & Commingle

Well: San Juan 28-6 Unit 213 30-039-20844

#### CONDITIONS OF APPROVAL

1. Contact BLM Inspection and Enforcement @ (505) 564 – 7750, 24 hours prior to conducting MIT work so an inspector can be present to witness the MIT.

Contact John Hoffman, Petroleum Engineer @ (505) 564 – 7742 to discuss any failed MIT results and/or your remedial action and isolation plans.

# Submit the electronic copy of the MIT Test Chart and CBL for verification to the following addresses: <u>jhoffman@BLM.gov</u> and <u>Brandon.Powell@state.nm.us</u>.

2. The following modifications to your recompletion program are to be made:

- a) Upon rigging up, record Bradenhead pressure and monitor same during recompletion operations. Notify BLM and NMOCD if anomalous pressure changes occur. Provide monitoring results in the subsequent Report of Operations.
- b) Casing pressure test for fracture stimulation operations cannot exceed the internal yield strength of the casing including a 20% safety factor unless a waiver is granted. Stimulation operations cannot exceed this test pressure.
- c) CIBP for base of fracture stimulation to be set less 50' above top existing perforation.

3. File well test and recompletion results within 30 days of completing recompletion operations.