in the second of					
RECEI	VED				
¥-0	Table Auf				
Form 3160-5	UNITED STATES	TERIOR	FORM APPROVED		
(August 2007)	DEPARTMENT OF THE IN BUREAU OF LAND MANAG		OMB No. 1004-0137 Expires: July 31, 2010		
Parmington Fi	eld Office		5. Lease Serial No.		
Bureau of Land N	NDRY NOTICES AND REPORT	S ON WELLS	6. If Indian, Allottee or Tribe N	ISF078423	
Do not us	e this form for proposals to d	rill or to re-enter an			
	well. Use Form 3160-3 (APD)				
1. Type of Well	UBMIT IN TRIPLICATE - Other instruct	ions on page 2.	7. If Unit of CA/Agreement, N	ame and/or No. uan 29-7 Unit	
	X Gas Well Other		8. Well Name and No.		
			the second se	n 29-7 Unit 550S	
2. Name of Operator	Hilcorp Energy Company		 9. API Well No. 30-0 	39-29202	
3a. Address	3b.	Phone No. (include area code)	10. Field and Pool or Exploratory Area		
382 Road 3100, Aztec,		505-599-3400	Blanco Mesa 11. Country or Parish, State	verde/Basin Dakota	
4. Location of Well <i>(Footage, Sec., T.,</i> Surface Unit I (N	IESE) 2332' FSL & 1109' FEL, 5	Sec. 11, T29N, R07W	Rio Arriba	, New Mexico	
12. CHECK	THE APPROPRIATE BOX(ES) TO	INDICATE NATURE OF N	OTICE, REPORT OR OTHE	ER DATA	
TYPE OF SUBMISSION		TYPE OF A	CTION		
X Notice of Intent	Acidize	Deepen	Production (Start/Resume)	Water Shut-Off	
	Alter Casing	Fracture Treat	Reclamation	Well Integrity	
Subsequent Report	Casing Repair Change Plans	New Construction X Plug and Abandon	Recomplete Temporarily Abandon	Other	
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disposal		
determined that the site is ready for Hilcorp Energy Compa Mesaverde well. The D	al Abandonment Notices must be filed only or final inspection.) ny plans to recomplete the su K was TA'd on 9/1/2009. Attac Il be utilized. Interim reclamat	bject well in the Mesav ched is the MV C-102, r	rerde formation and pro ecomplete procedure &	duce as a single wellbore schematic. A	
	pproval of well density exempt	Notify NMOCD prior to begin operation	mmg		
HOLDON	Density Exception		DISTRIC	T	
14. I hereby certify that the foregoing	is true and correct. Name (Printed/Typed)				
Cherylene Weston		Title Operations	/Regulatory Technician - S	Sr.	
Signature Charles	elleton	Date	R	CRI	
0		EDERAL OR STATE O	FFICE USE The V	E A	
Approved by		Title	Par -	Date	
that the applicant holds legal or equital entitle the applicant to conduct operati		which would Office	Ales	20 24	
	43 U.S.C. Section 1212, make it a crime for s or representations as to any matter within		ully to make to any department of	agency of the United States any	
(Instruction on page 2)		NMOCD r~		1	

5

* 1

A



HILCORP ENERGY COMPANY SAN JUAN 29-7 UNIT 550S MESA VERDE RECOMPLETION SUNDRY

API #: 30-039-29202

JOB PROCEDURES

- <u>Note:</u> The San Juan 29-7 Unit 550S well was sidetracked from a whipstock set in the 7" casing at a depth of 2822' (top of slide) on 9/25/2005. 4-1/2" casing was run through the sidetrack to surface and cemented on 10/9/2005. This is the string that the below referenced 10/28/2005 CBL was run on and is the string that all recomplete work will be done within. The sidetrack is also the wellbore which is depicted in the included schematic. On 7/16/2009, the OCD received a notice of intent from Burlington Resources to plug the Dakota and Gallup as well as put the well in TA status in order to allow later recompletion to the MV. This Dakota and Gallup plugging and TA work was performed in an operation finishing 9/1/2009 and the TA has since been extended.
- Perform MIT from initial existing 5888' CIBP, providing 24 hr notice to BLM and NMOCD. Once completed, review and submit the MIT charted test results to both the NMOCD and BLM If the MIT fails, discuss and gain approval with both the NMOCD and BLM with a plan of action to remediate the wellbore. Perform a 2nd MIT once remediated.
- 3. Note: 10/28/2005 Blue Jet CBL indicates TOC at 1860'.
- 4. ND BOP, NU frac stack. Pressure test the production casing or frac string and frac stack to maximum frac pressure. The pressure test will not exceed 85% of the internal yield pressure rating of the primary treatment string.
- 5. Perforate and frac the Mesa Verde within 4260'-5864'.
- 6. Optionally set a kill plug above recomplete interval for casing fracs.
- 7. ND the frac stack, NU the BOP and test.
- 8. MU and TIH with a mill. Tag and drill out the top isolation plug and Mesa Verde frac plugs if applicable.
- 9. Clean out the wellbore to the top of the 5888' isolation plug.
- 10. TIH and land production tubing.

Hikorp Energy Company Current Schematic Well Name: SAN JUAN 29-7 UNIT #550S								
A HANA		SUFBCE LADS LOCADO	[Parto Name	(90,60	Sinofredace	DEVIATED		
003028202 925 Senine		011-029N-007W-I	BASH (FRUITLAND COAL)	1002	NEW MEXICO	DEVIATED		
329.00		8.341.00	la c					
			DEVIATED, Sidetrack 1, 5/3	0/2019 1:59:00 PM				
(f)(f)(G)	TVD (RKB)		Vertical	schematic (actual)				
11.8		•		• •		······		
12.1								
50 1					Surface Casing Ce			
#6						sType III Class B;		
1417		1. Sudara Q RA In	: 9.00 in: 12.00 fb(B)		circulated 10 bbis to	SUTINCE.		
146.0			145.84 MB					
150.0								
612.0					Intermediate Casin	o Cement: 12.00-2.900.0		
122.1					-1/15/2004; Load 34	Sacks Premium Lite		
1,059.9					Class B, Tail 90 sac circulated 56 bbis to	ks Type III Class C;		
2,256 9		OJC2; Intermediate; 7 in	; 6.46 in; 11.96 ftKB;		ICH CUMIED OD DOIS R	J SUFIECE.		
2,358.0		- 1093 This wellbore had to be	2,897.55 M/B					
2.621 \$			ue to stuck drill line		·			
2,852.0								
2,659.9								
2,932.1		-FRUITLAND (Anal)						
3,199.1		PICTURED CUIFFS (final)						
3,408.1		LEWIS (final)		· · · · · · · · · · · · · · · · · · ·				
3,878.0								
3,880.7				1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	Production Casing			
4,250.8		-MESA VERDE TOP (fina				Lead 9 sacks Scaveng		
5,863 8		MESA VERDE BASE (An	(اھ	t t	TOC @ 1860' (CBL	icks Premium Lite Class 10/28/2005)		
5,806.1		Bridge Plug - Permaner	11 5.888.00-5.891.00					
5,801.1					Cement Plug: 6,26	.00-6,459.00; 9/1/2009.		
6,261.2						6261', W/15 SX, 17.7		
6,450 0					00171.0003500	ar grib. Pro.		
6,617.1		GALLUP (final)				00-7,408.00, 9/1/2009,		
7,224.1						7224', W/14 SX, 16.5		
7,260 2						ar e lo.orro.		
7,271.3								
7,369.1		GREENHORN (Anal)						
7,408.1		Bridge Plug - Permaner	nt 7,408.00-7,411.00	> <				
7,411.1		00000000000	•					
7,429.1		- GRANEROS (final)						
7,475.1		DAKOTA (Bnal)			میر خدید می می این کار این کار می می	······································		
7,532.2		Dakota: 7,485.00 Bridge Plug - Permanen	7,587.00, 11/3/2005					
7,535.1		Daily says plug didn't	hold, holes in casing	$\gg < 1$				
7,565.9								
7.542.0		ł				11/3/2005; Frac'd Dakot		
7.644 0						water and 38,642# 2014		
7.645.0		Bridge Plug - Permaner		> < 1	TLO SBID.			
7,660 0		Usxola: 7,582.00	7.724.00; 11/3/2005					
7.640 9		Bridge Plug - Permaner	nt 7,690.00-7,691.00	> < 1				
7,724 1								
7,736.9	[(REAL)				11 (A. 10 - A - A - A - A - A - A - A - A - A -		
		20104	detrack 1; 7,737.00		-PBTO: 7,737.00-7,7	04 40, 10 0/ (UD)		
7,742.5								
7,743,4	ĺ	1						
7,763,1 7,764,4		3, Production; 4 1/2 in	n; 4.00 in; 11.96 fb(B);					
	1	1	7.764.48 MGB		PBTD: 7,764.48-7,7	00.007 10/8/2005		
7.765.1			1,104.40 MMD 234					

•

District I

1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720 District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170 District IV

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

Form C-102 August 1, 2011

Permit 269105

WELL LOCATION AND ACREAGE DEDICATION PLAT

2. Pool Code	3. Pool Name
72319	BLANCO-MESAVERDE (PRORATED GAS)
5. Property Name	6. Well No.
SAN JUAN 29 7 UNIT	550S
8. Operator Name	9. Elevation
HILCORP ENERGY COMPANY	6329
	72319 5. Property Name SAN JUAN 29 7 UNIT 8. Operator Name

10. Surface Location										
UL - Lot	Section	Township	Range	Lot Idn	Feet From	N/S Line	Feet From	E/W Line	County	
	11	29N	07W		2332	S	1109	E	RIO	
									ARRIBA	

11. Bottom Hole Location If Different From Surface

UL - Lot	Section	Township	Range	Lot Idn	Feet From	N/S Line	Feet From	E/W Line	County
12. Dedicated Acres 320.00 - E/2		13. Joint or Infill		14. Consolidatio	n Code		15. Order No.		

NO ALLOWABLE WILL BE ASSIGNED TO THIS COMPLETION UNTIL ALL INTERESTS HAVE BEEN CONSOLIDATED OR A NON-STANDARD UNIT HAS BEEN APPROVED BY THE DIVISION

	OPERATOR CERTIFICATION I hereby certify that the information contained herein is true and complete to the best of my knowledge and belief, and that this organization either owns a working interest or unleased mineral interest in the land including the proposed bottom hole location(s) or has a right to drill this well at this location pursuant to a contract with an owner of such a mineral or working interest, or to a voluntary pooling agreement or a compulsory pooling order heretofore entered by the division. E-Signed By: Title: Cherylene Weston, Ops/Regulatory Tech-Sr. Date: 06/26/2019				
	SURVEYOR CERTIFICATION I hereby certify that the well location shown on this plat was plotted from field notes of actual surveys made by me or under my supervision, and that the same is true and correct to the bes of my belief.				
· · · · · · · · · · · · · · · · · · ·	Surveyed By: DAVID A JOHNSON				
	Date of Survey: 4/7/2003				
	Certificate Number: 14827				

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FARMINGTON DISTRICT OFFICE

6251 COLLEGE BLVD. FARMINGTON, NEW MEXICO 87402

Attachment to notice of Intent to Recomplete & Commingle

Well: San Juan 29-7 Unit 550S 30-039-29202

CONDITIONS OF APPROVAL

. . · ·

1. Contact BLM Inspection and Enforcement @ (505) 564 – 7750, 24 hours prior to conducting MIT work so an inspector can be present to witness the MIT.

Contact John Hoffman, Petroleum Engineer @ (505) 564 – 7742 to discuss any failed MIT results and/or your remedial action and isolation plans.

Submit the electronic copy of the MIT Test Chart and CBL for verification to the following addresses: <u>jhoffman@BLM.gov</u> and <u>Brandon.Powell@state.nm.us</u>.

2. The following modifications to your recompletion program are to be made:

- a) Upon rigging up, record Bradenhead pressure and monitor same during recompletion operations. Notify BLM and NMOCD if anomalous pressure changes occur. Provide monitoring results in the subsequent Report of Operations.
- b) Casing pressure test for fracture stimulation operations cannot exceed the internal yield strength of the casing including a 20% safety factor unless a waiver is granted. Stimulation operations cannot exceed this test pressure.
- c) CIBP for base of fracture stimulation to be set less 50' above top existing perforation.

3. File well test and recompletion results within 30 days of completing recompletion operations.