Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

SUNDRY NOTICES AND REPORTS ON W	ELLS	
Do not use this form for proposals to drill or to re	e-enter an	

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.			NMSF078115 6. If Indian, Allottee of		
SUBMIT IN TRIPLICATE - Other instructions on page 2			7. If Unit or CA/Agree	7. If Unit or CA/Agreement, Name and/or No.	
Type of Well ☐ Oil Well ☐ Gas Well ☑ Other: COAL BED METHANE			8. Well Name and No. GRENIER 101	8. Well Name and No. GRENIER 101	
Name of Operator Contact: AMANDA WALKER HILCORP ENERGY COMPANY E-Mail: mwalker@hilcorp.com			9. API Well No. 30-045-27247-0	9. API Well No. 30-045-27247-00-S1	
3a. Address 1111 TRAVIS STREET HOUSTON, TX 77002		3b. Phone No. (include area code) Ph: 505-324-5122		10. Field and Pool or Exploratory Area BASIN FRUITLAND COAL	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			11. County or Parish,	11. County or Parish, State	
Sec 7 T31N R11W NESW 1925FSL 1830FWL 36.911190 N Lat, 108.033630 W Lon			SAN JUAN COI	SAN JUAN COUNTY, NM	
12. CHECK THE AF	PPROPRIATE BOX(ES)	TO INDICATE NATURE OF	NOTICE, REPORT, OR OTH	HER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION				
☐ Notice of Intent	☐ Acidize	☐ Deepen	☐ Production (Start/Resume)	☐ Water Shut-Off	
	☐ Alter Casing	☐ Hydraulic Fracturing	☐ Reclamation	■ Well Integrity	
Subsequent Report	☐ Casing Repair	■ New Construction	☐ Recomplete	⊠ Other	
☐ Final Abandonment Notice	☐ Change Plans	□ Plug and Abandon	□ Temporarily Abandon	Hydraulic Fracture	
CH	☐ Convert to Injection	□ Plug Back	☐ Water Disposal		
Attach the Bond under which the wo following completion of the involved	ally or recomplete horizontally, rk will be performed or provide l operations. If the operation re pandonment Notices must be fi	ent details, including estimated starting , give subsurface locations and measure the Bond No. on file with BLM/BIA. esults in a multiple completion or recor- led only after all requirements, including	ed and true vertical depths of all pertir Required subsequent reports must be appletion in a new interval, a Form 316	nent markers and zones. filed within 30 days 50-4 must be filed once	
PLEASE SEE ATTACHED					
GRENIER 101 30-045-27247 LEASE: NMSF078115 REFRAC SUBSEQUENT			NMOCI	The state of the s	
AUG 3 0 2019					
			DISTRICT	I I	

14. I hereby certify that the foregoing is true and correct. Electronic Submission #477287 verified by the BLM Well Information System
For HILCORP ENERGY COMPANY, sent to the Farmington
Committed to AFMSS for processing by JOE KILLINS on 08/28/2019 (19JK0145SE)

Signature (Electronic Submission) Date 08/08/2019

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

OPERATIONS/REGULATORY TECH SR.

JOE KILLINS **Title** ENGINEER Date 08/28/2019 Approved By Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon. Office Farmington

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Name (Printed/Typed) AMANDA WALKER

(Instructions on page 2) ** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **



Grenier 101 30-045-27247

Lease: NMSF078115 Refrac Subsequent

6/4/2019: MIRU. ND WH. ND BOP & TEST. PU ON TBG & LD TBG HANGER. TIH & TAG 3' OF FILL. RU TUBOSCOPE. TOOH SCANNING & TALLY TBG. PU STRINGMILL & TIH TO 2365'. PU RBP & TIH W/2 JTS. SET RBP, RELEASE RBP & LD 2 JTS. LOAD CSG ABOVE RBP & PT TO 300 PSI/10 MIN. TEST GOOD. ND BOP. PT TO 2400 PSI. TEST GOOD. NU BOP & PT PIPE RAMS. TEST GOOD. TIH W/2 JTS & RETRIEVE RBP. TOOH W/2 JTS & LD RBP. FINISH TIH W/STRINGMILL TO 2750'. TOOH, LD TBG & STRINGMILL. SIW SL. SDFN.

6/5/2019: PU AS1X PKR W/10K CERAMIC DISK & 2 7/8"" P-110, RTS-8 FRAC STRING. TIH & SET @ 2740.07'. ND BOP, NU FRAC STACK. PT FRAC STACK & TBG TO 9000 PSI & RECORD ON CHART. TEST GOOD. RD RIG & EQUIP.

6/26/2019: (CHECK WHP 120, SITP 110, BH 0). RIH W/1.5 IB. TAG @ 2764 WLM. SIW. RD SLICKLINE. SL. BD CASING PSI.

7/1/2019: MIRU FRAC EQUIPMENT. PUMP PRE DESIGN, PUMP 75%Q FOAM FRAC WITH 60120# 20/40 SAND, MAX PSI 6709, AVG PSI 5731, MAX BH RATE 43.4 BPM AVG BH RATE 39.7 BPM ISIP 1201. TOTAL N2 940817 SCF.

7/9/2019: (SITP 5 PSIG, SICP 200 PSIG, BH 0 PSIG). MIRU. BD WELL. ND FRAC STACK. INSTALL 2 WAY CHK. NU BOP. MIRU WELLCHECK. PT & CHART BOP & WH. LOW 250 PSIG, HIGH 2,000 PSIG. TST OK. RLS PKR. SITP 0 PSIG. REMOVE 2-WAY CHK. REMOVE HNGR. TOH & LD 2 - 2-7/8" X 10' TBG SUBS, XO, 88 JTS 2-7/8" P-110 SEAMLESS RTS-8 TBG, XO, PKR, PUMP OUT SUB & WL RE-ENTRY GUIDE. PU & TIH 4-3/4" CONE BIT, BIT SUB & 86 JTS 2-3/8" TBG. TG FILL @ 2,771' (16' FILL). BRK CIRC W/AFU. CO FILL FR/2,771' - 2,787' (PBTD). CIRC CLN. TOH 11 JTS 2-3/8". SWI. SDFN.

7/10/2019: (SICP 165 PSIG, SITP 0 PSIG W/STRNG FLT, BH 0 PSIG). BD WELL. TIH 10 JTS 2-3/8" TBG. TG FILL @ 2,782'. BRK CIRC W/AFU. CO FILL FR/2,782' - 2,787' (PBTD). CIRC CLN. TIH 85 JTS 2-3/8" 4.7# J-55 TBG & LD BHA. TG PBTD. LD TBG. EOT @ 2,764'. SN @ 2,762'. ND BOP. NU WH W/B-2 ADPT. PMP 5 BBL PAD. DROP BALL. PT TBG TO 500 PSIG. TST OK. PMP OFF CHK @ 800 PSIG.

RDMO @ 1400 hrs



Current Schematic

Well Name: GRENIER #101



